



East
1:50 EXISTING



Helibar repairs to failing
brickwork in these locations

Replace dormers - to be
rebuilt with lead cheeks, roof
and new timber windows

Decayed porch
replaced with new
sympathetic design
porch, built in timber
or reconstituted
stone - Details TBA
prior to installation.
Repair steps

Helibar repairs to failing
brickwork in these locations

This drawing is the copyright of
Manorwood Construction Ltd but may
be used for planning purposes by the
Local Authority without breach of
copyright.

Do not scale from this drawing unless
for Local Authority planning purposes.
All dimensions must be checked on
site prior to commencement of works.
Construction (Design and
Management) Regulations, 2015

This drawing is intended for Planning
purposes only and as such does not
highlight residual design related health
and safety risks.

This information can be provided on
request; however, it is anticipated that
the full extent of residual risks will be
identified during the detailed Building
Regulations or construction design
Status and prior to construction works
commencing on site.

All responsibilities and duties of
Principal Designer as stated within the
above regulations now revert to the
client unless Manorwood are appointed
to undertake Building Regulations or
construction drawings.

MANORWOOD
Building on tradition

Suite 114
26 The Heron
Chichester
West Sussex
PO19 7BB

tel: 01243 201 102
email: enquiries@manorwood.co.uk
web: www.manorwood.co.uk

Address
Courtwick Park, Courtwick Lane,
Littlehampton, BN17 7PD

Submission **Planning**

Scale @ A1 1:50

Job No. 2601CO

Drawn By VM

Checked By BK

Drawn On 23.04.2026

Issued On 23.04.2026

Status Existing and Proposed

Drawing East

Drawing No. 2601CO_200

Revision **000**

1m @ 1:
50
100
200
500
1250

East
1:50 PROPOSED