

ROLAND HOUSE
LITTLEHAMPTON

THIS IS A GRADE II LISTED BUILDING
HISTORIC ENGLAND LIST ENTRY: 1027816

notes

Please note: These are planning application stage drawings not construction drawings and should be treated as such.



Part North Elevation - Proposed - 1:50@A1



Part West Elevation - Proposed - 1:50@A1



Part South Elevation - Proposed- 1:50@A1



East Elevation - Proposed - 1:50@A1

WINDOW / DOOR SCHEDULE - MEWSBROOK CAREHOME - EXISTING CONDITION				
Ref	Window Type	Glazing	Condition / Type	Period Correct Replacement Required to Regularise with Local Authority
W01	WT1	Single Pane	Timber Framed Sash - 6 over 6 (2 Side sash) - Mid/Late 19th Century	NO
W02	WT2	Single Pane	Timber Framed Sash - 3 over 2 - Mid/Late 19th Century	NO
W03	WT3	Double Glazed	Timber Casement window - Late 20th Century Eastern Extension	NO
W04	WT4	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W05	WT5	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W06	WT4	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W07	WT1	Single Pane	Timber Framed Sash - 6 over 6 (2 Side sash) - Mid/Late 19th Century	NO
W08	WT6	Single Pane	Timber Framed Sash - 4 over 8 - Mid/Late 19th Century	NO
W09	WT7	Single Pane	Timber Framed Sash - 2 over 2 - Mid/Late 19th Century	NO
W10	WT7	Single Pane	Timber Framed Sash - 2 over 2 - Mid/Late 19th Century	NO
W11	WT8	Single Pane	Timber Framed Sash - 2 over 2 - Mid/Late 19th Century	NO
W12	WT9	Single Pane	Timber Framed Sash - 8 over 8 - Regency Era	NO
W13	WT10	Single Pane	Timber Framed Sash - 2 over 4 - Mid/Late 19th Century	NO
W14	WT10	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W15	WT10	Single Pane	Timber Framed Sash - 2 over 4 - Mid/Late 19th Century	NO
W16	WT10	Single Pane	Timber Framed Sash - 2 over 4 - Mid/Late 19th Century	NO
W17	WT11	Double Glazed	Modern Inset UPVC Casement	NO
W18	WT12	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W19	WT17	Single Pane	Timber Framed Sash - 2 over 4 - Mid/Late 19th Century	NO

WINDOW / DOOR SCHEDULE - MEWSBROOK CAREHOME - EXISTING CONDITION				
Ref	Window Type	Glazing	Condition / Type	Period Correct Replacement Required to Regularise with Local Authority
W20	WT14	Single Pane	Timber Casement - Mid/Late 19th Century	NO
W21	WT14	Single Pane	Timber Casement - Mid/Late 19th Century	NO
W22	WT15	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W23	WT15	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W24	WT16	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W25	WT16	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W26	WT17	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W27	WT17	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W28	WT15	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W29	WT18	Histoglass HD10	New Replacement period correct Timber Panelled Door / Glazed side	YES
W30	WT15	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W31	WT16	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W32	WT16	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W33	WT16	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W34	WT7	Single Pane	Timber Framed Sash - 2 over 2 - Mid/Late 19th Century	NO
W35	WT7	Single Pane	Timber Framed Sash - 2 over 2 - Mid/Late 19th Century	NO
W36	WT16	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W37	WT17	Histoglass HD10	New Replacement period correct Timber Sash Window	YES
W38	WT17	Histoglass HD10	New Replacement period correct Timber Sash Window	YES



Photo - Mid 20th century prior to unauthorised UPVC windows casement replacements

EDWSArchitects



26 Millers Road Brighton BN1 5NQ M 07979532275
e ewan@EDWSArchitects.co.uk w www.edwsarchitects.co.uk

J O B Mewsbrook House 59-61 East Street Littlehampton BN17 6AU	CHECKED LRA
	DRAWN ES
CLIENT Lifetime Care Ltd	DATE 26.05.26
	SCALE 1:50 @ A0
DRAWING Elevations Proposed - Replacement period Correct Windows	REVISION .
	NUMBER 7243/025

DO NOT SCALE FROM THIS DRAWING. THIS DRAWING IS COPYRIGHT ©