

From: Finlay Gardner <Finlay.Gardner@arun.gov.uk>
Sent: 11 January 2021 13:53
To: Planning.Responses <Planning.Responses@arun.gov.uk>
Cc: Sarah Burrow <Sarah.Burrow@arun.gov.uk>
Subject: M/90/20/DOC

Please attach as further information.

Finlay Gardner
Planning Officer,
Planning Department

T: 01903 737915
E: finlay.gardner@arun.gov.uk

Arun District Council, Civic Centre, Maltravers Rd, Littlehampton, West Sussex, BN17 5LF
www.arun.gov.uk



Sign up to our newsletter [here](#)



From: gary longhurst [REDACTED]
Sent: 11 January 2021 12:58
To: Finlay Gardner <Finlay.Gardner@arun.gov.uk>
Subject: Fw: As discussed. Thanks Tim. Gary

Hi Finlay, please find attached details from Tim Murray as discussed. The infiltration test was carried out in the monitoring pit when empty from memory. I have explained the break on the 13th March to you. The depth was as directed and the pit was approx 60 cm (width and depth.) Hope this helps.

Regards and thank you for your help on this matter.

Gary Longhurst

From: Tim Murray [REDACTED]
Sent: 08 January 2021 15:37
To: gary longhurst [REDACTED]
Subject: RE: As discussed. Thanks Tim. Gary

Hi Gary

Block plan attached with soakaway and surface water drains marked on.

Best Regards

Tim

Sent from [Mail](#) for Windows 10

From: [gary longhurst](#)
Sent: 07 January 2021 16:30
To: [Tim Murray](#)
Subject: As discussed. Thanks Tim. Gary

Sent from my iPhone