

Location of 1937 cut and 1910 breach shown in relation to recent outlet channel location



Drawing C