

P/97/15/PL.


198, Pagham Road,

Nyetimber,

Bognor Regis

PO21 3QB

14th March 2016




The Planning Officer,
Arun District Council,
Maltravers Road,
Littlehampton.
BN17 5LF

Dear Sir,

The escalation in the erosion of Pagham beach appears to have been caused by the formation of the sand bank to the south of the entrance to Pagham Harbour which has diverted the flow in and out of the harbour, to nearer the beach.

We all know that an urgent remedy is required. Is it not time to divert the harbour entrance flow through a channel in the sand bank?

Yours faithfully,



Ray Walter