

	ADC Drainage Comments 24/02/2025 [WA/106/24/DOC] The Barter Hill report includes numerous other photos which clearly show there are defects and issues on phase 1 so it is expected that defects will exist for phase 2 once summarised. Comment outstanding. Designer Comments 1/04/2025 [WA/106/24/DOC] Comment updated			
	ADC Drainage Comments 03.08.2023 [WA/17/23/DOC – Full Site] Page 28 photo evidence shows headwall 1F detritus at the base. ADC Drainage Comments 24/02/2025 [WA/106/24/DOC] Construction records details of all phase 2 headwalls to be provided. Comment outstanding	Comment not answered; have remedial works been undertaken and can another photo be evidence?		Comment not answered; have remedial works been undertaken and can another photo be evidence? Comment outstanding.
	ADC Drainage Comments 03.08.2023 [WA/17/23/DOC – Full Site]	Noted. Comment closed		Swale & Headwall 1F inspected on 16th July 2025 - both well maintained & functioning. Photo showing swale 1F with remedials completed is on page 46 of the report in appendix C 