



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	FLOW %	0
---------	-----	--------	---

System	SW	Video reference	
Upstream M/H	SW 4.0	Downstream M/H	SW 4.1
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	25 m
Pipe Size	225mm		
Material		VC	Other

Comments

There are no visible defects on this line

Sketch



Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure

Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	RAIN	FLOW %	0
---------	------------	------	--------	---

System		SW	Video reference		
Upstream M/H	4.1		Downstream M/H		4.1a
Sewer Depth			Sewer Depth		
Direction		D/S	Distance surveyed		m
Pipe Size	225mm				
Material			VC		Other

Comments

--

Sketch

START	4.1	Ch.	Comments	Severity
		0.00	Start survey	
			10.1m connection @ 10 o'clock	
		12.5m	Enters manhole	0
		12.5m	End survey	
FINISH	4.1a			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	4.1a	Downstream M/H	4.2
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	11.5 m
Pipe Size	225mm		
Material		VC	Other

Comments

There are no visible defects in this line

Sketch

START	4.1a	Ch.	Comments	Severity
		0.00	Start survey	
				
		11.50	Enters manhole	0
		11.50	End survey	
FINISH	4.2			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	5,0	Downstream M/H	4.2
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	m
Pipe Size	225mm		
Material		VC	Other

Comments

There are no visible defects in this line

Sketch



Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	1.5	Downstream M/H	4.2
Sewer Depth		Sewer Depth	
Direction	U/S	Distance surveyed	39.2 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch



Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	1.5	Downstream M/H	1.5a
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	37.2 m
Pipe Size	525mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch

START	1.5	Ch.	Comments	Severity
		0.00	Start survey	
			3.4m connection @ 12 o'Clock	
		37.20	Enters manhole	0
		37.20	End survey	
FINISH	1.5a			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	1.2	Downstream M/H	1.3
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	37.2 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch

		Ch.	Comments	Severity
START	1.2			
		0.00	Start survey	
				
		37.20	Enters manhole	0
		37.20	End survey	
FINISH	1.3			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	1.3	Downstream M/H	1.4
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	25.5 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch



0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	2,0	Downstream M/H	1.1
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	6.6 m
Pipe Size	300mm		
Material	conc		Other

Comments

There are no visible defects in this line

Sketch

START	2,0	Ch.	Comments	Severity
		0.00	Start survey	
		6.60	Enters manhole	0
		6.60	End survey	
FINISH	1.1			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	1,0	Downstream M/H	1.1
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	28.9 m
Pipe Size	225mm		
Material		VC	Other

Comments

There are no visible defects in this line

Sketch



0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	RAIN	FLOW %	0
---------	-----	------	--------	---

System	SW	Video reference	
Upstream M/H	1.1	Downstream M/H	1.2
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	13 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch

START	1.1	Ch.	Comments	Severity
		0.00	Start survey	
		13.00	Enters manhole	0
		13.00	End survey	
FINISH	1.2			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	FLOW %	0
---------	-----	--------	---

System	SW	Video reference	
Upstream M/H	1.6	Downstream M/H	1.7
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	31.5 m
Pipe Size	525mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch

START	1.6	Ch.	Comments	Severity
		0.00	Start survey	
		31.50	Enters manhole	0
FINISH	1.7	31.50	End survey	

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	FLOW %	0
---------	-----	--------	---

System	SW	Video reference	
Upstream M/H	6.4	Downstream M/H	6.4a
Sewer Depth		Sewer Depth	
Direction	U/S	Distance surveyed	20 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch



Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	FLOW %	0
---------	-----	--------	---

System	SW	Video reference	
Upstream M/H	6.4	Downstream M/H	6.5
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	21.5 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch



Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
 Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		


Weather	DRY	FLOW %	0
---------	-----	--------	---

System	SW	Video reference	
Upstream M/H	6.5	Downstream M/H	1.6
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	14.8 m
Pipe Size	300mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch



Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure



Registered Office: Yelfs Yard, Botley Road, Bishops Waltham, Southampton, Hants, SO32 1DR
Reg No. 2965597 VAT No. 834 8735 95 UTR No. 1920154194

Date	14/01/2025		
Site	LH286 - Linden Homes Walberton		
Plot	Infrastructure	Postcode	BN18 0LS
House number / Road	Infrastructure		

Weather	DRY	FLOW %	0
---------	-----	--------	---

System	SW	Video reference	
Upstream M/H	1.5a	Downstream M/H	1.6
Sewer Depth		Sewer Depth	
Direction	D/S	Distance surveyed	20.5 m
Pipe Size	525mm		
Material	Conc		Other

Comments

There are no visible defects in this line

Sketch

START	1.5a	Ch.	Comments	Severity
		0.00	Start survey	
				
		20.50	Enters manhole	0
		20.50	End survey	
FINISH	1.6			

Severity:

0 - No issue, 1 - No action required, 2 - Monitor, 3 - Consider remedial action, 4 - Remedial action required, 5 - failure