

Conservation Area Advisory Committee

Meeting Date : 6th of November 2017

Ref	Description	Address	Design award
Y/65/17/HH	Buttressing & repair of failed flint wall. This application affects the setting of a Listed Building & the Character & Appearance of the Yapton (Main Road/Church Road) Conservation Area.	Rumford Church Road Yapton BN18 0EW	
Comments: <i>No objection</i> Suggested Conditions: <i>SAMPLES OF MATERIALS AND A SAMPLE PAINT OF THE FLINT WORK TO BE AGREED WITH THE LPA</i>			