

Site: Stakers Farm, Yapton
Date: 26/03/2020

		Water Depth (m)															
		02/10/2019	18/10/2019	04/11/2019	07/11/2019	15/11/2019	20/11/2019	06/12/2019	16/12/2019	02/01/2020	16/01/2020	31/01/2020	07/02/2020	13/02/2020	24/02/2020	12/03/2020	26/03/2020
New	WS01	-	-	-	3.41	-	3.05	3.03	2.60	2.38	2.53	2.90	2.65	2.00	N/A**	1.93	2.98
	WS02	-	-	-	Dry	-	Dry	4.22	3.90	3.46	3.89	4.10	3.94	3.71	3.04	3.10	4.14
	WS01	Dry	Dry	Dry	CNF	Dry	Dry	Dry	Dry	2.95	2.96	3.36	2.94	2.95	2.40	2.48	2.90
	WS04	Dry	Dry	Dry	Dry	-	Dry	Dry	Dry	2.93	2.95	2.95	2.97	2.96	2.94	Dry	2.93
Old	WS05	4.76	4.28	3.97	CNF	3.44	3.35	3.31	2.85	2.40	2.11	2.90	2.65	1.71	1.85	1.97	3.10
	WS06	Dry	Dry	Dry	2.46	-	2.05	2.00	1.55	1.10	CNF	1.53	1.60	N/A*	N/A***	0.63	1.87
	WS09	4.66	4.24	3.85	3.72	-	3.56	3.24	2.80	2.60	2.74	3.10	2.87	2.21	1.96	2.11	3.20
	WS10	Dry	Dry	Dry	Dry	-	Dry	Dry	2.85	2.45	2.55	2.93	2.77	1.65	1.50	2.04	2.90
		WYG	WYG	WYG	GESL	GESL	GESL	GESL	GESL	GESL	GESL	GESL	GESL	GESL	GESL	GESL	GESL

		Base Depth (m)														
New	WS01	-	-	-	4.90	-	4.85	4.85	-	4.85	4.82	4.85	4.80	4.80	4.80	4.80
	WS02	-	-	-	4.45	-	4.45	4.45	-	4.50	4.45	4.45	4.46	4.48	3.44	4.44
	WS01	3.05	3.03	3.03	CNF	2.95	2.95	2.97	-	3.00	2.97	4.89	2.95	2.96	2.90	2.90
	WS04	3.06	3.06	3.06	2.95	-	2.95	2.95	-	2.95	2.96	3.00	2.98	2.97	2.95	2.95
Old	WS05	5.80	5.79	5.75	CNF	5.65	5.65	5.65	-	5.65	4.53	5.65	4.58	4.55	5.65	5.75
	WS06	2.84	2.82	2.85	2.75	-	2.78	2.73	-	2.75	CNF	2.75	2.78	2.78	2.76	2.75
	WS09	4.76	4.84	4.78	4.70	-	4.65	4.65	-	4.65	4.64	4.65	4.65	4.65	4.64	4.63
	WS10	3.03	3.03	2.97	2.93	-	2.95	2.95	-	2.95	2.95	2.93	2.95	2.95	2.94	2.95

Key	
CNF	Could Not Find
	Highest reading
Noted on records as WS01 but should be WS01old based on Base Depth.	
Depths do not appear to be WS01 Old	
N/A*	Water level is not representative as the surface water washed into the well as soon as flush fitted cover has been opened for the monitoring/recording.
N/A**	Nearby Collapsed well is noted (possibly WS01). Water was encountered at 1.15m bgl - visible depth of the collapsed well was 1.5mbgl
N/A***	The area of the WS06 was flooded, no access was gained during the return visit.