Project

Project Name:	DAISY FIELDS.LITTLEHAMPTON.BN17 6LT
Project Description:	TO CARRY OUT CCTV SURVEY AT THE ABOVE ADDRESS
Project Number:	02
Project Status:	Complete
Project Date:	30/06/2025
Inspection Standard:	MSCC5 Sewers & Drainage GB (SRM5 Scoring)

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Table of Contents

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Project Information P-1
Scoring Summary P-3
Project Summary P-5
Section Item 1: L1 > FIC 1 (L1X) 1
Section Item 2: L2 > FIC 1 (L2X) 3
Section Item 3: L3 > FIC 1 (L3X) 5
Section Item 4: FIC 1 > FIC 2 (FIC 1X) 8
Section Item 5: L5 > FIC 2 (L5X) 10
Section Item 6: L6 > FIC 2 (L6X) 13
Section Item 7: L7 > FIC 2 (L7X) 16
Section Item 8: FIC 2 > FMH52 (FIC 2X) 18
Section Item 9: L9 > FIC 3 (L9X) 21
Section Item 10: L11 > FIC 3 (L11X) 23
Section Item 11: L12 > FIC 3 (L12X) 25
Section Item 12: FIC 3 > FIC 4 (FIC 3X) 28
Section Item 13: L14 > FIC 4 (L14X) 30
Section Item 14: L15 > FIC 4 (L15X) 33
Section Item 15: L16 > FIC 4 (L16X) 35
Section Item 16: FIC 4 > MAIN (FIC 4X) 37
Section Item 17: L18 > FIC 5 (L18X) 39
Section Item 18: FIC 6 > FIC 5 (FIC 6X) 42
Section Item 19: L20 > FIC 5 (L20X) 44
Section Item 20: L21 > FIC 5 (L21X) 46
Section Item 21: L22 > FIC 6 (L22X) 48
Section Item 22: L23 > FIC 6 (L23X) 50
Section Item 23: L24 > FIC 6 (L24X) 52
Section Item 24: FIC 5 > MAIN (FIC 5X) 55
Section Item 25: L26 > FIC 7 (L26X) 58
Section Item 26: L27 > FIC 7 (L27X) 61

Table of Contents

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Section Item 27: L28 > FIC 7 (L28X) 63
Section Item 28: FIC 8 > FIC 7 (FIC 8X) 65
Section Item 29: FIC 7 > MAIN (FIC 7X) 67
Section Item 30: L31 > FIC 8 (L31X) 70
Section Item 31: L32 > FIC 8 (L32X) 73
Section Item 32: L33 > FIC 8 (L33X) 75
Section Item 33: FIC 9 > MAIN (FIC 9X) 78
Section Item 34: PPCP 1 > SMH32 (PPCP 1X) 80
Section Item 35: FIC 10 > FMH77 (FIC 10X) 82
Section Item 36: FIC 11 > FMH77 (FIC 11X) 84
Section Item 37: FMH77 > FMH56 (FMH77X) 86
Section Item 38: FIC 12 > MAIN (FIC 12X) 88
Section Item 39: PPCP 2 > SMH49 (PPCP 2X) 90
Section Item 40: PPCP 4 > SMH49 (PPCP 4X) 92
Section Item 41: L43 > SMH49 (L43X) 94
Section Item 42: SMH49 > SMH32 (SMH49X) 96
Section Item 43: FMH51 > FMH56 (FMH51X) 98
Section Item 44: FIC 13 > MAIN (FIC 13X) 100
Section Item 45: FIC 14 > FMH78 (FIC 14X) 102
Section Item 46: PPCP 3 > SMH19 (PPCP 3X) 105
Section Item 47: SMH32 > SMH19 (SMH32X) 107
Section Item 48: FMH78 > FMH81 (FMH78X) 110
Section Item 49: FMH52 > FMH59 (FMH52X) 113
Section Item 50: FIC 16 > MAIN (FIC 16X) 116
Section Item 51: SMH75 > SMH42 (SMH75X) 119
Section Item 52: FIC 15 > FMH58 (FIC 15X) 122
Section Item 53: FMH58 > FMH59 (FMH58X) 125
Section Item 54: SMH62 > SMH35 (SMH62X) 127
Section Item 55: SMH35 > SMH7 (SMH35X) 130

Table of Contents

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Section Item 56: SMH7 > SMH44 (SMH7X) 132
Section Item 57: SMH44 > SMH6 (SMH44X) 134
Section Item 58: SMH6 > SMH5 (SMH6X) 138
Section Item 60: FMH57 > FMH54 (FMH57X) 141
Section Item 61: FMH54 > FMH68 (FMH54X) 144
Section Item 62: FMH68 > FMH70 (FMH68X) 146

Project Information

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Site

Street: DAISY FIELDS
Town or City: LITTLEHAMPTON
Phone: BN17 6LT

Contractor

Company: PROLINE DRAINAGE LTD
Street: CHARLWOOD ROAD
Town or City: CRAWLEY
Post Code: RH11 0JY
Phone:
Email: [redacted]

Project Information

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Project Drawing, Page 'DAISY FIELDS.LITTLEHAMPTON.BN17 6LT'



Scoring Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Structural Defects

Grade 3: Best practice suggests consideration should be given to repairs in the medium term.

Grade 4: Best practice suggests consideration should be given to repairs to avoid a potential collapse.

Grade 5: Best practice suggests that this pipe is at risk of collapse at any time. Urgent consideration should be given to repairs to avoid total failure.

Section	PLR	Grade	Description

Service / Operational Condition

Grade 3: Best practice suggests consideration should be given to maintenance activities in the medium term.

Grade 4: Best practice suggests consideration should be given to maintenance activity to avoid potential blockages.

Grade 5: Best practice suggests that this pipe is at a high risk of backing up or causing flooding.

Section	PLR	Grade	Description
25	L26X	3	Settled deposits, coarse, 5% cross-sectional area loss
34	PPCP 1X	3	Settled deposits, coarse, 5% cross-sectional area loss
35	FIC10X	4	Settled deposits, coarse, 15% cross-sectional area loss
47	SMH32	3	Settled deposits, coarse, 10% cross-sectional area loss
48	FMH78X	3	Settled deposits, coarse, 10% cross-sectional area loss
55	SMH35X	3	Settled deposits, coarse, 5% cross-sectional area loss
56	SMH7X	3	Settled deposits, coarse, 5% cross-sectional area loss
57	SMH44X	3	Settled deposits, coarse, 5% cross-sectional area loss
58	SMH6X	3	Settled deposits, coarse, 10% cross-sectional area loss
61	FMH54X	3	Settled deposits, coarse, 5% cross-sectional area loss
62	FMH68X	3	Settled deposits, coarse, 5% cross-sectional area loss

Scoring Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Abandoned Surveys

Section	PLR	Description
43	FMH51X	Survey abandoned
47	SMH32X	Survey abandoned
48	FMH78X	Survey abandoned
58	SMH6X	Survey abandoned
62	FMH68X	Survey abandoned

Information

These scoring summaries are based on the SRM grading from the WRc.

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Pipe Summary

No.	Type	PLR	Upstream Node	Downstream Node	Road	Town	Use	Mat.	Profile	Length
1	SEC	L1X	L1	FIC 1	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.06 m
2	SEC	L2X	L2	FIC 1	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.91 m
3	SEC	L3X	L3	FIC 1	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	10.11 m
4	SEC	FIC 1X	FIC 1	FIC 2	Daisy Fields	Littlehampton	F	VC	Circular 100mm	0.30 m
5	SEC	L5X	L5	FIC 2	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.79 m
6	SEC	L6X	L6	FIC 2	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.81 m
7	SEC	L7X	L7	FIC 2	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	4.98 m
8	SEC	FIC 2X	FIC 2	FMH52	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.52 m
9	SEC	L9X	L9	FIC 3	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	4.81 m
10	SEC	L11X	L11	FIC 3	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.60 m
11	SEC	L12X	L12	FIC 3	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	11.52 m
12	SEC	FIC 3X	FIC 3	FIC 4	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	0.41 m
13	SEC	L14X	L14	FIC 4	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	10.03 m
14	SEC	L15X	L15	FIC 4	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.76 m
15	SEC	L16X	L16	FIC 4	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.56 m
16	SEC	FIC 4X	FIC 4	MAIN	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	12.29 m
17	SEC	L18X	L18	FIC 5	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	11.03 m
18	SEC	FIC 6X	FIC 6	FIC 5	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	0.12 m
19	SEC	L20X	L20	FIC 5	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.91 m
20	SEC	L21X	L21	FIC 5	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.95 m
21	SEC	L22X	L22	FIC 6	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.63 m
22	SEC	L23X	L23	FIC 6	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.77 m
23	SEC	L24X	L24	FIC 6	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	11.24 m
24	SEC	FIC 5X	FIC 5	MAIN	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.02 m
25	SEC	L26X	L26	FIC 7	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	10.81 m
26	SEC	L27X	L27	FIC 7	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	10.11 m
27	SEC	L28X	L28	FIC 7	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.20 m
28	SEC	FIC 8X	FIC 8	FIC 7	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	0.53 m
29	SEC	FIC 7X	FIC 7	MAIN	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.79 m
30	SEC	L31X	L31	FIC 8	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	10.53 m

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

No.	Type	PLR	Upstream Node	Downstream Node	Road	Town	Use	Mat.	Profile	Length
31	SEC	L32X	L32	FIC 8	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.49 m
32	SEC	L33X	L33	FIC 8	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	5.42 m
33	SEC	FIC 9X	FIC 9	MAIN	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	9.46 m
34	SEC	PPCP 1X	PPCP 1	SMH32	Daisy Fields	Littlehampton	S	VC	Circular 100mm	13.13 m
35	SEC	FIC10X	FIC10	FMH77	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	8.28 m
36	SEC	FIC 11X	FIC 11	FMH77	Daisy Fields	Littlehampton	F	VC	Circular 100mm	9.63 m
37	SEC	FMH77X	FMH77	FMH56	Daisy Fields	Littlehampton	F	VC	Circular 150mm	23.97 m
38	SEC	FIC 12X	FIC 12	MAIN	Daisy Fields	Littlehampton	F	VC	Circular 100mm	11.67 m
39	SEC	PPCP 2X	PPCP 2	SMH49	Daisy Fields	Littlehampton	S	VC	Circular 100mm	16.27 m
40	SEC	PPCP 4X	PPCP 4	SMH49	Daisy Fields	Littlehampton	S	VC	Circular 100mm	15.63 m
41	SEC	L43X	L43	SMH49	Daisy Fields	Littlehampton	S	VC	Circular 100mm	0.18 m
42	SEC	SMH49X	SMH49	SMH32	Daisy Fields	Littlehampton	S	VC	Circular 225mm	12.43 m
43	SEC	FMH51X	FMH51	FMH56	Daisy Fields	Littlehampton	F	VC	Circular 150mm	30.50 m
44	SEC	FIC 13X	FIC 13	MAIN	Daisy Fields	Littlehampton	F	VC	Circular 150mm	7.03 m
45	SEC	FIC 14X	FIC 14	FMH78	Daisy Fields	Littlehampton	F	VC	Circular 150mm	9.70 m
46	SEC	PPCP 3X	PPCP 3	SMH19	Daisy Fields	Littlehampton	S	VC	Circular 100mm	7.53 m
47	SEC	SMH32X	SMH32	SMH19	Daisy Fields	Littlehampton	S	CO	Circular 525mm	19.08 m
48	SEC	FMH78X	FMH78	FMH81	Daisy Fields	Littlehampton	S	VC	Circular 150mm	45.14 m
49	SEC	FMH52X	FMH52	FMH59	Daisy Fields	Littlehampton	F	VC	Circular 150mm	40.23 m
50	SEC	FIC16X	FIC16	MAIN	Daisy Fields	Littlehampton	F	PVC	Circular 100mm	4.96 m
51	SEC	SMH75X	SMH75	SMH42	Daisy Fields	Littlehampton	S	CO	Circular 450mm	19.47 m
52	SEC	FIC15X	FIC15	FMH58	Daisy Fields	Littlehampton	F	VC	Circular 150mm	13.42 m
53	SEC	FMH58X	FMH58	FMH59	Daisy Fields	Littlehampton	F	VC	Circular 100mm	25.35 m
54	SEC	SMH62X	SMH62	SMH35	Daisy Fields	Littlehampton	S	CO	Circular 525mm	32.70 m
55	SEC	SMH35X	SMH35	SMH7	Daisy Fields	Littlehampton	S	CO	Circular 525mm	9.30 m
56	SEC	SMH7X	SMH7	SMH44	Daisy Fields	Littlehampton	S	CO	Circular 525mm	7.00 m
57	SEC	SMH44X	SMH44	SMH6	Daisy Fields	Littlehampton	S	CO	Circular 525mm	67.20 m
58	SEC	SMH6X	SMH6	SMH5	Daisy Fields	Littlehampton	S	CO	Circular 525mm	18.00 m
59	SEC	FMH57X	FMH57	FMH54	Daisy Fields	Littlehampton	F	VC	Circular 150mm	13.60 m
60	SEC	FMH54X	FMH54	FMH68	Daisy Fields	Littlehampton	F	VC	Circular 150mm	9.80 m
61	SEC	FMH68X	FMH68	FMH70	Daisy Fields	Littlehampton	F	VC	Circular 150mm	46.80 m

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

No.	Type	PLR	Upstream Node	Downstream Node	Road	Town	Use	Mat.	Profile	Length
									Total:	**787.47 m**

Pipe Levels

No.	PLR	Upstream Node	Upstream C.L.	Upstream I.L.	Upstream I.D.	Downstream Node	Downstream C.L.	Downstream I.L.	Downstream I.D.
1	L1X	L1			0.000 m	FIC 1			0.580 m
2	L2X	L2			0.000 m	FIC 1			0.580 m
3	L3X	L3			0.000 m	FIC 1			0.580 m
4	FIC 1X	FIC 1			0.580 m	FIC 2			0.580 m
5	L5X	L5			0.000 m	FIC 2			0.580 m
6	L6X	L6			0.000 m	FIC 2			0.580 m
7	L7X	L7			0.000 m	FIC 2			0.580 m
8	FIC 2X	FIC 2			0.580 m	FMH52			0.000 m
9	L9X	L9			0.000 m	FIC 3			0.580 m
10	L11X	L11			0.000 m	FIC 3			0.580 m
11	L12X	L12			0.000 m	FIC 3			0.580 m
12	FIC 3X	FIC 3			0.580 m	FIC 4			0.580 m
13	L14X	L14			0.000 m	FIC 4			0.580 m
14	L15X	L15			0.000 m	FIC 4			0.580 m
15	L16X	L16			0.000 m	FIC 4			0.580 m
16	FIC 4X	FIC 4			0.580 m	MAIN			0.000 m
17	L18X	L18			0.000 m	FIC 5			0.560 m
18	FIC 6X	FIC 6			0.000 m	FIC 5			0.560 m
19	L20X	L20			0.000 m	FIC 5			0.560 m
20	L21X	L21			0.000 m	FIC 5			0.560 m
21	L22X	L22			0.000 m	FIC 6			0.580 m
22	L23X	L23			0.000 m	FIC 6			0.580 m
23	L24X	L24			0.000 m	FIC 6			0.580 m
24	FIC 5X	FIC 5			0.580 m	MAIN			0.000 m
25	L26X	L26			0.000 m	FIC 7			0.580 m

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

No.	PLR	Upstream Node	Upstream C.L.	Upstream I.L.	Upstream I.D.	Downstream Node	Downstream C.L.	Downstream I.L.	Downstream I.D.
26	L27X	L27			0.000 m	FIC 7			0.580 m
27	L28X	L28			0.000 m	FIC 7			0.580 m
28	FIC 8X	FIC 8			0.580 m	FIC 7			0.580 m
29	FIC 7X	FIC 7			0.580 m	MAIN			0.000 m
30	L31X	L31			0.000 m	FIC 8			0.580 m
31	L32X	L32			0.000 m	FIC 8			0.580 m
32	L33X	L33			0.000 m	FIC 8			0.580 m
33	FIC 9X	FIC 9			0.580 m	MAIN			0.000 m
34	PPCP 1X	PPCP 1			0.000 m	SMH32			0.000 m
35	FIC10X	FIC10			0.870 m	FMH77			0.700 m
36	FIC 11X	FIC 11			0.000 m	FMH77			0.700 m
37	FMH77X	FMH77			0.700 m	FMH56			0.000 m
38	FIC 12X	FIC 12			0.480 m	MAIN			0.000 m
39	PPCP 2X	PPCP 2			0.000 m	SMH49			0.580 m
40	PPCP 4X	PPCP 4			0.000 m	SMH49			0.700 m
41	L43X	L43			0.000 m	SMH49			0.700 m
42	SMH49X	SMH49			0.700 m	SMH32			0.000 m
43	FMH51X	FMH51			0.000 m	FMH56			1.670 m
44	FIC 13X	FIC 13			1.670 m	MAIN			0.000 m
45	FIC 14X	FIC 14			1.670 m	FMH78			0.000 m
46	PPCP 3X	PPCP 3			0.000 m	SMH19			0.000 m
47	SMH32X	SMH32			1.520 m	SMH19			0.000 m
48	FMH78X	FMH78			1.520 m	FMH81			0.000 m
49	FMH52X	FMH52			1.580 m	FMH59			0.000 m
50	FIC16X	FIC16			0.580 m	MAIN			0.000 m
51	SMH75X	SMH75			1.400 m	SMH42			0.000 m
52	FIC15X	FIC15			0.000 m	FMH58			1.530 m
53	FMH58X	FMH58			1.530 m	FMH59			0.000 m
54	SMH62X	SMH62			0.000 m	SMH35			0.000 m
55	SMH35X	SMH35			0.000 m	SMH7			0.000 m
56	SMH7X	SMH7			0.000 m	SMH44			0.000 m
57	SMH44X	SMH44			0.000 m	SMH6			0.000 m

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

No.	PLR	Upstream Node	Upstream C.L.	Upstream I.L.	Upstream I.D.	Downstream Node	Downstream C.L.	Downstream I.L.	Downstream I.D.
58	SMH6X	SMH6			0.000 m	SMH5			0.000 m
59	FMH57X	FMH57			2.700 m	FMH54			0.000 m
60	FMH54X	FMH54			0.000 m	FMH68			0.000 m
61	FMH68X	FMH68			0.000 m	FMH70			0.000 m

Pipe Summary by Profile

Profile	Total Length	No. Pipes
Circular 100mm	5.06 m	
Circular 100mm	9.91 m	
Circular 100mm	10.11 m	
Circular 100mm	0.30 m	
Circular 100mm	9.79 m	
Circular 100mm	9.81 m	
Circular 100mm	4.98 m	
Circular 100mm	9.52 m	
Circular 100mm	4.81 m	
Circular 100mm	9.60 m	
Circular 100mm	11.52 m	
Circular 100mm	0.41 m	
Circular 100mm	10.03 m	
Circular 100mm	9.76 m	
Circular 100mm	5.56 m	
Circular 100mm	12.29 m	
Circular 100mm	11.03 m	
Circular 100mm	0.12 m	
Circular 100mm	9.91 m	
Circular 100mm	5.95 m	
Circular 100mm	5.63 m	
Circular 100mm	9.77 m	
Circular 100mm	11.24 m	
Circular 100mm	5.02 m	
Circular 100mm	10.81 m	
Circular 100mm	10.11 m	
Circular 100mm	5.20 m	
Circular 100mm	0.53 m	
Circular 100mm	5.79 m	
Circular 100mm	10.53 m	
Circular 100mm	9.49 m	
Circular 100mm	5.42 m	
Circular 100mm	9.46 m	

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Profile		Total Length	No. Pipes
Circular 100mm		13.13 m	
Circular 100mm		8.28 m	
Circular 100mm		9.63 m	
Circular 100mm		11.67 m	
Circular 100mm		16.27 m	
Circular 100mm		15.63 m	
Circular 100mm		0.18 m	
Circular 100mm		7.53 m	
Circular 100mm		4.96 m	
Circular 100mm		25.35 m	
Circular 100mm	=	362.10 m	43
Circular 150mm		23.97 m	
Circular 150mm		30.50 m	
Circular 150mm		7.03 m	
Circular 150mm		9.70 m	
Circular 150mm		45.14 m	
Circular 150mm		40.23 m	
Circular 150mm		13.42 m	
Circular 150mm		13.60 m	
Circular 150mm		9.80 m	
Circular 150mm		46.80 m	
Circular 150mm	=	240.19 m	10
Circular 225mm		12.43 m	
Circular 225mm	=	12.43 m	1
Circular 450mm		19.47 m	
Circular 450mm	=	19.47 m	1
Circular 525mm		19.08 m	
Circular 525mm		32.70 m	
Circular 525mm		9.30 m	
Circular 525mm		7.00 m	
Circular 525mm		67.20 m	
Circular 525mm		18.00 m	
Circular 525mm	=	153.28 m	6
Total	**=**	**787.47 m**	**61**

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Inspection Summary

Pipe No.	Insp. No.	Upstream Node	Downstream Node	Dir.	Operator	Insp. Date	Insp. Time	Str	Ser	Final Observation	Length
1	1	L1	FIC 1	US		30/06/2025	12:59	1	1	OCF, REST BEND	5.06 m
2	1	L2	FIC 1	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.91 m
3	1	L3	FIC 1	US		30/06/2025	12:59	1	1	OCF, REST BEND	10.11 m
4	1	FIC 1	FIC 2	DS		30/06/2025	12:59	1	1	MHF	0.30 m
5	1	L5	FIC 2	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.79 m
6	1	L6	FIC 2	US		30/06/2025	12:59	1	3	OCF, REST BEND	9.81 m
7	1	L7	FIC 2	US		30/06/2025	12:59	1	1	OCF, REST BEND	4.98 m
8	1	FIC 2	FMH52	DS		30/06/2025	12:59	1	3	MHF	9.52 m
9	1	L9	FIC 3	US		30/06/2025	12:59	1	1	OCF, REST BEND	4.81 m
10	1	L11	FIC 3	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.60 m
11	1	L12	FIC 3	US		30/06/2025	12:59	1	1	OCF, REST BEND	11.52 m
12	1	FIC 3	FIC 4	DS		30/06/2025	12:59	1	1	MHF	0.41 m
13	1	L14	FIC 4	US		30/06/2025	12:59	1	1	OCF, REST BEND	10.03 m
14	1	L15	FIC 4	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.76 m
15	1	L16	FIC 4	US		30/06/2025	12:59	1	1	OCF, REST BEND	5.56 m
16	1	FIC 4	MAIN	DS		30/06/2025	12:59	1	1	BRF, MAINLINE	12.29 m
17	1	L18	FIC 5	US		30/06/2025	12:59	1	4	OCF, CAPPED	11.03 m
18	1	FIC 6	FIC 5	US		30/06/2025	12:59	1	1	MHF	0.12 m
19	1	L20	FIC 5	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.91 m
20	1	L21	FIC 5	US		30/06/2025	12:59	1	1	OCF, REST BEND	5.95 m
21	1	L22	FIC 6	US		30/06/2025	12:59	4	1	OCF, REST BEND	5.63 m
22	1	L23	FIC 6	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.77 m
23	1	L24	FIC 6	US		30/06/2025	12:59	1	1	OCF, CAPPED	11.24 m
24	1	FIC 5	MAIN	DS		30/06/2025	12:59	1	1	BRF, MAINLINE	5.02 m
25	1	L26	FIC 7	US		30/06/2025	12:59	1	3	OCF, CAPPED	10.81 m
26	1	L27	FIC 7	US		30/06/2025	12:59	1	1	OCF, REST BEND	10.11 m
27	1	L28	FIC 7	US		30/06/2025	12:59	1	3	OCF, REST BEND	5.20 m
28	1	FIC 8	FIC 7	US		30/06/2025	12:59	1	1	MHF	0.53 m
29	1	FIC 7	MAIN	DS		30/06/2025	12:59	1	3	BRF	5.79 m
30	1	L31	FIC 8	US		30/06/2025	12:59	1	1	OCF, CAPPED	10.53 m

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Pipe No.	Insp. No.	Upstream Node	Downstream Node	Dir.	Operator	Insp. Date	Insp. Time	Str	Ser	Final Observation	Length
31	1	L32	FIC 8	US		30/06/2025	12:59	1	1	OCF, REST BEND	9.49 m
32	1	L33	FIC 8	US		30/06/2025	12:59	1	1	OCF, REST BEND	5.42 m
33	1	FIC 9	MAIN	DS		30/06/2025	12:59	1	1	BRF, MAINLINE	9.46 m
34	1	PPCP 1	SMH32	DS		30/06/2025	12:59	1	3	MHF	13.13 m
35	1	FIC10	FMH77	DS		30/06/2025	12:59	1	3	MHF	8.28 m
36	1	FIC 11	FMH77	US		30/06/2025	12:59	1	1	MHF	9.63 m
37	1	FMH77	FMH56	DS		30/06/2025	12:59	1	1	MHF, CAPPED	23.97 m
38	1	FIC 12	MAIN	DS		30/06/2025	12:59	1	3	BRF	11.67 m
39	1	PPCP 2	SMH49	US		30/06/2025	12:59	1	3	MHF	16.27 m
40	1	PPCP 4	SMH49	US		30/06/2025	12:59	1	3	OCF, LINE OPEN	15.63 m
41	1	L43	SMH49	US		30/06/2025	12:59	1	1	OCF, LINE OPEN	0.18 m
42	1	SMH49	SMH32	DS		30/06/2025	12:59	1	1	MHF	12.43 m
43	**1**	**FMH51**	**FMH56**	**US**		**30/06/2025**	**12:59**	**1**	**1**	**SA, LINE NOT INSTALLED**	**30.50 m**
44	1	FIC 13	MAIN	DS		30/06/2025	12:59	1	1	BRF	7.03 m
45	1	FIC 14	FMH78	DS		30/06/2025	12:59	4	3	MHF	9.70 m
46	1	PPCP 3	SMH19	DS		30/06/2025	12:59	1	3	MHF	7.53 m
47	**1**	**SMH32**	**SMH19**	**US**		**30/06/2025**	**12:59**	**1**	**4**	**SA, UNABLE TO PUSH**	**19.08 m**
48	**1**	**FMH78**	**FMH81**	**DS**		**30/06/2025**	**12:59**	**1**	**4**	**SA, UNABLE TO PUSH**	**45.14 m**
49	1	FMH52	FMH59	DS		30/06/2025	12:59	1	1	MHF	40.23 m
50	1	FIC16	MAIN	DS		30/06/2025	12:59	1	1	BRF, MAINLINE	4.96 m
51	1	SMH75	SMH42	DS		30/06/2025	12:59	1	1	MHF	19.47 m
52	1	FIC15	FMH58	US		30/06/2025	12:59	1	1	MHF	13.42 m
53	1	FMH58	FMH59	DS		30/06/2025	12:59	1	1	MHF	25.35 m
54	1	SMH62	SMH35	DS		08/07/2025	14:33	1	1	MHF	32.70 m
55	1	SMH35	SMH7	DS		08/07/2025	14:33	1	3	MHF	9.30 m
56	1	SMH7	SMH44	DS		08/07/2025	14:33	1	3	MHF	7.00 m
57	1	SMH44	SMH6	DS		08/07/2025	14:33	1	3	MHF	67.20 m
58	**1**	**SMH6**	**SMH5**	**DS**		**08/07/2025**	**14:33**	**1**	**4**	**SA, MASS DEBRIE IN LINE**	**18.00 m**
59	1	FMH57	FMH54	DS		08/07/2025	14:33	1	4	MHF	13.60 m
60	1	FMH54	FMH68	DS		08/07/2025	14:33	1	3	MHF	9.80 m
61	**1**	**FMH68**	**FMH70**	**DS**		**08/07/2025**	**14:33**	**3**	**3**	**SA, UNABLE TO GO ANY FURTHER**	**46.80 m**

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Pipe No.	Insp. No.	Upstream Node	Downstream Node	Dir.	Operator	Insp. Date	Insp. Time	Str	Ser	Final Observation	Length
										Total:	787.47 m

Defect Summary

				CCTV Drainage Survey Observation Count																					
				General				Structural Condition									Service Condition						Misc	
Sect. No.	Insp. No.	Upstream Node	Downstream Node	Insp. Length (m)	No. Grade 4/5 Obs.	Survey Abandoned	Camera Under Water	Cracks	Fractures	Broken	Deformed	Collapsed	Holes	Surface Damage	Displaced Joints	Open Joints	Roots	Infiltration	Encrustation	Silt	Grease	Obstruction	Water Level	Line Deviates
1	1	L1	FIC 1	5.1																			1	1
2	1	L2	FIC 1	9.9																			1	1
3	1	L3	FIC 1	10.1																			1	1
4	1	FIC 1	FIC 2	0.3																			1	
5	1	L5	FIC 2	9.8																			1	1
6	1	L6	FIC 2	9.8																			1	1
7	1	L7	FIC 2	5.0																			1	1
8	1	FIC 2	FMH52	9.5											3								1	
9	1	L9	FIC 3	4.8																			1	1
10	1	L11	FIC 3	9.6																			1	1
11	1	L12	FIC 3	11.5																			1	2
12	1	FIC 3	FIC 4	0.4																			1	1
13	1	L14	FIC 4	10.0																			1	3
14	1	L15	FIC 4	9.8																			1	1
15	1	L16	FIC 4	5.6																			1	1
16	1	FIC 4	MAIN	12.3																			1	1
17	1	L18	FIC 5	11.0																			1	
18	1	FIC 6	FIC 5	0.1																			1	1
19	1	L20	FIC 5	9.9																			1	2
20	1	L21	FIC 5	6.0																			1	1
21	1	L22	FIC 6	5.6	1								1										1	1
22	1	L23	FIC 6	9.8																			1	1

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Sect. No.	Insp. No.	Upstream Node	Downstream Node	Insp. Length (m)	No. Grade 4/5 Obs.	Survey Abandoned	Camera Under Water	Cracks	Fractures	Broken	Deformed	Collapsed	Holes	Surface Damage	Displaced Joints	Open Joints	Roots	Infiltration	Encrustation	Silt	Grease	Obstruction	Water Level	Line Deviates
23	1	L24	FIC 6	11.2																			1	
24	1	FIC 5	MAIN	5.0												1							1	1
25	1	L26	FIC 7	10.8																			1	1
26	1	L27	FIC 7	10.1																			1	2
27	1	L28	FIC 7	5.2																			1	1
28	1	FIC 8	FIC 7	0.5																			1	1
29	1	FIC 7	MAIN	5.8											2								1	1
30	1	L31	FIC 8	10.5																			1	1
31	1	L32	FIC 8	9.5																			1	2
32	1	L33	FIC 8	5.4																			3	1
33	1	FIC 9	MAIN	9.5																			1	1
34	1	PPCP 1	SMH32	13.1																			1	
35	1	FIC10	FMH77	8.3																			1	
36	1	FIC 11	FMH77	9.6																			1	
37	1	FMH77	FMH56	24.0																			1	
38	1	FIC 12	MAIN	11.7											1								1	
39	1	PPCP 2	SMH49	16.3											1								1	1
40	1	PPCP 4	SMH49	15.6											1								1	
41	1	L43	SMH49	0.2																			1	
42	1	SMH49	SMH32	12.4																			1	
43	**1**	**FMH51**	**FMH56**	**30.5**		**1**																	**1**	
44	1	FIC 13	MAIN	7.0																			1	1
45	1	FIC 14	FMH78	9.7	1			3	1														1	
46	1	PPCP 3	SMH19	7.5											1								1	
47	**1**	**SMH32**	**SMH19**	**19.1**		**1**																	**1**	
48	**1**	**FMH78**	**FMH81**	**45.1**		**1**																	**1**	
49	1	FMH52	FMH59	40.2																			5	
50	1	FIC16	MAIN	5.0																			1	2
51	1	SMH75	SMH42	19.5			1																3	

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Project Summary

Project Name	Project Number	Project Date
DAISY FIELDS.LITTLEHAMPTON.BN17 6LT	02	30/06/2025

Sect. No.	Insp. No.	Upstream Node	Downstream Node	Insp. Length (m)	No. Grade 4/5 Obs.	Survey Abandoned	Camera Under Water	Cracks	Fractures	Broken	Deformed	Collapsed	Holes	Surface Damage	Displaced Joints	Open Joints	Roots	Infiltration	Encrustation	Silt	Grease	Obstruction	Water Level	Line Deviates
52	1	FIC15	FMH58	13.4																			1	1
53	1	FMH58	FMH59	25.4																			2	
54	1	SMH62	SMH35	32.7																			1	
55	1	SMH35	SMH7	9.3																			1	
56	1	SMH7	SMH44	7.0																1			1	
57	1	SMH44	SMH6	67.2																			1	
58	**1**	**SMH6**	**SMH5**	**18.0**		**1**																	**1**	
59	1	FMH57	FMH54	13.6																			1	
60	1	FMH54	FMH68	9.8																			1	
61	**1**	**FMH68**	**FMH70**	**46.8**		**1**			**1**											**1**			**1**	
			Total:	**787.5**	**2**	**5**	**1**	**3**	**2**				**1**		**9**	**1**				**2**			**70**	**40**

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L1X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
1	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L1
Road:	Daisy Fields	**Inspected Length:**	5.06 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	5.06 m	**Downstream Node:**	FIC 1
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC1	00:00:00	L1X_1bbf4d6f-35cd-4337-a4a3-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:10		
4.71	LU	Line deviates up	00:00:26	L1X_740c3009-d51e-4fdd-b4f7-	
5.06	OCF	Finish node, other special chamber, reference: L1: REST BEND	00:00:28	L1X_b208af46-6f25-4ce0-b5a9	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
1	Upstream	L1X		



L1X_1bbf4d6f-35cd-4337-a4a3-12c395bffea7_20250701_165636_248.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC1



L1X_740c3009-d51e-4fdd-b4f7-50ca08ae2276_20250701_165638_085.jpg, 00:00:26, 4.71 m
Line deviates up



L1X_b208af46-6f25-4ce0-b5a9-73d6107d076e_20250701_165639_272.jpg, 00:00:28, 5.06 m
Finish node, other special chamber, reference: L1

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L2X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
2	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L2
Road:	Daisy Fields	**Inspected Length:**	9.91 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.91 m	**Downstream Node:**	FIC 1
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:86



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC1	00:00:00	L2X_2511c4da-2cc1-462c-a3a	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
8.68	JN	Junction at 9 o'clock, 100mm dia	00:00:22	L2X_fc0790c1-3560-447c-a154	
8.94	LU	Line deviates up	00:00:23	L2X_58c295d6-6d6b-47d4-baf9	
9.91	OCF	Finish node, other special chamber, reference: L2: REST BEND	00:00:28	L2X_8929a665-5a73-4a0c-a77	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L2X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
2	Upstream	L2X		




L2X_2511c4da-2cc1-462c-a3ae-c4b7dc92e414_20250701_165650_134.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC1



L2X_fc0790c1-3560-447c-a154-331fc145833d_20250701_165651_981.jpg, 00:00:22, 8.68 m
Junction at 9 o'clock, 100mm dia



L2X_58c295d6-6d6b-47d4-baf9-7f201caeab20_20250701_165653_361.jpg, 00:00:23, 8.94 m
Line deviates up



L2X_8929a665-5a73-4a0c-a776-ac0ec8cfeb3f_20250701_165654_537.jpg, 00:00:28, 9.91 m
Finish node, other special chamber, reference: L2

Section Inspection - 30/06/2025 - L3X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
3	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L3X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L3
Road:	Daisy Fields	**Inspected Length:**	10.11 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	10.11 m	**Downstream Node:**	FIC 1
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:88



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC1	00:00:00	L3X_e10ebae3-6c2e-48ef-8aab	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.89	JN	Junction at 2 o'clock, 100mm dia	00:00:13	L3X_0b9d4282-8b8e-4210-9ec	
9.23	JN	Junction at 9 o'clock, 100mm dia	00:00:21	L3X_59a283f4-b9ee-48e1-a44a	
9.35	LU	Line deviates up	00:00:22	L3X_a26419ca-6fb5-48c6-ab7a	
10.11	OCF	Finish node, other special chamber, reference: L3: REST BEND	00:00:24	L3X_386db8a1-6dee-4ac0-8c4	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L3X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
3	Upstream	L3X		




L3X_e10ebae3-6c2e-48ef-8aab-ca1c8fe4c35e_20250701_165659_651.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC1



L3X_0b9d4282-8b8e-4210-9ecb-88f7975ffd78_20250701_165701_356.jpg, 00:00:13, 4.89 m
Junction at 2 o'clock, 100mm dia



L3X_59a283f4-b9ee-48e1-a44a-7199d18bc453_20250701_165702_914.jpg, 00:00:21, 9.23 m
Junction at 9 o'clock, 100mm dia



L3X_a26419ca-6fb5-48c6-ab7a-cec7713e4c82_20250701_165704_269.jpg, 00:00:22, 9.35 m
Line deviates up

Section Pictures - 30/06/2025 - L3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
3	Upstream	L3X		



L3X_386db8a1-6dee-4ac0-8c43-8e3704fcde60_20250701_165705_683.jpg, 00:00:24, 10.11 m
Finish node, other special chamber, reference: L3

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 1X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
4	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 1
Road:	Daisy Fields	**Inspected Length:**	0.30 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	0.30 m	**Downstream Node:**	FIC 2
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC1: L4	00:00:00	MH 1X_7628e 776-9933-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.30	MHF	Finish node, manhole, reference: FIC2	00:00:07	MH 1X_514b3 128-7805-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
4	Downstream	FIC 1X		



MH
1X_7628e776-9933-4dfa-9d46-dc22df8876ef_20250701_165714_434.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC1



MH
1X_514b3128-7805-4a17-9427-a0a140d41911_20250701_165715_665.jpg, 00:00:07, 0.30 m
Finish node, manhole, reference: FIC2

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L5X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
5	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L5X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L5
Road:	Daisy Fields	**Inspected Length:**	9.79 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.79 m	**Downstream Node:**	FIC 2
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:85



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC2	00:00:00	L5X_3042f87b-d10b-437e-858d	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.70	JN	Junction at 12 o'clock, 100mm dia	00:00:15	L5X_938a87fe-7f62-4631-9572	
8.99	JN	Junction at 3 o'clock, 100mm dia	00:00:25	L5X_b62dc7c2-9d0a-43de-966	
9.15	LU	Line deviates up	00:00:26	L5X_6477f5c9-64de-4ead-b229	
9.79	OCF	Finish node, other special chamber, reference: L5: REST BEND	00:00:29	L5X_1a0213cc-e291-4f6f-a7c6-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L5X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
5	Upstream	L5X		



L5X_3042f87b-d10b-437e-858d-c84ca3e770ea_20250701_165720_869.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC2



L5X_938a87fe-7f62-4631-9572-b758cfe81fa2_20250701_165722_310.jpg, 00:00:15, 4.70 m
Junction at 12 o'clock, 100mm dia




L5X_b62dc7c2-9d0a-43de-9660-f1f9cf2db616_20250701_165723_631.jpg, 00:00:25, 8.99 m
Junction at 3 o'clock, 100mm dia



L5X_6477f5c9-64de-4ead-b229-b5a59f14c18e_20250701_165725_068.jpg, 00:00:26, 9.15 m
Line deviates up

Section Pictures - 30/06/2025 - L5X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
5	Upstream	L5X		



L5X_1a0213cc-e291-4f6f-a7c6-8620313a7280_20250701_165726_898.jpg, 00:00:29, 9.79 m
Finish node, other special chamber, reference: L5

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L6X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
6	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L6X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L6
Road:	Daisy Fields	**Inspected Length:**	9.81 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.81 m	**Downstream Node:**	FIC 2
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:85



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC2	00:00:00	L6X_6238a700-1bc4-4c2d-b66	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
8.33	JN	Junction at 9 o'clock, 100mm dia	00:00:27	L6X_a0c9a144-a188-4931-952	
8.68	LU	Line deviates up	00:00:28	L6X_325c04bb-f860-406e-8a77	3
9.81	OCF	Finish node, other special chamber, reference: L6: REST BEND	00:00:31	L6X_1b0e4397-66b3-4497-b71	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	1	2.0	0.2	2.0	3.0

Section Pictures - 30/06/2025 - L6X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
6	Upstream	L6X		



L6X_6238a700-1bc4-4c2d-b669-967fa98a2edd_20250701_165738_005.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC2



L6X_a0c9a144-a188-4931-952a-9200940455f8_20250701_165739_223.jpg, 00:00:27, 8.33 m
Junction at 9 o'clock, 100mm dia



L6X_325c04bb-f860-406e-8a77-e51080b36ace_20250701_165740_681.jpg, 00:00:28, 8.68 m
Line deviates up

Section Pictures - 30/06/2025 - L6X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
6	Upstream	L6X		



L6X_1b0e4397-66b3-4497-b719-b42cb18eaae0_20250701_165741_810.jpg, 00:00:31, 9.81 m
Finish node, other special chamber, reference: L6

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L7X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
7	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L7X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L7
Road:	Daisy Fields	**Inspected Length:**	4.98 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	4.98 m	**Downstream Node:**	FIC 2
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC2	00:00:00	L7X_7c378d31-52e2-4373-ba4	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.41	LU	Line deviates up	00:00:22	L7X_d8a5b776-61d9-4dee-b04	
4.98	OCF	Finish node, other special chamber, reference: L7: REST BEND	00:00:24	L7X_e935c35a-27c0-40c5-891	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L7X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
7	Upstream	L7X		



L7X_7c378d31-52e2-4373-ba48-3c02269acc9c_20250701_165808_083.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC2



L7X_d8a5b776-61d9-4dee-b049-ee94d4a66250_20250701_165808_887.jpg, 00:00:22, 4.41 m
Line deviates up



L7X_e935c35a-27c0-40c5-8911-1b3ede397993_20250701_165809_912.jpg, 00:00:24, 4.98 m
Finish node, other special chamber, reference: L7

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 2X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
8	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 2
Road:	Daisy Fields	**Inspected Length:**	9.52 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	9.52 m	**Downstream Node:**	FMH52
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:83



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC2: L8	00:00:00	MH 2X_31ae9 5cd-d3cd-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.02	MCVC	Pipe material changes to vitrified clay at this point	00:00:05	MH 2X_94e56 988-60b4-	
8.69	SC	Pipe size changes, new size(s), 150mm high	00:00:37	MH 2X_99ede 1bb-544a-	
9.52	MHF	Finish node, manhole, reference: FMH52	00:00:41	MH 2X_c00d6 2d1-8d8b-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
3	1.0	0.3	3.0	1.0	3	2.0	0.6	6.0	3.0

Section Pictures - 30/06/2025 - FIC 2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
8	Downstream	FIC 2X		



MH
2X_31ae95cd-d3cd-48e3-83cc-650b95633992_20250701_165818_110.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC2



MH
2X_94e56988-60b4-400c-8ddf-b2c25e92e3cf_20250701_165820_496.jpg, 00:00:05, 0.02 m
Pipe material changes to vitrified clay at this point

Section Pictures - 30/06/2025 - FIC 2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
8	Downstream	FIC 2X		



MH
2X_99ede1bb-544a-4a8d-a940-239d07540689_20250701_165825_903.jpg, 00:00:37, 8.69 m
Pipe size changes, new size(s), 150mm high



MH
2X_c00d62d1-8d8b-4452-b6e0-ec6d661688c0_20250701_165827_768.jpg, 00:00:41, 9.52 m
Finish node, manhole, reference: FMH52

Section Inspection - 30/06/2025 - L9X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
9	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L9X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L9
Road:	Daisy Fields	**Inspected Length:**	4.81 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	4.81 m	**Downstream Node:**	FIC 3
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:




Scale: 1:50 Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC3	00:00:00	L9X_695abca1-7d3a-43c9-b61	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
4.26	LU	Line deviates up	00:00:17	L9X_6a8c22e5-1168-48a0-a32	
4.81	OCF	Finish node, other special chamber, reference: L9: REST BEND	00:00:19	L9X_2ba4e900-a9a3-4dfc-9655	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L9X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
9	Upstream	L9X		



L9X_695abca1-7d3a-43c9-b614-72c7028508a9_20250630_185645_455.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC3



L9X_6a8c22e5-1168-48a0-a32d-5cf0c5b7625a_20250701_165858_809.jpg, 00:00:17, 4.26 m
Line deviates up



L9X_2ba4e900-a9a3-4dfc-9655-e23d937e7362_20250701_165859_796.jpg, 00:00:19, 4.81 m
Finish node, other special chamber, reference: L9

Section Inspection - 30/06/2025 - L11X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
10	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L11X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L11
Road:	Daisy Fields	**Inspected Length:**	9.60 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.60 m	**Downstream Node:**	FIC 3
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:84



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC3	00:00:00	L11X_767c4a3c-b460-4a8c-b2	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
8.00	JN	Junction at 3 o'clock, 100mm dia	00:00:28	L11X_c108a6c0-ce4f-4e71-85a	
9.05	LU	Line deviates up	00:00:31	L11X_44e2cbe1-6bee-49bd-ba	
9.60	OCF	Finish node, other special chamber, reference: L11: REST BEND	00:00:33	L11X_c727b411-ec56-4be1-96f	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L11X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
10	Upstream	L11X		



L11X_767c4a3c-b460-4a8c-b241-36e42d1a8127_20250701_165907_542.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC3



L11X_c108a6c0-ce4f-4e71-85a6-9047abcc196d_20250701_165908_983.jpg, 00:00:28, 8.00 m
Junction at 3 o'clock, 100mm dia



L11X_44e2cbe1-6bee-49bd-ba8b-bcaf18e67cbf_20250701_165910_196.jpg, 00:00:31, 9.05 m
Line deviates up



L11X_c727b411-ec56-4be1-96f4-f16a5e294fdc_20250701_165911_564.jpg, 00:00:33, 9.60 m
Finish node, other special chamber, reference: L11

Section Inspection - 30/06/2025 - L12X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
11	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L12X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L12
Road:	Daisy Fields	**Inspected Length:**	11.52 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	11.52 m	**Downstream Node:**	FIC 3
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:100



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC3	00:00:00	L12X_1c67c6ce-1072-4179-80	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.09	LL	Line deviates left	00:00:05	L12X_4c26aa87-9a13-49d6-95	
4.13	JN	Junction at 3 o'clock, 100mm dia	00:00:19	L12X_65cd4124-d1aa-497c-a4	
8.87	JN	Junction at 3 o'clock, 100mm dia	00:00:34	L12X_5ce7d6ae-ff7a-4a0d-b4d	
10.78	LU	Line deviates up	00:00:41	L12X_8838090a-ad35-4fa0-95e	
11.52	OCF	Finish node, other special chamber, reference: L12: REST BEND	00:00:44	L12X_7dc55b14-2bbc-4c06-b3	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L12X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
11	Upstream	L12X		



L12X_1c67c6ce-1072-4179-80aa-ebc15051e000_20250701_165917_485.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC3



L12X_4c26aa87-9a13-49d6-9596-9bd435029d2a_20250701_165919_090.jpg, 00:00:05, 0.09 m
Line deviates left



L12X_65cd4124-d1aa-497c-a461-6fb0f24bd3ce_20250701_165920_091.jpg, 00:00:19, 4.13 m
Junction at 3 o'clock, 100mm dia



L12X_5ce7d6ae-ff7a-4a0d-b4d9-cc27464934ca_20250701_165921_952.jpg, 00:00:34, 8.87 m
Junction at 3 o'clock, 100mm dia

Section Pictures - 30/06/2025 - L12X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
11	Upstream	L12X		



L12X_8838090a-ad35-4fa0-95ed-027d46885759_20250701_165924_960.jpg, 00:00:41, 10.78 m
Line deviates up



L12X_7dc55b14-2bbc-4c06-b374-91cd2a4c6b00_20250701_165923_774.jpg, 00:00:44, 11.52 m
Finish node, other special chamber, reference: L12

Section Inspection - 30/06/2025 - FIC 3X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
12	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 3X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 3
Road:	Daisy Fields	**Inspected Length:**	0.41 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	0.41 m	**Downstream Node:**	FIC 4
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC3: L13	00:00:00	MH 4X_c86ac707-b44e-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.09	LL	Line deviates left	00:00:04	MH 4X_975fb1c5-2f44-41	
0.41	MHF	Finish node, manhole, reference: FIC4	00:00:07	MH 4X_41e1036d-36e2-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
12	Downstream	FIC 3X		



MH
4X_c86ac707-b44e-41be-9b42-eb888e8895f0_20250701_165930_458.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC3



MH
4X_975fb1c5-2f44-413c-a3e1-faeccf9ba1cf_20250701_165931_628.jpg, 00:00:04, 0.09 m
Line deviates left



MH
4X_41e1036d-36e2-4be6-8a46-be6c787ce542_20250701_165932_631.jpg, 00:00:07, 0.41 m
Finish node, manhole, reference: FIC4

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L14X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
13	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L14X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L14
Road:	Daisy Fields	**Inspected Length:**	10.03 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	10.03 m	**Downstream Node:**	FIC 4
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:87



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC4	00:00:00	L14X_fb7530e0-a870-40a3-95b	
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.04	LR	Line deviates right	00:00:02	L14X_350b519f-60d0-4551-aa	
0.59	LL	Line deviates left	00:00:06	L14X_1b6d1808-0998-4c7c-8f5	
5.00	JN	Junction at 12 o'clock, 100mm dia	00:00:18	L14X_93f9c29a-33c3-4cfe-9e9d	
8.90	JN	Junction at 3 o'clock, 100mm dia	00:00:28	L14X_48e92ebe-8d23-4adb-b3	
9.45	LU	Line deviates up	00:00:29	L14X_eec33aec-2041-472c-84	
10.03	OCF	Finish node, other special chamber, reference: L14: REST BEND	00:00:31	L14X_41cd12fc-dfbb-47c9-af25	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L14X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
13	Upstream	L14X		




L14X_fb7530e0-a870-40a3-95b4-17f8bd0d4cab_20250701_165940_803.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC4



L14X_350b519f-60d0-4551-aa9e-b8f7cb8791cb_20250701_165941_811.jpg, 00:00:02, 0.04 m
Line deviates right




L14X_1b6d1808-0998-4c7c-8f52-ef9d7cade173_20250701_165943_387.jpg, 00:00:06, 0.59 m
Line deviates left




L14X_93f9c29a-33c3-4cfe-9e9d-351cc3703759_20250701_165944_696.jpg, 00:00:18, 5.00 m
Junction at 12 o'clock, 100mm dia

Section Pictures - 30/06/2025 - L14X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
13	Upstream	L14X		



L14X_48e92ebe-8d23-4adb-b3a8-6b40c62f347c_20250701_165946_565.jpg, 00:00:28, 8.90 m
Junction at 3 o'clock, 100mm dia



L14X_eec33aec-2041-472c-8420-53125881882e_20250701_165948_859.jpg, 00:00:29, 9.45 m
Line deviates up



L14X_41cd12fc-dfbb-47c9-af25-f1598ffb512b_20250701_165947_739.jpg, 00:00:31, 10.03 m
Finish node, other special chamber, reference: L14

Section Inspection - 30/06/2025 - L15X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
14	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L15X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L15
Road:	Daisy Fields	**Inspected Length:**	9.76 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.76 m	**Downstream Node:**	FIC 4
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:85



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC4	00:00:00	L15X_ee47413a-f90d-4052-90	
0.00	WL	Water level, 5% of the vertical dimension	00:00:03		
8.70	JN	Junction at 3 o'clock, 100mm dia	00:00:31	L15X_9dd469a6-cff0-446a-8d6	
9.19	LU	Line deviates up	00:00:33	L15X_314e08ad-9e8b-4d72-8cf	
9.76	OCF	Finish node, other special chamber, reference: L15: REST BEND	00:00:36	L15X_e8db75b0-d803-4588-9c	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L15X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
14	Upstream	L15X		



L15X_ee47413a-f90d-4052-9078-b98d4a60baaa_20250701_170004_497.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC4



L15X_9dd469a6-cff0-446a-8d6c-26f385a1409c_20250701_170006_358.jpg, 00:00:31, 8.70 m
Junction at 3 o'clock, 100mm dia



L15X_314e08ad-9e8b-4d72-8cff-b7717ed69cd0_20250701_170007_949.jpg, 00:00:33, 9.19 m
Line deviates up



L15X_e8db75b0-d803-4588-9c0a-4334eb6471ef_20250701_170009_182.jpg, 00:00:36, 9.76 m
Finish node, other special chamber, reference: L15

Section Inspection - 30/06/2025 - L16X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
15	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L16X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L16
Road:	Daisy Fields	**Inspected Length:**	5.56 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	5.56 m	**Downstream Node:**	FIC 4
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC4	00:00:00	L16X_e0ec2ed7-08f6-4814-95f	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.84	LU	Line deviates up	00:00:19	L16X_2b70c7af-9f89-49f3-9f3e-	
5.56	OCF	Finish node, other special chamber, reference: L16: REST BEND	00:00:21	L16X_87b980d2-b822-4e8f-87b	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L16X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
15	Upstream	L16X		



L16X_e0ec2ed7-08f6-4814-95f9-d2ea35796184_20250701_170016_857.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC4



L16X_2b70c7af-9f89-49f3-9f3e-118ce13f01d9_20250701_170017_910.jpg, 00:00:19, 4.84 m
Line deviates up



L16X_87b980d2-b822-4e8f-87b1-725ee3debbde_20250701_170019_361.jpg, 00:00:21, 5.56 m
Finish node, other special chamber, reference: L16

Section Inspection - 30/06/2025 - FIC 4X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
16	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 4X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 4
Road:	Daisy Fields	**Inspected Length:**	12.29 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	12.29 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:107




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC4	00:00:00	MH 5X_9c7c546a-2809-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.24	MCVC	Pipe material changes to vitrified clay at this point	00:00:05	MH 5X_79554204-539b-	
9.15	LD	Line deviates down	00:00:30	MH 5X_84b027ab-51f7-4	
12.29	BRF	Finish node, major connection without manhole, reference: L17: MAINLINE	00:00:39	MH 5X_152f6aef-c0a4-48	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 4X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
16	Downstream	FIC 4X		



MH
5X_9c7c546a-2809-48f7-af21-f5dc52fd9237_20250701_170032_703.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC4



MH
5X_79554204-539b-43bf-9e42-5e1eb01cfb4e_20250701_170034_661.jpg, 00:00:05, 0.24 m
Pipe material changes to vitrified clay at this point



MH
5X_84b027ab-51f7-4928-a7e0-1d0c026f51b7_20250701_170035_892.jpg, 00:00:30, 9.15 m
Line deviates down



MH
5X_152f6aef-c0a4-48cc-a997-b37a8dd35f18_20250701_170037_506.jpg, 00:00:39, 12.29 m
Finish node, major connection without manhole, reference: L17

Section Inspection - 30/06/2025 - L18X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
17	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L18X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L18
Road:	Daisy Fields	**Inspected Length:**	11.03 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	11.03 m	**Downstream Node:**	FIC 5
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.560 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations: HPWJ LINE

Scale: 1:96



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC5	00:00:00	L18X_71753cfd-526d-4b79-98	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
4.99	JN	Junction at 12 o'clock, 100mm dia	00:00:20	L18X_b559e82b-323a-4201-8e	
9.43	JN	Junction at 9 o'clock, 100mm dia	00:00:31	L18X_95c00c07-51e8-4ff7-afce	
9.90	JN	Junction at 12 o'clock, 100mm dia	00:00:32	L18X_e2a569b3-baf8-4abe-aa	
11.03	OCF	Finish node, other special chamber, reference: L18: CAPPED	00:00:34	L18X_00cba49f-781c-496e-8c	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	1	5.0	0.5	5.0	4.0

Section Pictures - 30/06/2025 - L18X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
17	Upstream	L18X		



L18X_71753cfd-526d-4b79-986c-b3174321c1a7_20250701_170111_730.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC5



L18X_b559e82b-323a-4201-8ed5-b0c320c86847_20250701_170049_660.jpg, 00:00:20, 4.99 m
Junction at 12 o'clock, 100mm dia




L18X_95c00c07-51e8-4ff7-afce-76ff066155ea_20250701_170048_363.jpg, 00:00:31, 9.43 m
Junction at 9 o'clock, 100mm dia

Section Pictures - 30/06/2025 - L18X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
17	Upstream	L18X		



L18X_e2a569b3-baf8-4abe-aab2-cdb83d3a3d36_20250701_170102_115.jpg, 00:00:32, 9.90 m
Junction at 12 o'clock, 100mm dia



L18X_00cba49f-781c-496e-8c25-a2e2cef55c98_20250701_170103_769.jpg, 00:00:34, 11.03 m
Finish node, other special chamber, reference: L18

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 6X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
18	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 6X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	FIC 6
Road:	Daisy Fields	**Inspected Length:**	0.12 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	0.12 m	**Downstream Node:**	FIC 5
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.560 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo
0.00	MH	Start node, manhole, reference: FIC5: L19	00:00:00	MH 7X_a0dc5e27-d718-
0.00	WL	Water level, 5% of the vertical dimension	00:00:00	
0.04	LL	Line deviates left	00:00:00	MH 7X_a79175aa-e2fa-4
0.12	MHF	Finish node, manhole, reference: FIC6	00:00:07	MH 7X_5941bba7-bcc6-


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 6X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
18	Upstream	FIC 6X		



MH
7X_a0dc5e27-d718-41c2-a8d8-48a490e3f360_20250701_170129_242.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC5



MH
7X_a79175aa-e2fa-4ecb-8d22-c68fd7e514fb_20250701_170130_436.jpg, 00:00:00, 0.04 m
Line deviates left



MH
7X_5941bba7-bcc6-4bff-b777-35939dffe072_20250701_170131_841.jpg, 00:00:07, 0.12 m
Finish node, manhole, reference: FIC6

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L20X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
19	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L20X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L20
Road:	Daisy Fields	**Inspected Length:**	9.91 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.91 m	**Downstream Node:**	FIC 5
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.560 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:86



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC5	00:00:00	L20X_af50a0fc-6632-498a-8f06-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.37	LL	Line deviates left	00:00:06	L20X_e231ad4f-6329-4834-bb	
9.37	LU	Line deviates up	00:00:26	L20X_ffd22232-8f7c-43a1-9452	
9.91	OCF	Finish node, other special chamber, reference: L20: REST BEND	00:00:27	L20X_dbfad9c3-6daf-459a-aef1-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L20X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
19	Upstream	L20X		




L20X_af50a0fc-6632-498a-8f06-06ae9ff0437e_20250701_170137_175.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC5



L20X_e231ad4f-6329-4834-bbd9-60ce2bfd9fef_20250701_170138_447.jpg, 00:00:06, 0.37 m
Line deviates left



L20X_ffd22232-8f7c-43a1-9452-a7ba47932ba9_20250701_170139_418.jpg, 00:00:26, 9.37 m
Line deviates up



L20X_dbfad9c3-6daf-459a-aef1-d013eb22457f_20250701_170140_997.jpg, 00:00:27, 9.91 m
Finish node, other special chamber, reference: L20

Section Inspection - 30/06/2025 - L21X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
20	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L21X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L21
Road:	Daisy Fields	**Inspected Length:**	5.95 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	5.95 m	**Downstream Node:**	FIC 5
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.560 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:52



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC5	00:00:00	L21X_3362d6ac-9d56-4fcb-a30	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
5.05	LU	Line deviates up	00:00:16	L21X_d82494c6-9ef7-44d0-86	
5.95	OCF	Finish node, other special chamber, reference: L21: REST BEND	00:00:20	L21X_431a4ee1-98b5-428f-993	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L21X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
20	Upstream	L21X		



L21X_3362d6ac-9d56-4fcb-a30b-61576191f540_20250701_170148_977.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC5



L21X_d82494c6-9ef7-44d0-861c-520d7362bb84_20250701_170150_265.jpg, 00:00:16, 5.05 m
Line deviates up



L21X_431a4ee1-98b5-428f-9936-c19276812a75_20250701_170151_350.jpg, 00:00:20, 5.95 m
Finish node, other special chamber, reference: L21

Section Inspection - 30/06/2025 - L22X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
21	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L22X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L22
Road:	Daisy Fields	**Inspected Length:**	5.63 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	5.63 m	**Downstream Node:**	FIC 6
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC6	00:00:00	L22X_9ecf6878-c28d-4e9e-8cc	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.96	LU	Line deviates up	00:00:16	L22X_45675bc0-01f7-4c64-a8	
5.63	OCF	Finish node, other special chamber, reference: L22: REST BEND	00:00:18	L22X_16b71ae8-46cd-4aed-96	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
1	80.0	14.2	80.0	4.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L22X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
21	Upstream	L22X		



L22X_9ecf6878-c28d-4e9e-8cc0-813c802ae888_20250701_170201_605.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC6



L22X_45675bc0-01f7-4c64-a830-67f27a4f2d40_20250701_170204_018.jpg, 00:00:16, 4.96 m
Line deviates up



L22X_16b71ae8-46cd-4aed-9628-477cfc08740b_20250701_170205_167.jpg, 00:00:18, 5.63 m
Finish node, other special chamber, reference: L22

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L23X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
22	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L23X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L23
Road:	Daisy Fields	**Inspected Length:**	9.77 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.77 m	**Downstream Node:**	FIC 6
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:85



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC6	00:00:00	L23X_05483963-bd6a-42a9-9a	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
9.03	LU	Line deviates up	00:00:29	L23X_c1caa1c2-c20d-4253-8b	
9.77	OCF	Finish node, other special chamber, reference: L23: REST BEND	00:00:31	L23X_78767e09-2e67-400c-b3	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L23X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
22	Upstream	L23X		



L23X_05483963-bd6a-42a9-9a2b-20fb4b71cc9b_20250701_170221_825.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC6



L23X_c1caa1c2-c20d-4253-8b0c-4cec330014f6_20250701_170223_349.jpg, 00:00:29, 9.03 m
Line deviates up



L23X_78767e09-2e67-400c-b39e-9a8d570b83f3_20250701_170224_543.jpg, 00:00:31, 9.77 m
Finish node, other special chamber, reference: L23

Section Inspection - 30/06/2025 - L24X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
23	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L24X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L24
Road:	Daisy Fields	**Inspected Length:**	11.24 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	11.24 m	**Downstream Node:**	FIC 6
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:98



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC6	00:00:00	L24X_b3aecc8a-89fc-441c-932	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
5.23	JN	Junction at 12 o'clock, 100mm dia	00:00:17	L24X_632ce246-3902-421b-b3	
9.77	JN	Junction at 3 o'clock, 100mm dia	00:00:27	L24X_edb9189f-978a-4e52-a4	
10.01	JN	Junction at 12 o'clock, 100mm dia	00:00:27	L24X_95e10676-0d75-4700-ac	
11.24	OCF	Finish node, other special chamber, reference: L24: CAPPED	00:00:30	L24X_8cbdbb2f-8c2b-4f05-91e	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L24X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
23	Upstream	L24X		




L24X_b3aecc8a-89fc-441c-9322-54aeb5668802_20250701_170239_547.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC6



L24X_632ce246-3902-421b-b351-0284182b7ed8_20250701_170240_640.jpg, 00:00:17, 5.23 m
Junction at 12 o'clock, 100mm dia



L24X_edb9189f-978a-4e52-a46c-f695935820cc_20250701_170241_508.jpg, 00:00:27, 9.77 m
Junction at 3 o'clock, 100mm dia



L24X_95e10676-0d75-4700-ac2f-92c8a77e2404_20250701_170242_738.jpg, 00:00:27, 10.01 m
Junction at 12 o'clock, 100mm dia

Section Pictures - 30/06/2025 - L24X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
23	Upstream	L24X		



L24X_8cbdbb2f-8c2b-4f05-91ee-feded1350506_20250701_170244_398.jpg, 00:00:30, 11.24 m
Finish node, other special chamber, reference: L24

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 5X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
24	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 5X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 5
Road:	Daisy Fields	**Inspected Length:**	5.02 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	5.02 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 0.58 m FIC 5						
	0.00	MH	Start node, manhole, reference: FIC5	00:00:00	MH 6X_c6c58 a00-b959-	
	0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
	0.22	MCVC	Pipe material changes to vitrified clay at this point	00:00:08	MH 6X_28a93 d44-dc4d-	
	4.59	LD	Line deviates down	00:00:24	MH 6X_dd748 9f3-b8fd-4	
	5.02	BRF	Finish node, major connection without manhole, reference: L25: MAINLINE	00:00:26	MH 6X_4c66a 576-178d-	
MAIN Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	1.0	0.2	1.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 5X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
24	Downstream	FIC 5X		



MH
6X_c6c58a00-b959-4740-9062-1bb79d81512e_20250701_150620_114.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC5



MH
6X_28a93d44-dc4d-4996-aa35-585673cb0242_20250701_170253_926.jpg, 00:00:08, 0.22 m
Pipe material changes to vitrified clay at this point



MH
6X_dd7489f3-b8fd-4936-8070-ffeff079b4e4_20250701_170256_010.jpg, 00:00:24, 4.59 m
Line deviates down

Section Pictures - 30/06/2025 - FIC 5X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
24	Downstream	FIC 5X		



MH
6X_4c66a576-178d-44dd-8418-f414a370aa04_20250701_170300_909.jpg, 00:00:26, 5.02 m
Finish node, major connection without manhole, reference: L25

Section Inspection - 30/06/2025 - L26X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
25	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L26X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L26
Road:	Daisy Fields	**Inspected Length:**	10.81 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	10.81 m	**Downstream Node:**	FIC 7
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations: HPWJ LINE

Scale: 1:94




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC7	00:00:00	L26X_9da0f554-513e-4e1a-88	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.22	LL	Line deviates left	00:00:04	L26X_fbcd8b09-5c2b-45e3-926	
4.80	DER	Settled deposits, coarse, 5% cross-sectional area loss	00:00:20	L26X_8c748d7e-6e80-41d5-8e	3
4.80	JN	Junction at 10 o'clock, 100mm dia	00:00:20	L26X_096d598d-7eed-41c7-8e	
9.33	JN	Junction at 9 o'clock, 100mm dia	00:00:33	L26X_2d7e3045-ccc4-4a4c-92	
9.93	JN	Junction at 12 o'clock, 100mm dia	00:00:34	L26X_bb0f8418-7960-422a-afab	
10.81	OCF	Finish node, other special chamber, reference: L26: CAPPED	00:00:38	L26X_d77d8a73-98da-43ca-9d	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	0.2	2.0	3.0

Section Pictures - 30/06/2025 - L26X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
25	Upstream	L26X		



L26X_9da0f554-513e-4e1a-88b3-15def15fd299_20250701_150823_731.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC7



L26X_fbcd8b09-5c2b-45e3-9260-c38fb52b49f9_20250701_170325_927.jpg, 00:00:04, 0.22 m
Line deviates left



L26X_8c748d7e-6e80-41d5-8e9e-3ca6b8908f4d_20250701_170329_128.jpg, 00:00:20, 4.80 m
Settled deposits, coarse, 5% cross-sectional area loss




L26X_096d598d-7eed-41c7-8e61-3228eecbd8a7_20250701_170330_674.jpg, 00:00:20, 4.80 m
Junction at 10 o'clock, 100mm dia

Section Pictures - 30/06/2025 - L26X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
25	Upstream	L26X		



L26X_2d7e3045-ccc4-4a4c-9202-c453bad45397_20250701_170332_782.jpg, 00:00:33, 9.33 m
Junction at 9 o'clock, 100mm dia



L26X_bb0f8418-7960-422a-afab-49b191e827b6_20250701_170333_911.jpg, 00:00:34, 9.93 m
Junction at 12 o'clock, 100mm dia



L26X_d77d8a73-98da-43ca-9dc7-078ef4fa5d41_20250701_170335_231.jpg, 00:00:38, 10.81 m
Finish node, other special chamber, reference: L26

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L27X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
26	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L27X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L27
Road:	Daisy Fields	**Inspected Length:**	10.11 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	10.11 m	**Downstream Node:**	FIC 7
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:88



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC7	00:00:00	L27X_6e79de81-231d-41d5-8f3	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.50	LL	Line deviates left	00:00:05	L27X_ddb0d084-8b81-450a-92	
8.92	LU	Line deviates up	00:00:34	L27X_1367f3f5-dd01-4eb3-9be	
10.11	OCF	Finish node, other special chamber, reference: L27: REST BEND	00:00:37	L27X_7f3cadb2-7fa9-4e3e-8ea4	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L27X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
26	Upstream	L27X		



L27X_6e79de81-231d-41d5-8f39-2fcb37537f0b_20250701_170656_245.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC7



L27X_ddb0d084-8b81-450a-921b-cdab44ff2023_20250701_170657_353.jpg, 00:00:05, 0.50 m
Line deviates left



L27X_1367f3f5-dd01-4eb3-9be0-1bb0528067d6_20250701_170658_752.jpg, 00:00:34, 8.92 m
Line deviates up



L27X_7f3cadb2-7fa9-4e3e-8ea4-17bed0734b7e_20250701_170700_201.jpg, 00:00:37, 10.11 m
Finish node, other special chamber, reference: L27

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L28X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
27	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L28X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L28
Road:	Daisy Fields	**Inspected Length:**	5.20 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	5.20 m	**Downstream Node:**	FIC 7
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC7	00:00:00	L28X_680eec6d-8221-4989-be	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
4.74	LU	Line deviates up	00:00:15	L28X_6ece63e4-544b-49c5-bb	
5.20	OCF	Finish node, other special chamber, reference: L28: REST BEND	00:00:17	L28X_1db90be5-4416-4f6f-b51	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	1	2.0	0.4	2.0	3.0

Section Pictures - 30/06/2025 - L28X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
27	Upstream	L28X		



L28X_680eec6d-8221-4989-be09-cd10bb23a6d0_20250701_151458_645.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC7



L28X_6ece63e4-544b-49c5-bb9f-0567f6524307_20250701_170706_596.jpg, 00:00:15, 4.74 m
Line deviates up



L28X_1db90be5-4416-4f6f-b51e-56d82223305d_20250701_170707_472.jpg, 00:00:17, 5.20 m
Finish node, other special chamber, reference: L28

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 8X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
28	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 8X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	FIC 8
Road:	Daisy Fields	**Inspected Length:**	0.53 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	0.53 m	**Downstream Node:**	FIC 7
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC7: L29	00:00:00	MH 9X_88411 c36-58cb-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.20	LL	Line deviates left	00:00:04	MH 9X_ff6d5c c7-60f5-4b	
0.53	MHF	Finish node, manhole, reference: MH 9	00:00:08	MH 9X_9f2d91 21-05dc-4	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 8X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
28	Upstream	FIC 8X		



MH
9X_88411c36-58cb-4942-81a3-9a13ce137e3b_20250701_151617_761.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC7



MH
9X_ff6d5cc7-60f5-4b17-87d1-b45710adc309_20250701_170722_563.jpg, 00:00:04, 0.20 m
Line deviates left



MH
9X_9f2d9121-05dc-4e93-8318-28fba525ce9e_20250701_170723_381.jpg, 00:00:08, 0.53 m
Finish node, manhole, reference: MH 9

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 7X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
29	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 7X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 7
Road:	Daisy Fields	**Inspected Length:**	5.79 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	5.79 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:51



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC7	00:00:00	MH 8X_2bb9b6d8-11a1-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.18	MCVC	Pipe material changes to vitrified clay at this point	00:00:04	MH 8X_6e208c22-d6a4-	
5.16	LD	Line deviates down	00:00:18	MH 8X_ea9f699c-a617-4	
5.79	BRF	Finish node, major connection without manhole, reference: L30	00:00:20	MH 8X_38f1ddd-0636-4	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
2	1.0	0.3	2.0	1.0	2	2.0	0.7	4.0	3.0

Section Pictures - 30/06/2025 - FIC 7X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
29	Downstream	FIC 7X		



MH
8X_2bb9b6d8-11a1-4e71-9cf7-ddcdb8cee365_20250701_151726_921.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC7



MH
8X_6e208c22-d6a4-4988-92a0-0fb0cd3422ce_20250701_170728_259.jpg, 00:00:04, 0.18 m
Pipe material changes to vitrified clay at this point

Section Pictures - 30/06/2025 - FIC 7X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
29	Downstream	FIC 7X		



MH
8X_ea9f699c-a617-46f3-b323-6ab1b76fb2e4_20250701_170732_567.jpg, 00:00:18, 5.16 m
Line deviates down



MH
8X_38f1dedd-0636-48cb-bb58-a64c45474d27_20250701_170733_833.jpg, 00:00:20, 5.79 m
Finish node, major connection without manhole, reference: L30

Section Inspection - 30/06/2025 - L31X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
30	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L31X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L31
Road:	Daisy Fields	**Inspected Length:**	10.53 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	10.53 m	**Downstream Node:**	FIC 8
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:92




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC8	00:00:00	L31X_7b19a8f0-dca6-4bb9-b6	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.32	LR	Line deviates right	00:00:06	L31X_3b2e0d3d-8fa8-4fc7-a71	
9.17	JN	Junction at 3 o'clock, 100mm dia	00:00:32	L31X_17a81b75-1a42-4daa-9a	
9.89	JN	Junction at 12 o'clock, 100mm dia	00:00:33	L31X_30447f9a-57af-44de-8ff9-	
10.53	OCF	Finish node, other special chamber, reference: L31: CAPPED	00:00:36	L31X_18350002-44d5-4eaf-80b	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L31X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
30	Upstream	L31X		




L31X_7b19a8f0-dca6-4bb9-b6b3-050d38c26002_20250701_170752_079.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC8



L31X_3b2e0d3d-8fa8-4fc7-a71a-8be422023423_20250701_170752_924.jpg, 00:00:06, 0.32 m
Line deviates right




L31X_17a81b75-1a42-4daa-9a7e-307be2c49266_20250701_170753_850.jpg, 00:00:32, 9.17 m
Junction at 3 o'clock, 100mm dia



L31X_30447f9a-57af-44de-8ff9-504360f01e09_20250701_170754_888.jpg, 00:00:33, 9.89 m
Junction at 12 o'clock, 100mm dia

Section Pictures - 30/06/2025 - L31X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
30	Upstream	L31X		



L31X_18350002-44d5-4eaf-80ba-452eaa3bf113_20250701_170756_338.jpg, 00:00:36, 10.53 m
Finish node, other special chamber, reference: L31

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - L32X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
31	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L32X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L32
Road:	Daisy Fields	**Inspected Length:**	9.49 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.49 m	**Downstream Node:**	FIC 8
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:83



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC8	00:00:00	L32X_ef774b42-8bb7-4e83-96a	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.26	LR	Line deviates right	00:00:08	L32X_a653e029-9f5b-4e61-be	
9.17	LU	Line deviates up	00:00:36	L32X_15bb80fe-d993-43e1-b9	
9.49	OCF	Finish node, other special chamber, reference: L32: REST BEND	00:00:38	L32X_5425e612-715c-43b0-a8	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L32X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
31	Upstream	L32X		




L32X_ef774b42-8bb7-4e83-96a9-bd27bfc016f7_20250701_170802_674.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC8



L32X_a653e029-9f5b-4e61-be3b-7592023faccd_20250701_170803_809.jpg, 00:00:08, 0.26 m
Line deviates right



L32X_15bb80fe-d993-43e1-b97b-02fa2b90178f_20250701_170804_974.jpg, 00:00:36, 9.17 m
Line deviates up



L32X_5425e612-715c-43b0-a841-f79979034c5f_20250701_170806_866.jpg, 00:00:38, 9.49 m
Finish node, other special chamber, reference: L32

Section Inspection - 30/06/2025 - L33X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
32	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L33X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L33
Road:	Daisy Fields	**Inspected Length:**	5.42 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	5.42 m	**Downstream Node:**	FIC 8
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC8	00:00:00	L33X_a02971be-6f89-4ced-91	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.47	WL	Water level, 5% of the vertical dimension	00:00:06	L33X_21a7342b-2438-4a3f-a4d	
1.31	WL	Water level, 5% of the vertical dimension	00:00:09	L33X_1e2cc001-e770-4413-b1	
5.14	LU	Line deviates up	00:00:19	L33X_45c437ca-615a-4fc3-b1d	
5.42	OCF	Finish node, other special chamber, reference: L33: REST BEND	00:00:20	L33X_133461c5-9c80-4335-90	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L33X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
32	Upstream	L33X		



L33X_a02971be-6f89-4ced-9161-63f0ef750068_20250701_152404_141.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC8



L33X_21a7342b-2438-4a3f-a4d1-a4bb3c42f243_20250701_170813_347.jpg, 00:00:06, 0.47 m
Water level, 5% of the vertical dimension



L33X_1e2cc001-e770-4413-b151-5020a8396adb_20250701_170814_568.jpg, 00:00:09, 1.31 m
Water level, 5% of the vertical dimension



L33X_45c437ca-615a-4fc3-b1de-97e3714f5d1f_20250701_170815_782.jpg, 00:00:19, 5.14 m
Line deviates up

Section Pictures - 30/06/2025 - L33X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
32	Upstream	L33X		



L33X_133461c5-9c80-4335-90c3-45fd7edccf2f_20250701_170816_900.jpg, 00:00:20, 5.42 m
Finish node, other special chamber, reference: L33

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 9X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
33	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 9X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 9
Road:	Daisy Fields	**Inspected Length:**	9.46 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	9.46 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:82



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC9	00:00:00	MH 10X_2cbfc 18d-a6a1-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.34	MCVC	Pipe material changes to vitrified clay at this point	00:00:07	MH 10X_d9c3 1105-c8fa-	
8.72	LD	Line deviates down	00:00:30	MH 10X_1a97 efa3-373a-	
9.46	BRF	Finish node, major connection without manhole, reference: L34: MAINLINE	00:00:33	MH 10X_adbc c411-c696	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 9X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
33	Downstream	FIC 9X		




MH
10X_2cbfc18d-a6a1-41fa-a0d2-7c275e7a450a_20250701_170821_815.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC9



MH
10X_d9c31105-c8fa-4a63-8956-95dd5c9a69ad_20250701_170822_692.jpg, 00:00:07, 0.34 m
Pipe material changes to vitrified clay at this point



MH
10X_1a97efa3-373a-4a10-9a0b-812b99802d83_20250701_170824_007.jpg, 00:00:30, 8.72 m
Line deviates down



MH
10X_adbcc411-c696-410b-b1b7-faa9e9a4c3ce_20250701_170825_407.jpg, 00:00:33, 9.46 m
Finish node, major connection without manhole, reference: L34

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - PPCP 1X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
34	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	PPCP 1X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	PPCP 1
Road:	Daisy Fields	**Inspected Length:**	13.13 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	13.13 m	**Downstream Node:**	SMH32
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:114

Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m					
PPCP 1					
0.00	MH	Start node, manhole, reference: PCPP1: L35	00:00:00	RW1X_17f319a1-05c0-444b-a0	
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
1.89	DER	Settled deposits, coarse, 5% cross-sectional area loss	00:00:20		3
13.13	MHF	Finish node, manhole, reference: SMH32	00:01:01	RW1X_25a4fa14-6ce2-47e6-b	
SMH32					
Depth: m					

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	1	2.0	0.2	2.0	3.0

Section Pictures - 30/06/2025 - PPCP 1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
34	Downstream	PPCP 1X		



RW1X_17f319a1-05c0-444b-a076-ac21c78080f6_20250701_152835_305.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: PCPP1



RW1X_25a4fa14-6ce2-47e6-be28-dda2abd915fd_20250701_170838_272.jpg, 00:01:01, 13.13 m
Finish node, manhole, reference: SMH32

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC10X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
35	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC10X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC10
Road:	Daisy Fields	**Inspected Length:**	8.28 m	**Upstream Pipe Depth:**	0.870 m
Location:	Other walkway	**Total Length:**	8.28 m	**Downstream Node:**	FMH77
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.700 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations: HPWJ LINE


Scale: 1:72

Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: 0.87 m			
		FIC10			
0.00	MH	Start node, manhole, reference: FIC10: L37	00:00:00	MH 11X_1965 b6ba-210c	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.90	MCVC	Pipe material changes to vitrified clay at this point	00:00:06	MH 11X_f9c60 126-d79b-	
7.64	DER	Settled deposits, coarse, 15% cross-sectional area loss	00:00:25	MH 11X_9169 1825-464d	3
8.28	MHF	Finish node, manhole, reference: FMH77	00:00:29	MH 11X_52ea 81d8-a3e5	
		FMH77			
		Depth: 0.70 m			

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	1	2.0	0.2	2.0	3.0

Section Pictures - 30/06/2025 - FIC10X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
35	Downstream	FIC10X		



MH
11X_1965b6ba-210c-480b-9f64-abe928a145e6_20250701_170905_822.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC10



MH
11X_f9c60126-d79b-426f-ad26-8be088aa6ce7_20250701_170907_112.jpg, 00:00:06, 0.90 m
Pipe material changes to vitrified clay at this point



MH
11X_91691825-464d-4d15-ba6c-5119b173f1fa_20250701_170908_566.jpg, 00:00:25, 7.64 m
Settled deposits, coarse, 15% cross-sectional area loss



MH
11X_52ea81d8-a3e5-4f90-a435-5e0d3a37668b_20250701_170909_809.jpg, 00:00:29, 8.28 m
Finish node, manhole, reference: FMH77

Section Inspection - 30/06/2025 - FIC 11X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
36	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 11X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	FIC 11
Road:	Daisy Fields	**Inspected Length:**	9.63 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	9.63 m	**Downstream Node:**	FMH77
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.700 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:84



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FMH77: L38	00:00:00	MH 13X_5424 87ce-bc2b	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
8.10	MCPVC	Pipe material changes to polyvinyl chloride at this point	00:00:23	MH 13X_df2f6 b5c-d883-	
9.63	MHF	Finish node, manhole, reference: FIC11	00:00:28	MH 13X_7365 6d1d-e237	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 11X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
36	Upstream	FIC 11X		



MH
13X_542487ce-bc2b-41e8-a440-7d6d188d7837_20250701_170926_996.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FMH77



MH
13X_df2f6b5c-d883-4533-8373-055732486320_20250701_170928_132.jpg, 00:00:23, 8.10 m
Pipe material changes to polyvinyl chloride at this point



MH
13X_73656d1d-e237-4282-a5ae-75aa3a4f0259_20250701_170929_326.jpg, 00:00:28, 9.63 m
Finish node, manhole, reference: FIC11

Section Inspection - 30/06/2025 - FMH77X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
37	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FMH77X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FMH77
Road:	Daisy Fields	**Inspected Length:**	23.97 m	**Upstream Pipe Depth:**	0.700 m
Location:	Other walkway	**Total Length:**	23.97 m	**Downstream Node:**	FMH56
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:208



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FMH77: L39	00:00:00	MH 12X_0df86777-8bc3-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
22.23	JN	Junction at 2 o'clock, 150mm dia	00:00:53	MH 12X_ae8ecd57-5ba5	
23.97	MHF	Finish node, manhole, reference: FMH56: CAPPED	00:00:59	MH 12X_9cc4ca99-7b63-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FMH77X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
37	Downstream	FMH77X		



MH
12X_0df86777-8bc3-4ab2-b3e1-925b22642569_20250701_153725_379.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FMH77



MH
12X_ae8ecd57-5ba5-4875-9bd5-2c010693ccb7_20250701_170942_601.jpg, 00:00:53, 22.23 m
Junction at 2 o'clock, 150mm dia



MH
12X_9cc4ca99-7b63-4d42-b7a6-9b2d1fb69134_20250701_170944_553.jpg, 00:00:59, 23.97 m
Finish node, manhole, reference: FMH56

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 12X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
38	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 12X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 12
Road:	Daisy Fields	**Inspected Length:**	11.67 m	**Upstream Pipe Depth:**	0.480 m
Location:	Other walkway	**Total Length:**	11.67 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:102	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 0.48 m **FIC 12**						
	0.00	MH	Start node, manhole, reference: FIC12	00:00:00	MH 15X_9b58 31c1-41ab	
	0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
	11.67	BRF	Finish node, major connection without manhole, reference: L40	00:00:31	MH 15X_7069 3e50-5f42-	
MAIN **Depth: m**						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
1	1.0	0.1	1.0	1.0	1	2.0	0.2	2.0	3.0

Section Pictures - 30/06/2025 - FIC 12X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
38	Downstream	FIC 12X		



MH
15X_9b5831c1-41ab-46be-a468-ebcd7b7b22cc_20250701_160736_294.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC12



MH
15X_70693e50-5f42-4988-8b93-f4438a912902_20250701_171001_299.jpg, 00:00:31, 11.67 m
Finish node, major connection without manhole, reference: L40

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - PPCP 2X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
39	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	PPCP 2X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	PPCP 2
Road:	Daisy Fields	**Inspected Length:**	16.27 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	16.27 m	**Downstream Node:**	SMH49
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.580 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:141



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: SMH49	00:00:00	RW 4X_a93b3 982-9e1b-	
0.00	WL	Water level, 5% of the vertical dimension: L41	00:00:01		
15.75	LR	Line deviates right	00:00:46	RW 4X_4a3d0 c84-57e7-	
16.27	MHF	Finish node, manhole, reference: PPCP2	00:00:52	RW 4X_4293e 051-128e-	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	1.0	0.1	1.0	1.0	1	2.0	0.1	2.0	3.0

Section Pictures - 30/06/2025 - PPCP 2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
39	Upstream	PPCP 2X		



RW
4X_a93b3982-9e1b-4ea8-9f32-d73468393559_20250701_171036_564.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: SMH49



RW
4X_4a3d0c84-57e7-43e7-932e-ecde1b48e52d_20250701_171038_965.jpg, 00:00:46, 15.75 m
Line deviates right



RW
4X_4293e051-128e-43bd-af61-42012154903d_20250701_171040_244.jpg, 00:00:52, 16.27 m
Finish node, manhole, reference: PPCP2

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - PPCP 4X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
40	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	PPCP 4X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	PPCP 4
Road:	Daisy Fields	**Inspected Length:**	15.63 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	15.63 m	**Downstream Node:**	SMH49
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.700 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:136

Depth: 0.70 m
SMH49



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: SMH49	00:00:00	L42X_b19ed3d1-e8ac-49b8-bc	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
15.63	OCF	Finish node, other special chamber, reference: PPCP4: LINE OPEN	00:00:51	L42X_671d8aa7-91ea-4559-85	

PPCP 4
Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
1	1.0	0.1	1.0	1.0	1	2.0	0.1	2.0	3.0

Section Pictures - 30/06/2025 - PPCP 4X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
40	Upstream	PPCP 4X		



L42X_b19ed3d1-e8ac-49b8-bcbc-5ecef1a1e853_20250701_171102_905.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: SMH49



L42X_671d8aa7-91ea-4559-851a-df5ee5461d31_20250701_171105_580.jpg, 00:00:51, 15.63 m
Finish node, other special chamber, reference: PPCP4

Section Inspection - 30/06/2025 - L43X


Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
41	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	L43X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	L43
Road:	Daisy Fields	**Inspected Length:**	0.18 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	0.18 m	**Downstream Node:**	SMH49
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	0.700 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:



Scale: 1:50 Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: SMH49	00:00:00	L43X_e186bf16-5689-4693-b0	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.18	OCF	Finish node, other special chamber, reference: L43: LINE OPEN	00:00:07	L43X_89ba41a3-68c9-46a7-b7f	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - L43X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
41	Upstream	L43X		



L43X_e186bf16-5689-4693-b09f-43388f8e7d29_20250701_171125_590.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: SMH49



L43X_89ba41a3-68c9-46a7-b7f3-e1fc5b98fa28_20250701_171126_579.jpg, 00:00:07, 0.18 m
Finish node, other special chamber, reference: L43

Section Inspection - 30/06/2025 - SMH49X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
42	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	SMH49X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	SMH49
Road:	Daisy Fields	**Inspected Length:**	12.43 m	**Upstream Pipe Depth:**	0.700 m
Location:	Other walkway	**Total Length:**	12.43 m	**Downstream Node:**	SMH32
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:108	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 0.70 m						
SMH49						
	0.00	MH	Start node, manhole, reference: SMH49: L44	00:00:00	RW 3X_7a290 796-02cb-	
	0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
	12.43	MHF	Finish node, manhole, reference: SMH32	00:00:35	RW 3X_1f5987 20-5046-4	
SMH32						
Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - SMH49X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
42	Downstream	SMH49X		



RW
3X_7a290796-02cb-4df0-9696-5199da4b61f3_20250701_171131_646.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: SMH49



RW
3X_1f598720-5046-4406-8d08-ccb434507be9_20250701_171133_556.jpg, 00:00:35, 12.43 m
Finish node, manhole, reference: SMH32

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FMH51X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
43	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FMH51X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	FMH51
Road:	Daisy Fields	**Inspected Length:**	30.50 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	30.50 m	**Downstream Node:**	FMH56
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	1.670 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:265



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FMH56	00:00:00	L45X_54fa6a9d-8fa3-4c87-8269	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
30.50	SA	Survey abandoned: LINE NOT INSTALLED	00:01:14	FMH51X_c519aef4-3824-4b76	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FMH51X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
43	Upstream	FMH51X		



L45X_54fa6a9d-8fa3-4c87-8269-b961a2f7090e_20250701_171145_211.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FMH56



FMH51X_c519aef4-3824-4b76-9d7c-9d17c2d02585_20250722_124522_253.jpg, 00:01:14, 30.50 m
Survey abandoned

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 13X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
44	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 13X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 13
Road:	Daisy Fields	**Inspected Length:**	7.03 m	**Upstream Pipe Depth:**	1.670 m
Location:	Other walkway	**Total Length:**	7.03 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:61

Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 1.67 m **FIC 13**					
0.00	MH	Start node, manhole, reference: FIC13	00:00:00	MH 17X_a10a edf6-cdeb-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
6.32	LD	Line deviates down	00:00:18	MH 17X_6371 23b5-5d38	
7.03	BRF	Finish node, major connection without manhole, reference: L47	00:00:21	MH 17X_c161 e9a8-ab15	
MAIN **Depth: m**					


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC 13X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
44	Downstream	FIC 13X		



MH
17X_a10aedf6-cdeb-4ae4-b22b-f10f512d74c5_20250701_171159_431.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC13



MH
17X_637123b5-5d38-49b0-9d51-6bcc010a04c3_20250701_171201_084.jpg, 00:00:18, 6.32 m
Line deviates down



MH
17X_c161e9a8-ab15-4730-91e9-96ed611f1553_20250701_171202_241.jpg, 00:00:21, 7.03 m
Finish node, major connection without manhole, reference: L47

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC 14X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
45	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC 14X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified


Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC 14
Road:	Daisy Fields	**Inspected Length:**	9.70 m	**Upstream Pipe Depth:**	1.670 m
Location:	Other walkway	**Total Length:**	9.70 m	**Downstream Node:**	FMH78
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:84

Depth: 1.67 m
FIC 14



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC14: L48	00:00:00	MH 18X_d6d0 340d-fd57-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
8.77	JN	Junction at 6 o'clock, 100mm dia: DROPSHAFT	00:00:26	MH 18X_90cf7 bcf-f849-4	
9.70	MHF	Finish node, manhole, reference: FMH78	00:00:39	MH 18X_202d d446-6da3	

FMH78
Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
4	120.0	14.4	140.0	4.0	4	2.0	0.4	4.0	3.0

Section Pictures - 30/06/2025 - FIC 14X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
45	Downstream	FIC 14X		

Section Pictures - 30/06/2025 - FIC 14X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
45	Downstream	FIC 14X		



MH
18X_90cf7bcf-f849-4bdd-b5a4-65d855e184d4_20250701_171212_939.jpg, 00:00:26, 8.77 m
Junction at 6 o'clock, 100mm dia



MH
18X_202dd446-6da3-4391-ad8d-15a0a9b2aed1_20250701_171213_817.jpg, 00:00:39, 9.70 m
Finish node, manhole, reference: FMH78

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - PPCP 3X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
46	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	PPCP 3X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	PPCP 3
Road:	Daisy Fields	**Inspected Length:**	7.53 m	**Upstream Pipe Depth:**	
Location:	Other walkway	**Total Length:**	7.53 m	**Downstream Node:**	SMH19
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations: PATCH REPAIR DISPLACED JOINT



Scale: 1:66	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m PPCP 3						
	0.00	MH	Start node, manhole, reference: PPCP3: L49	00:00:00	RW 5X_67376 e35-7df7-4	
	0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
	6.00	JDM	Joint displaced, medium	00:00:24	RW 5X_ab342 3f2-c33a-4	1 / 3
	7.53	MHF	Finish node, manhole, reference: SMH19	00:00:30	RW 5X_d1ce2 970-2dca-	
SMH19 Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
1	1.0	0.1	1.0	1.0	1	2.0	0.3	2.0	3.0

Section Pictures - 30/06/2025 - PPCP 3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
46	Downstream	PPCP 3X		



RW
5X_67376e35-7df7-4393-8606-b9a703663b0b_20250701_163005_166.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: PPCP3



RW
5X_d1ce2970-2dca-4650-b1c8-1f0f291bfa46_20250701_171236_366.jpg, 00:00:30, 7.53 m
Finish node, manhole, reference: SMH19

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - SMH32X


Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
47	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	SMH32X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Upstream	**Upstream Node:**	SMH32
Road:	Daisy Fields	**Inspected Length:**	19.08 m	**Upstream Pipe Depth:**	1.520 m
Location:	Other walkway	**Total Length:**	19.08 m	**Downstream Node:**	SMH19
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	525 mm
Flow Control:	No flow control	**Material:**	Concrete
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations: HPWJ LINE



Scale: 1:166	Position [m]	Code	Observation	MPEG	Photo	Grade
	0.00	MH	Start node, manhole, reference: SMH19	00:00:00	RW 6X_ee1bd 8ae-80e0-	
	0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
	12.83	CN	Connection other than junction at 9 o'clock, 150mm dia	00:00:35	RW 6X_a3597 531-0668-	
	13.03	DER	Settled deposits, coarse, 10% cross-sectional area loss	00:00:35	RW 6X_41c28 64b-3924-	4
	16.25	CN	Connection other than junction at 2 o'clock, 150mm dia	00:01:17	RW 6X_3b52f4 c5-18b4-4	
	19.08	SA	Survey abandoned: UNABLE TO PUSH	00:02:08	RW 6X_1a452 a71-d337-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	1	5.0	0.3	5.0	4.0

Section Pictures - 30/06/2025 - SMH32X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
47	Upstream	SMH32X		



RW
6X_ee1bd8ae-80e0-481e-a8f9-742d6a44516c_20250701_171254_847.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: SMH19



RW
6X_a3597531-0668-4c4c-8051-6e759ca75387_20250701_171256_231.jpg, 00:00:35, 12.83 m
Connection other than junction at 9 o'clock, 150mm dia



RW
6X_41c2864b-3924-4bc4-96b7-07289dc46039_20250701_171257_433.jpg, 00:00:35, 13.03 m
Settled deposits, coarse, 10% cross-sectional area loss



RW
6X_3b52f4c5-18b4-459b-8301-7d3856c56ca3_20250701_171259_239.jpg, 00:01:17, 16.25 m
Connection other than junction at 2 o'clock, 150mm dia

Section Pictures - 30/06/2025 - SMH32X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
47	Upstream	SMH32X		



RW
6X_1a452a71-d337-404b-94e5-42f911da25b2_20250701_171301_750.jpg, 00:02:08, 19.08 m
Survey abandoned

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FMH78X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
48	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FMH78X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FMH78
Road:	Daisy Fields	**Inspected Length:**	45.14 m	**Upstream Pipe Depth:**	1.520 m
Location:	Other walkway	**Total Length:**	45.14 m	**Downstream Node:**	FMH81
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations: HPWJ LINE

Scale: 1:391




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: MH 16	00:00:00	MH 16X_ffa5c aad-b699-	
0.00	WL	Water level, 5% of the vertical dimension	00:00:03		
0.00	DER	Settled deposits, coarse, 10% cross-sectional area loss	00:00:03	MH 16X_831b e70e-b5d3	4
22.60	JN	Junction at 2 o'clock, 150mm dia	00:00:44	MH 16X_4920 7387-fce9-	
22.60	DER	Settled deposits, coarse, 10% cross-sectional area loss	00:00:44	MH 16X_ae66 37d3-2ee9	4
42.44	DER	Settled deposits, coarse, 10% cross-sectional area loss	00:01:18	MH 16X_f0451 5b5-4de7-	4
42.82	JN	Junction at 2 o'clock, 100mm dia	00:01:22	MH 16X_06d9 a35f-f385-	
44.72	DER	Settled deposits, coarse, 10% cross-sectional area loss	00:01:34	MH 16X_21b8 2981-a94f-	3
45.14	SA	Survey abandoned: UNABLE TO PUSH	00:01:43	MH 16X_1eca beb2-2ba5	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	4	5.0	0.4	17.0	4.0

Section Pictures - 30/06/2025 - FMH78X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
48	Downstream	FMH78X		



MH
16X_ffa5caad-b699-48b2-b22e-d61fc1640811_20250701_163439_190.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: MH 16



MH
16X_831be70e-b5d3-4fd3-a591-6508bf28d573_20250701_171316_109.jpg, 00:00:03, 0.00 m
Settled deposits, coarse, 10% cross-sectional area loss



MH
16X_49207387-fce9-4f86-a358-b32d11aac392_20250701_171322_631.jpg, 00:00:44, 22.60 m
Junction at 2 o'clock, 150mm dia



MH
16X_ae6637d3-2ee9-4e78-8611-e4a6e2d9159e_20250701_171324_926.jpg, 00:00:44, 22.60 m
Settled deposits, coarse, 10% cross-sectional area loss

Section Pictures - 30/06/2025 - FMH78X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
48	Downstream	FMH78X		



MH
16X_f04515b5-4de7-4fef-a6a0-a0ded038ff0f_20250701_171326_485.jpg, 00:01:18, 42.44 m
Settled deposits, coarse, 10% cross-sectional area loss



MH
16X_06d9a35f-f385-4247-8ba2-0711951d2b2b_20250701_171328_973.jpg, 00:01:22, 42.82 m
Junction at 2 o'clock, 100mm dia



MH
16X_21b82981-a94f-4b09-a015-4cd51ef86c41_20250701_171331_125.jpg, 00:01:34, 44.72 m
Settled deposits, coarse, 10% cross-sectional area loss



MH
16X_1ecabeb2-2ba5-4ac7-ae40-e368e776e9f1_20250701_171333_167.jpg, 00:01:43, 45.14 m
Survey abandoned

Section Inspection - 30/06/2025 - FMH52X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
49	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FMH52X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FMH52
Road:	Daisy Fields	**Inspected Length:**	40.23 m	**Upstream Pipe Depth:**	1.580 m
Location:	Other walkway	**Total Length:**	40.23 m	**Downstream Node:**	FMH59
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Vitrified clay
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:349



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FMH52	00:00:00	MH 3X_cd882 e98-e9b0-	
0.00	WL	Water level, 10% of the vertical dimension	00:00:01		
2.47	WL	Water level, 5% of the vertical dimension	00:00:09	MH 3X_3e3b1 e92-366c-	
3.37	WL	Water level, 20% of the vertical dimension	00:00:10	MH 3X_89e96 bbc-6644-	
11.03	WL	Water level, 5% of the vertical dimension	00:00:22	MH 3X_80298 9a5-0534-	
25.85	JN	Junction at 9 o'clock, 100mm dia	00:00:47	MH 3X_48989 a1c-9e95-	
26.15	JN	Junction at 3 o'clock, 100mm dia	00:00:48	MH 3X_f1f451 71-fd3f-45	
38.28	WL	Water level, 20% of the vertical dimension	00:01:14	MH 3X_b00ac e25-f294-4	
40.23	MHF	Finish node, manhole, reference: FMH59	00:01:28	MH 3X_c2314 810-71d2-	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FMH52X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
49	Downstream	FMH52X		



MH
3X_cd882e98-e9b0-49f6-88cb-8ad3bf3c588e_20250701_171346_507.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FMH52



MH
3X_3e3b1e92-366c-47b8-9586-a085288d2eb7_20250701_171349_715.jpg, 00:00:09, 2.47 m
Water level, 5% of the vertical dimension



MH
3X_89e96bbc-6644-4496-b404-0162371237fa_20250701_171350_903.jpg, 00:00:10, 3.37 m
Water level, 20% of the vertical dimension



MH
3X_802989a5-0534-4b38-8657-062f89b8600b_20250701_171352_112.jpg, 00:00:22, 11.03 m
Water level, 5% of the vertical dimension

Section Pictures - 30/06/2025 - FMH52X


Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
49	Downstream	FMH52X		



MH
3X_48989a1c-9e95-4c8e-8925-695b3b9f80b9_20250701_171354_153.jpg, 00:00:47, 25.85 m
Junction at 9 o'clock, 100mm dia



MH
3X_f1f45171-fd3f-45b6-89f7-ecc838128f44_20250701_171355_430.jpg, 00:00:48, 26.15 m
Junction at 3 o'clock, 100mm dia



MH
3X_b00ace25-f294-404c-9763-72f83220d81c_20250701_171357_040.jpg, 00:01:14, 38.28 m
Water level, 20% of the vertical dimension



MH
3X_c2314810-71d2-42b8-a1a5-269413f999c8_20250701_171359_152.jpg, 00:01:28, 40.23 m
Finish node, manhole, reference: FMH59

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - FIC16X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
50	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	FIC16X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	FIC16
Road:	Daisy Fields	**Inspected Length:**	4.96 m	**Upstream Pipe Depth:**	0.580 m
Location:	Other walkway	**Total Length:**	4.96 m	**Downstream Node:**	MAIN
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: FIC16	00:00:00	MH 20X_46c1f fbe-7ae8-4	
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.00	LD	Line deviates down	00:00:01	MH 20X_19a7 5c38-5faa-	
0.34	MCVC	Pipe material changes to vitrified clay at this point	00:00:04	MH 20X_1a57 9186-68b0	
3.95	LR	Line deviates right	00:00:13	MH 20X_64f35 a48-bdcb-	
4.96	BRF	Finish node, major connection without manhole, reference: L53: MAINLINE	00:00:20	MH 20X_b029 9369-bae6	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 30/06/2025 - FIC16X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
50	Downstream	FIC16X		



MH
20X_46c1ffbe-7ae8-44dc-b555-49cfe8c7dc1c_20250701_164240_563.jpg, 00:00:00, 0.00 m
Start node, manhole, reference: FIC16



MH
20X_19a75c38-5faa-45f8-801b-16fc79676ae1_20250701_171404_367.jpg, 00:00:01, 0.00 m
Line deviates down



MH
20X_1a579186-68b0-4579-979a-5bfcbd216fde_20250701_171405_246.jpg, 00:00:04, 0.34 m
Pipe material changes to vitrified clay at this point



MH
20X_64f35a48-bdcb-4e49-97a6-66b6e013821a_20250701_171406_201.jpg, 00:00:13, 3.95 m
Line deviates right

Section Pictures - 30/06/2025 - FIC16X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
50	Downstream	FIC16X		



MH
20X_b0299369-bae6-4a13-863e-0d6773b594ee_20250701_171407_949.jpg, 00:00:20, 4.96 m
Finish node, major connection without manhole, reference: L53

PROLINE DRAINAGE

PROLINE DRAINAGE LTD
CHARLWOOD ROAD, CRAWLEY
[redacted]

Section Inspection - 30/06/2025 - SMH75X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
51	1	30/06/25	12:59	Not Specified	No Rain Or Snow	No	SMH75X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	CAMERA VAN	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Littlehampton	**Inspection Direction:**	Downstream	**Upstream Node:**	SMH75
Road:	Daisy Fields	**Inspected Length:**	19.47 m	**Upstream Pipe Depth:**	1.400 m
Location:	Other walkway	**Total Length:**	19.47 m	**Downstream Node:**	SMH42
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	450 mm
Flow Control:	No flow control	**Material:**	Concrete
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:	Routine inspection	**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:169

Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: 1.40 m			
		SMH75			
0.00	MH	Start node, manhole, reference: SMH75	00:00:00	RW 7X_f9af21dc-4dea-4	
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.54	WL	Water level, 10% of the vertical dimension	00:00:08	RW 7X_67c55cd0-36ed-	
13.75	WL	Water level, 20% of the vertical dimension	00:00:19	RW	

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]