ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	2	
Present:	Vehicle: **WM69 YNA**	Camera: **Camera 1**	Preset:	Cleaned: **Yes**	Grade:

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 21** End MH: **SMH 21.1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



11.2M	MH	Camera Enters Manhole S 21.1

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	3	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 21** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.3M	G	Camera Stops At Gully 1

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		Dry	Mick	4	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 21** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
3.0M	G	Camera Stops At Gully 2

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	5	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 21** End MH: **SMH 20** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



26.3M JN Line Drops In From The Left From Manhole S 20.3

30.7M MH Camera Enters Manhole S 20

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	6	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 20.3** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	7	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 20** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.1M	PR	Pipe Reduces To 100mm



7.0M	MH	Camera Enters Manhole S 20.1

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	8	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 3** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	9	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 4** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	10	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 20** End MH: **SMH 19** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.2M JN Line Drops In From Above From G 3

8.2M JN Line Drops In From Above From G 4

18.3M MH Camera Enters Manhole S 19

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	11	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 18.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.0M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	12	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 5** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
1.2M	PS	Pipe Smashed At Top
2.8M	LD	Line Drops Into Main



REM ; THERE IS A HOLE IN THE TOP OF THE PIPE AT 1.2 METRES

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	13	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 6** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.3M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	14	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 19** End MH: **SMH 17** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
7.6M	JN	Line Drops In From The Right From S 18.1
10.5M	JN	Line Drops In From The Right From G 5
11.2M	JN	Line Drops In From The Left From G 6
22.1M	MH	Camera Enters Manhole S 17



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 17.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	15	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 7** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.5M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	16	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 17.2** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		Dry	Mick	17	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 8** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	18	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 16.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.7M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	19	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 9** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	20	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 10** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.8M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	21	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 11** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	22	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 12** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.3M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	23	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 16** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.1M	WL	Water Level 20 %
9.5M	WL	Water Level 0 %
12.8M	G	Camera Stops At Gully 13



REM ; THERE IS AN UNDEROLL IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	24	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 16** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.2M	JN	Line Drops InFrom The Right From Gully 15
12.8M	G	Camera Stops At Gully 14



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]3


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	25	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 15** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.1M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	26	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 16** End MH: **SMH 15** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.2M	JN	Line Drops InFrom The Right From Gully 15
3.0M	MH	Camera Enters Manhole S 15



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	27	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 15** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
2.7M	JN	Line Drops InFrom The Left From Gully 17
4.8M	G	Camera Stops At Gully 16



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	28	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 18** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.2M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	29	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 19** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	30	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 20** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.7M LL Line Turns Left

5.1M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	31	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 22** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.8M	MH	Camera Enters Manhole S22.4

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	32	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 22** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.2M	G	Camera Stops At Gully 21

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	33	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 22** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.5M	G	Camera Stops At Gully 22

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	34	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 22** End MH: **LAT 4** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.2M	CP	Line Capped Off

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE, BUT MANHOLE S22.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	35	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 14.2** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	36	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 14.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	37	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 23** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.3M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	38	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 13.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.5M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	39	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 12.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	40	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 24** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.8M	JN	Line Drops In From The Left From G 25
3.5M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	41	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 25** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.5M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	42	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 11.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.0M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	43	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 24** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.3M	G	Camera Stops At Gully 26

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	44	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 24** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.2M	CP	Line Capped Off

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE, BUT MANHOLE S24.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	45	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 27** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	46	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 9** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.9M CP Line Capped Off

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE, BUT MANHOLE S9.1 , S9.2, S9.3 & S10.1 HAVE NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	47	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 28** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.8M	LD	Line Drops Down
6.4M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	48	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 29** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P [redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	49	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 37.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	50	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 32** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.8M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	51	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 33** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.7M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	52	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 34** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	53	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 35** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.2M	D	Concrete In Line, Unable To Pass

REM ; THERE IS CONCRETE IN THIS LINE WHICH WE CAN NOT REMOVE. UNABLE TO ACCESS MANHOLE S35.1 AS HAS SCAFFOLD ERECTED ON IT

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	54	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 34.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.5M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	55	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 36** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	56	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 37** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE
MANHOLE S 33.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]nts
[redacted]B


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	57	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 38** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
2.2M	LL	Line Turns Left
4.4M	JN	Line Drops In From The Right From G 39
8.7M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIP

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	58	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 39** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.0M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	59	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 32.2** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	60	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 32.1** End MH: **SMH 64** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.4M	MH	Camera Enters Manhole S 64

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		**Dry**	**Mick**	61	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 40** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
31/03/25		Dry	Mick	62	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 41** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.1M	JN	Line Drops In From The Left From G 40



2.6M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE
MANHOLE S33.3 AND GULLIES 42 & 43 HAVE NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		Dry	Mick	63	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 55** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.9M PR Pipe Reduces To 100mm

3.6M MH Camera Enters Manhole S 22.2

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	64	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 55** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.1M	G	Camera Stops At Gully 44

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	65	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 55** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.6M	G	Camera Stops At Gully 45

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	66	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 55** End MH: **LAT 4** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.2M	PR	Pipe Reduces To 100mm
6.7M	MH	Camera Enters Manhole S 55.1



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	62	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 46** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.2M	JN	Line Drops In From The Left From Gully 47
3.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	68	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 56.4** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.7M	MH	Camera Enters Manhole S 56

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	69	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 56.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.4M	MH	Camera Enters Manhole S 56

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	70	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 57.1** End MH: **SMH 57** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.9M	MH	Camera Enters Manhole S 57

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	71	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 48** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		Dry	Mick	72	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 49** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.8M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	73	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 53.1** End MH: **SMH 53** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.5M	MH	Camera Enters Manhole S 53

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		Dry	Mick	74	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 50** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	75	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 51** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	76	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 54** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE
MANHOLE S54.2 NOT INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	77	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 54** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



11.7M	G	Camera Stops At Gully 52

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PI

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	78	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 54** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



11.4M	G	Camera Stops At Gully 53

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	79	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 54** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE
MANHOLES S 51.4 - S 51.5 & S 51.3 NOT INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	80	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 55** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE
GULLIES G 56 & G 57 BOTH HAVE THE TOP BUNGS CONCRETED IN SO CAN NOT CAMERA

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	81	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 51.1** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	82	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 58** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.2M	D	Concrete In Entrance To Drain
3.2M	LD	Line Drops Into Main

REM ; THERE IS CONCRETE IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		Dry	Mick	83	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 59** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	84	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 50** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



5.6M CP Line Is Capped Off

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE
MANHOLE S 50.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/04/25		**Dry**	**Mick**	85	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 50** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



3.5M G Camera Stops At Gully 60

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	86	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 61** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		Dry	Mick	87	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 62** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.9M	JN	Line Drops In From The Left From Gully 63
2.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	88	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 63** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.5M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		Dry	Mick	89	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 64** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
01/4/25		**Dry**	**Mick**	90	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 49.1** End MH: **SMH 49** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.5M	MH	Camera Enters Manhole S 49

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		Dry	Mick	91	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 38** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.9M	JN	Line Drops In From The Right
10.4M	G	Camera Stops At Gully 30



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	92	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 38** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.2M	CR	Cracks In Top Of Pipe
10.5M	PR	Pipe Reduces To 100mm
12.2M	MH	Camera Enters Manhole S 38.1



REM ; THERE ARE CRACKS IN THE TOP OF THIS PIPE WHERE WATER IS DRIPPING IN

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	93	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 31** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.7M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	94	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 36.1** End MH: **SMH 36** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.4M	MH	Camera Enters Manhole S 36

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	95	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 31** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.9M	CP	Line Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANOHLE S 30.5 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	96	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 31** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



15.6M	G	Camera Enters Gully 80

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	97	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 31** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



16.0M	G	Camera Enters Gully 81

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	98	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 31** End MH: **LAT 4** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



11.1M	CP	Line Is Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 30.4 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	99	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 82** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.7M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	100	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 83** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.4M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
GULLY 84 BUNG HAS BEEN CONCRETED IN

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	101	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 85** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.5M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
GULLY 84 BUNG HAS BEEN CONCRETED IN

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	102	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 30** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.7M	CP	Line Is Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 30.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	103	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 29** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.2M	G	Camera Stops At Gullly 86

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		Dry	Mick	104	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 29** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.5M	G	Camera Stops At Gullly 87

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		Dry	Mick	105	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 41** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.6M	CP	Line Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 41.1 NOT INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	106	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 41** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.1M	G	Camera Stops At Gully 86

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	107	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 41** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



9.1M	CP	Line Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 41.7 NOT INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	108	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 41** End MH: **LAT 4** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.2M	G	Camera Stops At Gully 87

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	109	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 88** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.7M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	110	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 89** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.3M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	111	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 91** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	112	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 90** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.7M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	113	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 28** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.0M CP Line Is Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 28.1 NOT INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	114	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 27** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	115	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 27** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.3M	CP	Line Is Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 27.1 NOT INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		Dry	Mick	116	
Present:	**Vehicle:**	**Camera:**	**Preset:**	**Cleaned:**	**Grade:**
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 93** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.2M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	117	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 94** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]
Te[redacted]B


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	118	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 95** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.2M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
27/03/25		**Dry**	**Mick**	119	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 17** End MH: **SMH 16** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
3.6M	JN	Line Drops In From The Right
16.4M	JN	Line Drops In From The Left
17.9M	JN	Line Drops In From The Right
21.3M	JN	Line Drops In From The Right
35.5M	JN	Line Drops In From The Right
41.1M	JN	Line Drops In From The Left
41.8M	JN	Line Drops In From The Right
46.3M	JN	Line Drops In From The Left
47.3M	JN	Line Drops In From The Left
48.3M	MH	Camera Enters Manhole S 16



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		Dry	Mick	120	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	Camera 1		Yes	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 22** End MH: **SMH 15** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
25.0M	JN	Line Drops In From The Left
30.0M	JN	Line Drops In From The Left
30.2M	JN	Line Drops In From The Left
42.2M	JN	Line Drops In From The Left
44.7M	MH	Camera Enters Manhole S 15



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	121	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 14** End MH: **SMH 15** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 375mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
8.4M	JN	Line Drops In From The Left From S 14.1
22.6M	JN	Line Drops In From The Left From S 14.23
29.4M	MH	Camera Enters Manhole S 15



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	122	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 13** End MH: **SMH 14** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 375mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.6M	JN	Line Drops In From The Left From S 13.1
5.8M	JN	Line Drops In From The Right
11.9M	MH	Camera Enters Manhole S 14



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]

Inspection Photos

Place:	Road:	Date:	Section Number:	PLR:
Tye Lane		03/04/**25**	**123**	



MANHOLE S 13 NEEDS MAN ENTRY TO CLEAN OUT
AS STONES TO LARGE TO SUCK UP WITH TANKER

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]

Inspection Photos

Place:	Road:	Date:	Section Number:	PLR:
Tye Lane		03/04/**25**	**123**	



MANHOLE S 12 NEEDS MAN ENTRY TO CLEAN OUT
AS UNABLE TO GET TANKER ANYWHERE NEAR DRAIN

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	125	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 38** End MH: **SMH 36** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
21.1M	JN	Line Drops In From The Left
24.0M	JN	Line Drops In From The Right
24.8M	JN	Line Drops In From The Left
39.3M	MH	Camera Enters Manhole S 36



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
03/04/25		**Dry**	**Mick**	126	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 36** End MH: **SMH 35** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



25.8M	JN	Line Drops In From Above
26.6M	JN	Line Drops In From Above
34.1M	MH	Camera Enters Manhole S 35

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	126	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 35** End MH: **SMH 34** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



14.5M	JN	Line Drops In From The Right From S 34.1
23.6M	MH	Camera Enters Manhole S 34

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	128	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 34** End MH: **SMH 33** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
3.2M	JN	Line Drops In From The Right
5.9M	JN	Line Drops In From The Left
9.9M	JN	Line Drops In From The Right From S 33.1
12.2M	JN	Line Drops In From The Right
14.7M	MH	Camera Enters Manhole S 35



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 33.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	129	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 30** End MH: **SMH 64** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.5M	JN	Line Drops In From The Left From S 30.3
5.5M	JN	Line Drops In From The Right
6.4M	JN	Line Drops In From The Right
31.1M	MH	Camera Enters Manhole S 64



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 30.3 HAS NOT BEEN NSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	130	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 64** End MH: **SMH 32** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.9M	MH	Camera Enters Manhole S 32

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	131	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 32** End MH: **SMH 33** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING


All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	132	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 31** End MH: **SMH 30** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	



Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.9M	JN	Line Drops In From The Left
7.1M	JN	Line Drops In From The Right
12.2M	JN	Line Drops In From The Right From S 30.6
13.0M	JN	Line Drops In From The Left From S 30.7
27.8M	JN	Line Drops In From The Right From S 30.5
28.6M	JN	Line Drops In From The Left From S 30.4
31.4M	JN	Line Drops In From The Right
32.2M	JN	Line Drops In From The Left
50.8M	MH	Camera Enters Manhole S 30

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLES S 30.4 -S 30.5 - S 30.7 - S 30.6 HAVE NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	133	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 30** End MH: **SMH 29** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



11.5M	MH	Camera Enters Manhole S 29

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	134	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 29** End MH: **SMH 28** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.8M	MH	Camera Enters Manhole S 28

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	135	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 41** End MH: **SMH 28** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
18.7M	JN	Line Drops In From The Left
19.3M	JN	Line Drops In From The Right From S 28.4
31.4M	JN	Line Drops In From The Left
36.2M	MH	Camera Enters Manhole S 28



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE
MANHOLE S 28.4 HAS NOT BEEN INSTALLED

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	136	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 28** End MH: **SMH 27** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
12.5M	JN	Line Drops In From The Right
13.4M	JN	Line Drops In From The Left
28.0M	MH	Camera Enters Manhole S 27



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
04/04/25		**Dry**	**Mick**	137	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 27** End MH: **SMH 26** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
10.4M	JN	Line Drops In From The Right
13.5M	MH	Camera Enters Manhole S 26

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	138	
Present:	Vehicle: **WM69 YNA**	Camera: **Camera 1**	Preset:	Cleaned: **Yes**	Grade:

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 25** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.2M	CP	Line Caped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE, BUT MANHOLE S26.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	139	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 25** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



13.6M	G	Camera Enters Gully 96

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	140	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 25** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



12.6M	D	Pug In Line
14.6M	G	Camera Enters Gully 97

REM ; THERE IS A LAYER OF PUG IN THIS SECTION OF PIPE THAT THE JETTER WONT REMOVE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	141	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 98** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	142	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 99** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	143	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 100** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.8M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]

Inspection Report


Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	144	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 101** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.0M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	145	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 40** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.8M CP Line Capped Off

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE, MANHOLE S40.1 HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	146	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **GULLY 102** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 150mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
2.2M	JN	Line Drops In From The Left From Gully 103
6.1M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	147	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 25** End MH: **SMH 26** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.4M	JN	Line Drops In From The Right From G 95
7.0M	JN	Line Drops In From The Left From G 94
11.2M	MH	Camera Enters Manhole S 26



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	148	
Present:	Vehicle: **WM69 YNA**	Camera: **Camera 1**	Preset:	Cleaned: **Yes**	Grade:

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 25** End MH: **SMH 40** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
3.1M	JN	Line Drops In From The Right From G 98
4.1M	JN	Line Drops In From The Right From Gully 99
10.9M	JN	Line Drops In From Above From G100
12.0M	JN	Line Drops In From The Right From G 101
14.9M	MH	Camera Enters Manhole S 40



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	149	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 40** End MH: **SMH 39** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



16.3M	JN	Line Drops In From The Right From G 102- G 103
17.4M	JN	Line Drops In From The Right
25.6M	MH	Camera Enters Manhole S 39

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE, MANHOLE S39.1 HAS NOT BEEN INSTALLED YET
UNABLE TO CLEAN FROM MANHOLE S 39 TO S 5 AS UNABLE TO ACCESS MANHOLE S 39 AS COVERED OVER WITH SCAFFOLDING

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	150	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 9** End MH: **SMH 8** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



15.9M	D	Debris In Line, Unable To Pass

REM ; UNABLE TO GET LORRY NEAR MANHOLE S 8 TO CLEAN LINE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	151	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 24** End MH: **SMH 9** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 450mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



18.9M	JN	Line Drops In From Above
21.1M	MH	Camera Enters Manhole S 9

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
[redacted]

Inspection Photos

Place:	Road:	Date:	Section Number:	PLR:
Tye Lane		23/04/**25**	**152**	



MANHOLE S 9 HAS A BUNG IN THE MANHOLE AND IT HAS BEEN CONCRETED INTO THE CHANNEL, THIS IS HOLDING UP WATER IN THE DRAINS UPSTREAM SO UNABLE TO CLEAN OR CAMERA FROM MANHOLES S12- S11 & S10

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	153	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 55** End MH: **SMH 56** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 375mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



33.6M	JN	Line Drops In From The Right
35.6M	JN	Line Drops In From The Left
42.8M	MH	Camera Enters Manhole S 56

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	154	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 56** End MH: **SMH 57** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 375mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



12.6M	MH	Camera Enters Manhole S 57

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	155	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 57** End MH: **SMH 50** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 375mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
7.0M	JN	Line Drops In From The Right
7.9M	JN	Line Drops In From The Left
11.4M	JN	Line Drops In From The Right
12.1M	JN	Line Drops In From The Right
15.1M	JN	Line Drops In From The Left
16.6M	MH	Camera Enters Manhole S 50



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	156	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 52** End MH: **SMH 54** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 225mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
3.0M	JN	Line Drops In From The Right
7.3M	MH	Camera Enters Manhole S 54



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth Hants
[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	157	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 52** End MH: **SMH 53** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.6M	JN	Line Drops In From The Right
14.6M	MH	Camera Enters Manhole S 53



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
P[redacted]


Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
23/04/25		**Dry**	**Mick**	158	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **Tye Lane** Place: **Walberton**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 52** End MH: **SMH 50** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 300mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
16.2M	JN	Line Drops In From The Left
16.7M	JN	Line Drops In From The Right
20.3M	JN	Line Drops InFrom The Right
21.1M	JN	Line Drops In From The Right
29.9M	JN	Line Drops In From The Right
44.9M	JN	Line Drops In From The Left
45.5M	JN	Line Drops In From The Right
51.2M	JN	Line Drops In From The Left
60.1M	JN	Line Drops In From The Left
64.7M	MH	Camera Enters Manhole S 50



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE. MAHOLES S49 & S 48 ARE CONCRETED OVER AND FULL OF DEBRIS SO UNABLE TO CLEAN OR CAMERA THESE LINES AROUND THESE MANHOLES INCLUDING THE GULLIES UNTILL THE MANHOLES HAVE BEEN EXPOSED

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features