

## **APPENDIX F**

### **PHOTOGRAPHIC LOG**

---

# PHOTOGRAPHIC LOG

*Former Gas Works, Ford Road, Arundel – Block A validation.*

|                                                                                        |                                |                                                                                     |
|----------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><br>1                                                              | <b>Date:</b><br><br>13/08/2025 |  |
|                                                                                        |                                |                                                                                     |
| <b>Description:</b><br><br>HP01 – garden validation<br>(membrane observed at the base) |                                |                                                                                     |

|                                              |            |                                                                                      |
|----------------------------------------------|------------|--------------------------------------------------------------------------------------|
| Photo No.                                    | Date:      |  |
| 2                                            | 13/08/2025 |                                                                                      |
|                                              |            |                                                                                      |
| Description:                                 |            |                                                                                      |
| HP01 – garden validation<br>(soil thickness) |            |                                                                                      |

|                                                          |                            |                                                                                    |
|----------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br>3                                    | <b>Date:</b><br>13/08/2025 |  |
| <b>Description:</b><br>HP01 – garden validation overview |                            |                                                                                    |

|                                                                                              |                                |                                                                                      |
|----------------------------------------------------------------------------------------------|--------------------------------|--------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><br>4                                                                    | <b>Date:</b><br><br>13/08/2025 |  |
|                                                                                              |                                |                                                                                      |
| <b>Description:</b><br><br>HP01 – garden validation,<br>orange membrane<br>observed at base. |                                |                                                                                      |

|                                                                     |                     |                                                                                    |
|---------------------------------------------------------------------|---------------------|------------------------------------------------------------------------------------|
| Photo No.<br>5                                                      | Date:<br>13/08/2025 |  |
|                                                                     |                     |                                                                                    |
| <b>Description:</b><br>HP02 – garden validation<br>(soil thickness) |                     |                                                                                    |

|                                                                         |                                |                                                                                      |
|-------------------------------------------------------------------------|--------------------------------|--------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><br>6                                               | <b>Date:</b><br><br>13/08/2025 |  |
|                                                                         |                                |                                                                                      |
| <b>Description:</b><br>HP02 – garden validation<br>(pit base and depth) |                                |                                                                                      |

|                                                                   |                            |                                                                                    |
|-------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br>7                                             | <b>Date:</b><br>13/08/2025 |  |
| <b>Description:</b><br>HP02 – garden validation location overview |                            |                                                                                    |

|                                          |                     |                                                                                      |
|------------------------------------------|---------------------|--------------------------------------------------------------------------------------|
| Photo No.<br>8                           | Date:<br>13/08/2025 |  |
| Description:<br>HP02 – garden validation |                     |                                                                                      |

|                                                                                                |                                |                                                                                    |
|------------------------------------------------------------------------------------------------|--------------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><br>9                                                                      | <b>Date:</b><br><br>13/08/2025 |  |
|                                                                                                |                                |                                                                                    |
| <b>Description:</b><br><br>HP03 – garden validation<br>(pit depth and membrane<br>at the base) |                                |                                                                                    |


|                                                                     |                            |                                                                                      |
|---------------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><b>10</b>                                       | <b>Date:</b><br>13/08/2025 |  |
|                                                                     |                            |                                                                                      |
| <b>Description:</b><br>HP03 – garden validation<br>(excavated soil) |                            |                                                                                      |

|                                                                     |                            |                                                                                    |
|---------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br>11                                              | <b>Date:</b><br>13/08/2025 |  |
|                                                                     |                            |                                                                                    |
| <b>Description:</b><br>HP03 – garden validation<br>(excavated soil) |                            |                                                                                    |

|                                              |            |                                                                                      |
|----------------------------------------------|------------|--------------------------------------------------------------------------------------|
| Photo No.                                    | Date:      |  |
| 12                                           | 13/08/2025 |                                                                                      |
| Description:                                 |            |                                                                                      |
| HP03 – garden validation<br>(soil thickness) |            |                                                                                      |

|                                                           |                            |                                                                                    |
|-----------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><b>13</b>                             | <b>Date:</b><br>13/08/2025 |  |
|                                                           |                            |                                                                                    |
| <b>Description:</b><br>HP03 – Garden validation overview. |                            |                                                                                    |

|                                                                                                                    |                                |                                                                                      |
|--------------------------------------------------------------------------------------------------------------------|--------------------------------|--------------------------------------------------------------------------------------|
| <b>Photo no.</b><br><br>14                                                                                         | <b>Date:</b><br><br>22/08/2025 |  |
| Facing northwest from the central east of the site                                                                 |                                |                                                                                      |
| <b>Description:</b><br><br>Block A – public open space (landscape validation area). At locations of HP04 and HP05. |                                |                                                                                      |

|                                                                                 |                            |                                                                                    |
|---------------------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><b>15</b>                                                   | <b>Date:</b><br>22/08/2025 |  |
| Facing west along the northern site boundary from the site entrance.            |                            |                                                                                    |
| <b>Description:</b><br>Block A – public open space (landscape validation area). |                            |                                                                                    |

|                                                                                                            |                            |                                                                                      |
|------------------------------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------|
| <b>Photo No.</b><br><b>16</b>                                                                              | <b>Date:</b><br>22/08/2025 |  |
| Facing northwest from the central east of the site                                                         |                            |                                                                                      |
| <b>Description:</b><br>Block A – public open space (landscape validation area). Showing topsoil placement. |                            |                                                                                      |

|                                                            |                            |                                                                                    |
|------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------|
| <b>Photo No.</b><br>17                                     | <b>Date:</b><br>22/08/2025 |  |
|                                                            |                            |                                                                                    |
| <b>Description:</b><br>View of imported topsoil stockpile. |                            |                                                                                    |

|                                                                                     |                                |
|-------------------------------------------------------------------------------------|--------------------------------|
| <b>Photo No.</b><br><br>18                                                          | <b>Date:</b><br><br>22/08/2025 |
| Facing north along the western site boundary.                                       |                                |
| <b>Description:</b><br><br>Block A – public open space (landscape validation area). |                                |



|                                                                                 |                            |
|---------------------------------------------------------------------------------|----------------------------|
| <b>Photo No.</b><br><b>19</b>                                                   | <b>Date:</b><br>22/08/2025 |
| Facing north east from the south west corner of Block A.                        |                            |
| <b>Description:</b><br>Block A – public open space (landscape validation area). |                            |

A photograph showing a large, flat, brownish-grey area, likely a landscape validation area, situated in front of a red brick building. The building has several windows with white frames. A concrete path leads into the area from the bottom right. The shadow of the person taking the photo is visible on the path in the foreground.

|                                                            |                            |                                                                                      |
|------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------|
| <b>Photo No.</b><br>7                                      | <b>Date:</b><br>22/08/2025 |  |
|                                                            |                            |                                                                                      |
| <b>Description:</b><br>View of imported subsoil stockpile. |                            |                                                                                      |