

HEADWALL PHOTOGRAPHS

FOR

DISCHARGE OF SURFACE WATER PLANNING CONDITION

AT

STANWYCK
NORTHFIELDS LANE
WESTERGATE
CHICHESTER
PO20 3UH

March 2026



Evidence of test pit depth and pit showing strata



Pit showing 25% and 75% levels for measuring water absorption and image of the pit during the test



Hole for the headwall



Base sandbags in place, secured with reinforcement bars



View of the headwall and ditch and completed headwall backfilled