


NIAN CHAMBERS
CHWOOD NALK - ALDWICK,

REFERENCE T.3.



ANGLE OF INCLINE
APPROX 14°

--- DOTTED AREA
MARKS EROSION.

 DARK AREA
MARKS WHERE DECAY