

APPENDIX THIRTEEN

AUGUST 2025

54, PINEHURST PARK

IMAGE OF A RAISED BRICK NEAR THE
SIDE GATE

- ① The arrow indicates the top right corner of the brick where a new poplar tree shoot/sucker was growing and lifting the brick which began to form a trip hazard.
- ② A dose of weedkiller has killed the shoot/sucker off and the brick has sunk back down, but not quite to ^{the} level of the other bricks on the driveway.