

54. PINEHURST PARK

CLOSE UP IMAGE OF TWO POPLAR SHOOTS/SUCKERS
UNDER THE OUTSIDE TAP.



- ① Close up image to support Appendix Fifteen of the two poplar tree shoots/suckers under the outside tap where the rear patio paving slabs meet the outside brick of the house.