






NORTH EAST

BROKEN LINE INDICATES
RECONSTRUCTED GARDAGE AT FRONT
OF NORTH EAST ELEVATION

SOUTH WEST

NORTH EAST ELEVATION FROM 4000
AND THIS CAN BE WEST ELEVATION



SOUTH EAST

WITH PROPOSED RECONSTRUCTED GARDAGE

NORTH WEST