
[illegible]

| PAS 128 : 2014     |               |                                                                                                                                   |
|--------------------|---------------|-----------------------------------------------------------------------------------------------------------------------------------|
| SURVEY CATEGORY    | QUALITY LEVEL | CRITERIA USED IN THE DETERMINATION OF QUALITY LEVEL                                                                               |
| TYPE B - DETECTION | CL-B1         | <p>UTILITY SEGMENT WHICH IS SUSPECTED TO EXIST BUT HAS NOT BEEN VERIFIED BY AN INDEPENDENT PARTY</p> <p>NO DETECTION RESULTS</p>  |
|                    | CL-B3         | <p>PORTABLE UTILITY DETECTED BY ONE OF THE GEOPHYSICAL TECHNIQUES</p> <p>NO OR SPW DETECTION WITH LIMITED CONFIDENCE AS SEPTA</p> |
|                    | CL-B2         | <p>PORTABLE UTILITY DETECTED BY TWO OF THE GEOPHYSICAL TECHNIQUES</p> <p>NO OR SPW DETECTION WITH CONFIDENCE AS SEPTA</p>         |
|                    | CL-B4         | <p>PORTABLE UTILITY DETECTED BY THREE OF THE GEOPHYSICAL TECHNIQUES</p> <p>NO OR SPW DETECTION WITH CONFIDENCE AS SEPTA</p>       |
|                    | CL-B5         | <p>PORTABLE UTILITY DETECTED BY FOUR OF THE GEOPHYSICAL TECHNIQUES</p> <p>NO OR SPW DETECTION WITH CONFIDENCE AS SEPTA</p>        |



|      |                                       |     |                    |
|------|---------------------------------------|-----|--------------------|
| AR   | ASSUMED ROUTE                         | PE  | POLYETHYLENE       |
| BD   | BACKDROP                              | PIR | PIPER RISER        |
| BL   | BLOCKED                               | PVC | POLYVINYL CHLORIDE |
| BTIC | BUILDING INSULATION DETECTION CHAMBER | R   | ROOFING            |
| CI   | CAST IRON                             | RWP | RAIN WATER PIPE    |
| CL   | CLOSER LEVEL                          | ST  | STOP TAP           |
| CP   | CABLE PIT                             | SV  | STOP VALVE         |
| CR   | CABLE RISER                           | SVL | SOFT VENT PIPE     |
| EM   | EARTH MAT                             | TFR | TAKEN FROM RECORD  |
| EF   | ELECTRICITY POLE                      | TL  | TRAFFIC LIGHTS     |
| EOT  | END OF TRACE                          | TE  | TELEGRAPH POLE     |
| EP   | END OF POINT                          | UTL | UNABLE TO LOCATE   |
| FI   | FIRE HYDRANT                          | UTR | UNABLE TO RAISE    |
| GV   | GAS VALVE                             | UTS | UNABLE TO SURVEY   |
| GJ   | GULLY                                 | UTT | UNABLE TO TRACE    |
| IG   | INSULATION CHAMBER                    | V   | VENT PIPE          |
| I    | INVERT LEVEL                          | VR  | VAPOUR RECOVERY    |
| LP   | LAMP POST                             | W   | WATER LEVEL        |
| M    | MANHOLE                               | WM  | WATER METER        |
| NPV  | NOT VISIBLY                           | WSP | WASHOUT WATER PIPE |
| OSA  | OSHA SURVEY AREA                      | WWP | WASTE WATER PIPE   |

|  |                                     |
|--|-------------------------------------|
|  | BOREHOLE (BH)                       |
|  | BOREHOLE PROPOSED LOCATION          |
|  | BT                                  |
|  | TV - CABLE TV                       |
|  | CATV - CABLE TV                     |
|  | COMM - COMMUNICATIONS               |
|  | EARTH - EMPTY DUCT                  |
|  | FIBRE OPTICS                        |
|  | GAUGES - GAUGES                     |
|  | TRAFFIC SIGNALS                     |
|  | ELECTRIC HV - ELECTRIC HIGH VOLTAGE |
|  | FUEL LINES                          |
|  | OFFSET FILL                         |
|  | VENT                                |
|  | FUEL PIPE                           |
|  | GAS                                 |
|  | WATER                               |
|  | OIL                                 |
|  | COMPRESSED AIR                      |
|  | RADAR TOWER                         |
|  | UNKNOWN TRAFFIC                     |
|  | DRAINAGE FOUL                       |
|  | DRAINAGE SURFACE                    |
|  | OUTFALL                             |
|  | RISING MAIN                         |
|  | END OF TRAFFIC SURVEYED AREA        |

**groundscan**  
Unit 4, The Old Glove Factory,  
Bristol Road,  
Sherborne,  
Dorset DT9 4HP  
Tel: 01935 389123  
Website: [www.groundscan.co.uk](http://www.groundscan.co.uk)  
Company Reg: 07847795

|                      |                                 |            |  |
|----------------------|---------------------------------|------------|--|
| Client:              | McCarthy & Stone                |            |  |
| Survey Location:     | Chandlers BMW Site<br>Angmering |            |  |
| Survey type: Utility | Scale:                          | 1:200@A0   |  |
| Drawing ref: 2253    | Sheet:                          | 1 of 1     |  |
| Drawn/QA: A.B.       | Date:                           | 06-10-2020 |  |
|                      | Issue:                          | 1          |  |

