

PHOTOGRAPHIC LOG	
Site Location: Cresswell Park, Angmering	
Photo No. 11	
Date: 05/09/2019	
Subsoil from Plot 255 front garden.	
Photo No. 12	
Date: 05/09/2019	
Detailed view of Plot 255 front garden.	

PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No. 13	
Date: 05/09/2019	
Detailed view of capping layer in plot 255 front garden.	

Photo No. 14	
Date: 27/08/2019	
Overview of Plot 255 rear garden.	

PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No.
15

Date:
27/08/2019

Detailed view
of capping
layer in Plot
255 rear
garden.




Photo No.
16

Date:
27/08/2019

Detailed view
of Plot 255
rear garden.



PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No.
17

Date:
05/09/2019

Overview of
Plot 256 front
garden.



Photo No.
18

Date:
05/09/2019


Arisings from
Plot 256 front
garden.



PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No. 19	
Date: 05/09/2019	
Detailed view of capping layer in Plot 256 front garden.	

Photo No. 20	
Date: 05/09/2019	
Detailed view of Plot 256 front garden.	

PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No.
21

Date:
27/08/2019

Overview of
Plot 256 rear
garden.



Photo No.
22

Date:
27/08/2019

Detailed view
of Plot 256
rear garden.



PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No.
23

Date:
27/08/2019

Detailed view
of capping
layer in Plot
256 rear
garden.




Photo No.
24

Date:
05/09/2019

Overview of
Plot 257 front
garden.



PHOTOGRAPHIC LOG

Site Location: Cresswell Park, Angmering

Photo No. 25	
Date: 05/09/2019	
Detailed view of capping layer in Plot 257 front garden.	
Photo No. 26	
Date: 05/09/2019	
Detailed view of Plot 257 front garden.	

PHOTOGRAPHIC LOG	
Site Location: Cresswell Park, Angmering	
Photo No. 27	
Date: 05/09/2019	
Topsoil front Plot 257 front garden.	
Photo No. 28	
Date: 05/09/2019	
Subsoil front Plot 257 front garden.	