



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP1 (test 1)

Dimensions (LxWxH) (2.0x0.6x2.5)

Gravel filled to 1.0mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.65
1	2.04
2	2.23
3	2.34
4	2.42
	700 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP1 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.48
1	2.01
2	2.18
3	2.30
4	2.41
	1000 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP1 (test 3)

Test Time (Minutes)	Water Level (Metres)
0.1	1.50
1	1.99
2	2.21
3	2.31
4	2.34
5	2.37
	1000 litres used