



**Site Address: Manor Nursery, Angmering**

**Client: The Civil Engineering Practice**

**Date of Test: 20/06/19**

**BRE 365 Soakage Test Results**

**Hole ID.....TP2 (test 1)**

**Dimensions (LxWxH) (2.1x0.6x2.5)**

**Gravel filled to 0.8mbql**

| Test Time (Minutes) | Water Level (Metres) |
|---------------------|----------------------|
| 0.1                 | 1.46                 |
| 1                   | 2.02                 |
| 2                   | 2.34                 |
| 3                   | 2.45                 |
| 4                   | 2.50                 |
|                     |                      |
|                     | 1000 litres used     |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |



**Site Address: Manor Nursery, Angmering**

**Client: The Civil Engineering Practice**

**Date of Test: 21/06/19**

**BRE 365 Soakage Test Results**

**Hole ID.....TP2 (test 2)**

| Test Time (Minutes) | Water Level (Metres) |
|---------------------|----------------------|
| 0.1                 | 1.23                 |
| 1                   | 2.05                 |
| 2                   | 2.30                 |
| 3                   | 2.43                 |
| 4                   | 2.50                 |
|                     |                      |
|                     | 1100 litres used     |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |



**Site Address: Manor Nursery, Angmering**

**Client: The Civil Engineering Practice**

**Date of Test: 21/06/19**

**BRE 365 Soakage Test Results**

**Hole ID.....TP2 (test 3)**

| Test Time (Minutes) | Water Level (Metres) |
|---------------------|----------------------|
| 0.1                 | 1.24                 |
| 1                   | 1.83                 |
| 2                   | 2.20                 |
| 3                   | 2.35                 |
| 4                   | 2.44                 |
| 5                   | 2.50                 |
|                     |                      |
|                     | 1000 litres used     |
|                     |                      |
|                     |                      |
|                     |                      |
|                     |                      |