



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP5 (test 1)

Dimensions (LxWxH) (2.1x0.6x2.5)

Gravel filled to 0.75mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.60
1	1.95
2	2.12
3	2.23
4	2.31
5	2.37
6	2.43
7	2.47
8	2.5
	600 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP5 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.66
1	1.99
2	2.15
3	2.25
4	2.31
5	2.39
6	2.44
7	2.48
8	2.50
	1000 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP5 (test 3)

Test Time (Minutes)	Water Level (Metres)
0.1	1.57
1	1.94
2	2.12
3	2.23
4	2.31
5	2.36
6	2.41
7	2.46
8	2.50
	1000 litres used