



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 24/06/19

BRE 365 Soakage Test Results

Hole ID.....TP7 (test 1)

Dimensions (LxWxH) (2.1x0.6x2.1)

Gravel filled to 0.5mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.42
1	1.77
2	1.93
3	2.10
	1000 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 24/06/19

BRE 365 Soakage Test Results

Hole ID.....TP7 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.46
1	1.76
2	1.92
3	2.10
	1200 litres used



Date of Test: 24/06/19

Hole ID.....TP7 (test 3)

[illegible]