



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP2 (test 1)

Dimensions (LxWxH) (2.1x0.6x2.5)

Gravel filled to 0.8mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.46
1	2.02
2	2.34
3	2.45
4	2.50
	1000 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP2 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.23
1	2.05
2	2.30
3	2.43
4	2.50
	1100 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP2 (test 3)

Test Time (Minutes)	Water Level (Metres)
0.1	1.24
1	1.83
2	2.20
3	2.35
4	2.44
5	2.50
	1000 litres used