



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP3 (test 1)

Dimensions (LxWxH) (2.1x0.6x2.5)

Gravel filled to 0.8mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.50
1	1.97
2	2.23
3	2.48
	600 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP3 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.47
1	1.78
2	2.07
3	2.38
4	2.50
	700 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 20/06/19

BRE 365 Soakage Test Results

Hole ID.....TP3 (test 3)

Test Time (Minutes)	Water Level (Metres)
0.1	1.69
1	1.98
2	2.30
3	2.50
	900 litres used