


GD Group Drainage Report Update

SWALLOW GATE

Thursday, 13 January 2022

Prepared For GD Concepts

27 Issues Identified




Shane Noone

GD Homes




S4

Pipes cut back. Pipes plugged and chamber cleaned.




S4

Pipes cut back and pipes plugged. Chamber cleaned.




S2

Pipes cut back. Pipes plugged and chamber cleaned.




S2

Pipes cut back. Pipes plugged and chamber cleaned.




S2

Pipes cut back. Pipes plugged and chamber cleaned.




S1

Pipes cut back. Pipes plugged and chamber cleaned.



S1

Pipes cut back. Pipes plugged and chamber cleaned.




S1

Pipes cut back. Pipes plugged and chamber cleaned.




S5

Pipes cut back. Pipes plugged and chamber cleaned.



S5

Pipes cut back. Pipes plugged and chamber cleaned.




S5

Pipes cut back. Pipes plugged and chamber cleaned.



S6

Pipes cut back. Pipes plugged and chamber cleaned.




S6

Pipes cut back. Pipes plugged and chamber cleaned.




S6

Pipes cut back. Pipes plugged and chamber cleaned.




S6




S8

Pipes cut back. Pipes plugged and chamber cleaned.




S8

Pipes cut back. Pipes plugged and chamber cleaned.




S8

Pipes cut back. Pipes plugged and chamber cleaned.




S9

Pipes cut back. Pipes plugged and chamber cleaned.




S9

Pipes cut back. Pipes plugged and chamber cleaned.




S11

Pipes cut back. Pipes plugged and chamber cleaned.




S11

Pipes cut back. Pipes plugged and chamber cleaned.




S10

Pipes cut back. Pipes plugged and chamber cleaned.




S10




S10

Pipes cut back. Pipes plugged and chamber cleaned.



S3

Pipes cut back. Pipes plugged and chamber cleaned.



S3

Pipes cut back. Pipes plugged and chamber cleaned.
