





















Plate 1: View of site from entrance looking south.



Plate 2: View of site from south west corner looking north east. Shows extensive hard standing and pea gravel surface covering west of the site.



Plate 3: View of northern end of nursery area viewed from eastern boundary. Shows extensive concrete ground surface cover.



Plate 4: South east corner of the site, viewed from corner of the site looking north. Shows scrub and rough vegetation cover.



Plate 5: View of boundary field to the south east corner of the site looking south west.



Plate 6: Southern boundary of the site.



Plate 7: View of north boundary of site from the north
[elevated location of foot bridge across A280]



Plate 8: View of area to the immediate north east of
the site



Plate 9: Site access route looking towards the west



Plate 10: Western boundary looking south.