



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP4 (test 1)

Dimensions (LxWxH) (2.1x0.6x2.6)

Gravel filled to 0.7mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.30
1	1.77
2	2.13
3	2.42
4	2.60
	700 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP4 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.28
1	1.78
2	2.11
3	2.39
4	2.60
	500 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 21/06/19

BRE 365 Soakage Test Results

Hole ID.....TP4 (test 3)

Test Time (Minutes)	Water Level (Metres)
0.1	1.11
1	1.38
2	1.76
3	2.08
4	2.35
5	2.59
	400 litres used