



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 24/06/19

BRE 365 Soakage Test Results

Hole ID.....TP6 (test 1)

Dimensions (LxWxH) (1.9x0.6x2.5)

Gravel filled to 0.5mbql

Test Time (Minutes)	Water Level (Metres)
0.1	1.51
1	2.08
2	2.20
3	2.28
4	2.31
5	2.34
6	2.36
7	2.38
10	2.40
15	2.45
20	2.50
	1000 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 24/06/19

BRE 365 Soakage Test Results

Hole ID.....TP6 (test 2)

Test Time (Minutes)	Water Level (Metres)
0.1	1.56
1	2.13
2	2.24
3	2.29
4	2.31
5	2.34
6	2.37
7	2.39
8	2.40
10	2.42
15	2.47
20	2.50
	1100 litres used



Site Address: Manor Nursery, Angmering

Client: The Civil Engineering Practice

Date of Test: 24/06/19

BRE 365 Soakage Test Results

Hole ID.....TP6 (test 3)

Test Time (Minutes)	Water Level (Metres)
0.1	1.64
1	2.01
2	2.17
3	2.24
4	2.28
5	2.31
6	2.33
7	2.35
8	2.37
9	2.39
10	2.41
15	2.44
20	2.47
25	2.50
	1000 litres used