

security fencing located along boundary

SITE COMPOUND AREA

Existing security fence remains during construction

MATERIALS COMPOUND


	Bin Storage
	Shed
	Rumble Strip
	600mm Flint/Brick
	1800mm Brick
	Post and Rail
	Proposed Trees
	Existing Trees
	Removed Trees
	Site Boundary

- A. Repositioned garage and amended house type G2.
- B. Added more trees and landscaping
- C. Minor amendment to house type A, bays added for passive surveillance
- D. Wider pedestrian footpath
- E. Extent of Acoustic fence
- F. Redesign plot 32 to a C3 unit

A280

P5	10.08.18	Minor amendments	EM	MN
P4	07.08.18	Minor amendments	EM	MN
P3	03.08.18	Minor amendments to house types	EM	MN
P2	19.03.18	minor amendment	MN	PF
P1	01.03.18	ISSUED FOR PLANNING	CA	MN

Rev	Date	Revision Details	Dr	Ch
-----	------	------------------	----	----



London: 76 Great Suffolk Street
London, SE1 0BL

T 0207 928 2773 E London@ecearchitecture.com

Sussex: Brookling Chambers, 11 Goring Road
Worthing, West Sussex, BN12 4AP

T 01903 248777 E sussex@ecearchitecture.com

Bristol: Westworks, Colston Tower
Colston Street, Bristol, BS1 4XE

T 0117 214 1101 E bristol@eceworksworks.com

ECE Architecture

www.ecearchitecture.com

CAD Plot date: 13/08/2018 - 16:22:27 8345 site layout.dwg

© FCF Architecture Limited. No dimensions to be scaled from drawing except for the purposes of Planning Applications. The contractor should check all dimensions on site. It is the contractors responsibility to ensure compliance with Building Regulations.