Application to fell yew tree **14 Feb 2022**



<— The tree as seen from the road. It has been pruned in order to keep it off the thatched roof, giving it a lop-sided appearance.

The yew tree has been a prominent backdrop to our house for at least a hundred years.



The leaning wall.



Narrow gap between our house and the wall. The yew tree is 500mm away from the wall, on the other side.





This repair was done about 3 years ago, but within a year, the mortar had cracked again.

The wet area is marked (everything below the curved white line), and indicates the ground level on the other side of the wall. This area can get very wet, depending on the weather, and is destroying the structure of the wall.



Location plan showing positions of yew tree and wall.

