

Tree schedule				
Tree No	Species	Category	RPA Radius	Tree Works
T1	Plum	C	7.2	Fell
H2	Thorn	C	4.8	Fell (part)
T4	Laurel	C	2.4	Fell
T5	Cypress	C	7.2	Fell
T6	Variegated holly	C	3.6	Fell
T7	Holly	C	3.6	Fell
T8	Cypress	C	3.6	Fell
T9	Pittosporum	C	3.6	Fell
T10	Cypress	C	4.0	Fell
T11	Cypress stump	U	4.8	Fell for management
T12	Barberry	C	7.2	Fell
T13	Willow	C	3.6	Fell
T15	Willow	C	3.6	Fell
T16	Willow	C	3.6	Fell
T17	Cypress	U	7.2	Fell for management
H18	Privet, thorn	C	4.8	Fell (part)
T19	Ash	C	15.0	-
T20	Monterey cypress	C	15.0	Fell
G21	Thorn, willow	C	7.2	Fell
T22	Poplar	C	3.0	-
T23	Oak	C	3.6	-
T24	Willow	C	7.2	Fell
G25	Apple, laurel, palm	C	3.0	Fell
G26	Apple	C	3.6	Fell

TX

BS category C

Trees of low quality

TX

BS category U

Trees unsuitable for retention

TX

Trees to be removed

Proposed layout

Estimated tree positions not included on original land survey

Construction exclusion zone (CEZ) to be protected by fencing and/or ground protection

Tree protection plan

Location of trees, categorisation & protection/management proposals at The Lillies Caravan Park, Yapton Road, Barnham

Permission is granted to scale from this drawing for Local Authority Planning Approval purposes relating to tree protection measures only. Where applicable this drawing is to be read in conjunction with the arboricultural report. This drawing is the copyright of Barrell Tree Consultancy 2015. ©

This drawing to be reproduced in colour only.

Barrell Plan Ref: 15192-BT1

Provided Plan Refs: 15708cv-01 & 15708cv-02 & 409.200_Site Plan

barrell

TREE CONSULTANCY

Field House, Fordingbridge Business Park,
Ashford Road, Fordingbridge SP6 1BT
Tel: 01425 651470 Fax: 01425 653449
www.barrelltrees.co.uk

