


Column Foundation and Reinstatement Details

G630 Good: Compact, well graded sand and gravel, hard clay, well graded fine and coarse sand, decomposed granite rock and soil. Good material should be well drained and in locations where water will not stand.

G390 Average: Compact fine sand, medium clay, compact, well drained sandy loam, loose course sand and gravel. Average soils should be drained sufficiently well that water does not stand on surface.

G230 Poor: Soft clay, clay loam, poorly compacted sand, clays containing a large amount of silt and vegetable matter, and made ground. Poor soils will normally be wet and have poor drainage.



1. Contractors to check dimensions and notify any discrepancies or errors to the company immediately.
2. Work to figured dimensions only and to be checked before commencement of work on site.
3. Do not scale off this drawing.
4. All dimensions in millimetres unless otherwise stated.
5. For further details of external cabinet and base, refer to drawing number C-0000-004.



ParkingEye
car park solutions

Office Contact:
40 Eaton Avenue, Matrix Park
Buckshaw Village, Chorley,
Lancashire, PR7 7NA

Tel: 01772 450 970
Fax: 01772 450 979
Email: ops.civils@parkingeye.co.uk

Client: ParkingEye

Project:	Standard Details
----------	------------------

Title: ANPR Lighting Column
General Arrangement

© ParkingEye Limited. The copyright and other intellectual property rights in this drawing and the works depicted are the property of ParkingEye Limited and/or its licensors. It may not be copied, reproduced or altered in any way (in whole or in part) without the express written authorisation of ParkingEye Limited. All rights reserved