

Drainage works 31 Aldwick Road

From Abacus Drain Repairs <

Date 2021-05-25 18:01


New soil stack and underground repairs made to drainage pipe after complete collapse of drain.

Upon using CCTV camera to view underground drainage we have found that nearby tree is causing significant damage to the underground clay drainage. Damage will only worsen over time till tree/action is made.

regards, Darren

Kind Regards

Abacus Drain Repairs



Find us on
Checkatrade.com
and see what our customers say.