

2-4 Waterloo Square Bognor Regis PO21 1SU

Design & Access Statement (DAS) (18-1236)
APPENDIX A

Issue Status:

Revision	Date	Description
-	23 Jul 18	Issued in support of Application for Demolition in a Conservation Area

Site Photographic Record taken May - July 2018

(This is a small selection of photographs for 2-4 Waterloo Square)



P1 - Waterloo Square View



P2 - View of Gym Structure (First Floor)



P3 - Rear First Floor Infill



P4 – Norfolk Street (Gym at 1st Floor)



P5 – Norfolk Street (Gym at 1st Floor)



P6 – Norfolk Street



P7 – Access to 2nd Floor Flats Norfolk Street



P8 – Access to 1st Floor Flats Norfolk Street



P9 – Norfolk Street View of Southern Elevation



P10 - Previous demolished site Area



P11 – Cracking to 2nd Floor rear elevation



P12 – Internal Beam supporting Gym at 1st Floor
(note delamination of Bottom Flange)



P13 – External beam (RHS) No. 2 Waterloo Sq Elevation
(note delamination of Bottom Flange)



P14 –Abandoned internal works No. 4 Waterloo Sq.



P15 –Abandoned internal works No. 2 Waterloo Sq.