

### **APPENDIX 3: Photographs**



Front Elevation



Front Bay



Building in Context



View of side passage from Steyne Gardens/ Flat 6 External entrance




UPVC flat 1 window to be replaced



Existing Timber windows to be restored



Rear bin store



Stair and hall with entrance to flat 1