

Photographs of the Listed Buildings and their setting

Site access and setting



Site access off Upper Bognor Road



Existing access road looking back towards Upper Bognor Road

Photographs of the Listed Buildings and their setting



Existing boundary wall to north of site in rat-tap bond red brick.
Opening to be infilled with matching brickwork.



Existing barrier to access road and area of grass to west of 71 Upper Bognor Road

Photographs of the Listed Buildings and their setting



Grass area to west of 71 Upper Bognor Road



View from access road towards existing boundary wall of courtyard

Photographs of the Listed Buildings and their setting



Current setting to Charlotte House

