

The White Tower

16 Aldwick Road, Bognor Regis, PO21 2LP



Roof

Wooden ceiling has rotted and the roofing felt disintegrated. New wood support beams and sheet wood will be fixed to beams

Outside

Windows have rusted and will be replaced with the same style. Wood cladding on walls will be replaced with cladding of the same profile as original



Inside

Picture shows inside of Summer House with rotted walls and ceiling

