



IMAGE 1



IMAGE 2



IMAGE 3



IMAGE 4



IMAGE 5



IMAGE 6



IMAGE 7



IMAGE 8



IMAGE 9



IMAGE 10



IMAGE 11



IMAGE 12



IMAGE 13




IMAGE 14



IMAGE 15

ALL BOUNDARY FLINT WALLS AND FLINT GARDEN WALLS TO BE REPAIRED AS REQUIRED.
SEE SPECIFICATION FOR FURTHER DETAILS



Notes:
All dimensions must be checked/verified on site.
No responsibility or liability is accepted for CDM unless otherwise agreed in writing.

Date	Revisions

Client
Mr G.Love

Job Title
Climping Mill Project

Drawing Title
**Existing Site layout :-
Extent of
Flint Boundary Garden
Walls**

**Architectural & Historic
Buildings Consultants**
Mob: 07909 544908
Email: info@dgc-consultants.com
Web: www.dgc-consultants.com

Date 18/06/2018 Drawn By GSB
Scale 1:200 @ A1

Drg. No.
DGC-21815/MS01

Rev.

© Copyright 841 x 594mm A1