

PHOTOGRAPHIC APPENDICES III

in connection with

Clymping Mill, Littlehampton

Mill Cottage, Mill Thatch, Outbuilding, Structures within the Curtilage and Views and Vistas



INSTITUTE · OF · HISTORIC ·
BUILDING · CONSERVATION

REF: DGC21732

Date of Issue: 15/08/2017



Registered Office:
The Spinney St Marys Lane Bexhill on
Sea E. Sussex TN39 5JE

DGC (Historic Buildings) Consultants
Limited

Registered in England and Wales No. 740584
VAT Reg No. 014 8050 18

Mill Cottage (Building C on drawings)


North Elevation



DSC03219: North Elevation, western end later extension to Historic core of Mill Cottage



DSC02752: Brick dressing denoting former opening to historic range Mill Cottage, North Elevation



DSC02753 DSC03216, DSC03214: General defects including missing roof tiles, lead flashings & cracks to flintwork Mill Cottage, North Elevation.


East Elevation



DSC03219: Historic range of Mill Cottage, East Elevation



DSC03229: Originally part of historic core, but largely rebuilt in 20th century denoted by the change of brick bond.



DSC03232: Change of brick bond denoting extent of rebuild, East Elevation Mill Cottage