

Enclosure ENCLOSURE 1

List of operatives

ALEX UDALL

BRETT HEMMINGS

PETER KOSZTY

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	yes
Viewing panels / CCTV Image clear & distinct	yes
Warning signs displayed	yes
Adequately weighted flaps with chains	yes
'H' type vacuum cleaner, in inner stage	yes
Water, hand sprayer, bucket & PDE	yes
Transit overalls, etc, stored in outer stage	yes
Airlocks/Baglocks clear and free from debris	yes
Dwyer Gauge (wg) AM:	0.2
Dwyer Gauge (wg) PM:	0.2

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 01/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM 500 PM
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 01/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #2 Vacuum serial number: 175023408	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #1 Vacuum serial number: 175022208	Retest date: 2019-04-18
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #3 Vacuum serial number: MVLP 092 SE	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 01/11/2018

Project number: SOU003492



Fixed scaffolds

FIXED SCAFFOLD #1	
No image	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 01/11/2018

Project number: SOU003492



Smoke test's

Name:	Simon	
Independent:	No	
Enclosure Ref No:		
Date:	November 01, 2018	
Time:	November 15, 2018 Hour 09:29	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 250	Gauge reading (PM): 240
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: Yes Directly connected comments:		
		
Comments: ALL OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492




Daily entry

Recorded at 02/11/2018

Weather AM: SUNNY 4°

Weather PM: SUNNY 11°

Day photos






ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492





Days Events

Time	Description	Image
02/11/2018 08:04:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN	No image
02/11/2018 08:19:00 AM	DCU POWERED UP AN ALL CHECKS COMPLETE AND RECORDED	
02/11/2018 08:30:00 AM	NPU READING	
02/11/2018 08:30:00 AM	ENCLOSURE CHECKS COMPLETE AND RECORDED	No image
02/11/2018 08:33:00 AM	DWYER GAUGE READING SHOWING GOOD NEGATIVE PRESSURE	
02/11/2018 08:34:00 AM	ENCLOSURE STRUCTURE LOOKING GOOD	
02/11/2018 08:38:00 AM	3X OPERATIVES HAVE CHANGED UP AND ENTERED THE ENCLOSURE TO CONTINUE WORKS TO HE HAND DIG	No image
02/11/2018 09:07:00 AM	1X OPERATIVE WILL BE AN OUTSIDE MAN AND ALSO BE RUNNING ANY WASTE THROUGHOUT THE SHIFT.	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492



02/11/2018 09:10:00 AM	WORKS CONTINUE WITHIN IN THE ENCLOSURE	No image
02/11/2018 10:22:00 AM	BRETT HAS STARTED TO DOUBLE BAG WASTE AND RUN IT TO THE SKIP	No image
02/11/2018 11:09:00 AM	HAND DIG MOVING ALONG NICELY	No image
02/11/2018 11:25:00 AM	EE ARE RUNNING PUMPS THROUGHOUT THE WORKS, ALSO ROUN THE WHOLE SITE AT VARIOUS TIMES.	No image
02/11/2018 11:43:00 AM	THE RHODAR TEAM HEAD TO THE SHOWER REAY FOR THERE LUNCH BREAK	No image
02/11/2018 12:57:00 PM	ALL RHODAR OPERATIVES HEAD BACK OUT ON SITE,	No image
02/11/2018 01:18:00 PM	TWO OPERATIVES CHANGE UP AND ENTER THE ENCLOSURE TO CARRY ON WITH THE HAD DIG. ONE OPERATIVE WILL CONTINUE WITH THE WASTE RUN.	No image
02/11/2018 01:19:00 PM	ALL AFTERNOON CHECKS HAVE BEEN CARRIED OUT AND ALL IS WELL THROUGHOUT THE WORKS	No image
02/11/2018 01:22:00 PM	NPU READING	
02/11/2018 01:24:00 PM	DYWER GAUGE READING	
02/11/2018 01:33:00 PM	BRETT HEMMINGS HAS SIGNED OUT AND LEFT SITE FOR THE DAY TO HEAD HOME TO WALES	No image
02/11/2018 01:34:00 PM	I HAVE REFIED THE HEADER TANK ON THE DCU, ALL CHECKS COMPLETE FOR THE AFTERNOON	No image
02/11/2018 02:32:00 PM	WASTE RUN COMPLETE FOR THE DAY AND THE SKIP HAS BEEN LOCKED.	No image
02/11/2018 02:47:00 PM	ALL OPERATIVES ARE NOW HEADING THROUGH THE DCU FOR END OF SHIFT	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492



02/11/2018 03:16:00 PM	ENCLOSURE HAS BEEN POWERED DOWN AND SEALED FOR THE WEEKEND. OPERATIVES HAVE FINISHED WITH THE DCU AND THIS IS ALSO LOCKED FOR THE WEEKEND.	No image
02/11/2018 03:33:00 PM	RHODAR SIGN OUT AND LEAVE SITE	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492



Enclosure ENCLOSURE 1

List of operatives

ALEX UDALL

BRETT HEMMINGS

PETER KOSZTY

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	yes
Viewing panels / CCTV Image clear & distinct	yes
Warning signs displayed	yes
Adequately weighted flaps with chains	yes
'H' type vacuum cleaner, in inner stage	yes
Water, hand sprayer, bucket & PDE	yes
Transit overalls, etc, stored in outer stage	yes
Airlocks/Baglocks clear and free from debris	yes
Dwyer Gauge (wg) AM:	0.2
Dwyer Gauge (wg) PM:	0.2

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM 490 PM 490
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #3	Retest date: 2019-02-02
Vacuum serial number: MVLP 092 SE	
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #1	Retest date: 2019-04-18
Vacuum serial number: 175022208	
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #2	Retest date: 2019-02-02
Vacuum serial number: 175023408	
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 02/11/2018

Project number: SOU003492



Fixed scaffolds


FIXED SCAFFOLD #1	
No image	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 250	Gauge reading (PM): 250
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: Yes Directly connected comments:		
		
Comments: ALL UP AND RUNNING OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492




Daily entry

Recorded at 05/11/2018

Weather AM: PARTLY CLOUDY 12°

Weather PM: SUNNY 16°

Day photos






ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492






Days Events

Time	Description	Image
05/11/2018 08:01:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN	No image
05/11/2018 08:09:00 AM	ALL OPERATIVES ARE BRIEFED ON THE DAYS WORK AHEAD. WE WILL BE CONTINUING WITH THE HAND DIG WITH IN THE ENCLOSURE, LOOKING TO GET OUR DEPTH OF 1 METER.	No image
05/11/2018 08:31:00 AM	DCU POWERED UP AND ALL CHECKS COMPLETE	 A photograph of a large, light-colored industrial unit, likely the DCU, with various pipes and cables connected to it.
05/11/2018 08:44:00 AM	ENCLOSURE CHECKS COMPLETE AND ALL IS WELL. THESE HAVE BEEN RECORDED	 A photograph showing the interior of an enclosure, with various mechanical components and wiring visible.
05/11/2018 08:46:00 AM	DWYER GAUGE READING SHOWING GOOD NEGATIVE PRESSURE	 A close-up photograph of a Dwyer pressure gauge with a coiled hose attached to it.
05/11/2018 08:46:00 AM	ENCLOSURE	 A photograph of the exterior of the enclosure, showing its metal structure and access points.

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492




05/11/2018 08:47:00 AM	INTEGRITY LOOKING GOOD AFTER BEING LEFT ALL WEEKEND	
05/11/2018 08:48:00 AM	NPU READING	
05/11/2018 08:51:00 AM	OPERATIVES MAKE A START CHANGING UP AND WILL ENTER THE ENCLOSURE VIA THE DIRECT CONNECTION AND CONTINUE WITH THE HAND DIG.	No image
05/11/2018 09:08:00 AM	WORKS NOW CONTINUE WITHIN THE ENCLOSURE, TWO OPERATIVES ON THE HAND DIG AND ONE BAGGING THE WASTE.	No image
05/11/2018 10:21:00 AM	TRANSIT AND WASTE ROUTES CLEANED AND MOPED THROUGH AS BEST AS POSSIBLE	
05/11/2018 10:22:00 AM	TRANSIT AND WASTE ROUTES CLEANED	
05/11/2018 01:09:00 PM	LUNCH COMPLETED AD RHODAR OPERATIVES HEAD BACK OUT ON SITE, 2X OPERATIVES CHANGE UP IN DCU AND ENTER ENCLOSURE AND THE THIRD OPERATIVE WILL START THE WASTE RUN.	No image
05/11/2018 01:11:00 PM	AFTERNOON CHECKS TO THE ENCLOSURE, PLANT AND DCU HAVE BEEN COMPLETED AND AL RECORDED	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492



05/11/2018 01:13:00 PM	DWYER GAUGE READING	
05/11/2018 01:13:00 PM	NPU READING	
05/11/2018 01:14:00 PM	GOOD FLAP MOVEMENT AND INTEGRITY TO THE BAG LOCK	
05/11/2018 01:17:00 PM	WORKS CONTINUE.	No image
05/11/2018 02:30:00 PM	STEVE MARSHALL HAS JUST LEFT SITE.	No image
05/11/2018 02:32:00 PM	WORKS MOVING ALONG OK, STILL HAVE SOME DEPTH TO REACH TOMORROW. WASTE RUN NEARLY COMPLETE FOR TODAY.	No image
05/11/2018 02:46:00 PM	WASE RUN COMPLETE AND THE OPERATIVES ARE CLEANING THROUGH THE BAGLOCK AND DIRECT CONNECTION	No image
05/11/2018 03:08:00 PM	OPERATIVES HAVE TIDIED THROUGH THE WORK AREA AND HAVE NOW STARTED O HEAD TO THE SHOWERS.	No image

Enclosure ENCLOSURE 1

List of operatives

ALEX UDALL

BRETT HEMMINGS

PETER KOSZTY

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	yes
Viewing panels / CCTV Image clear & distinct	yes
Warning signs displayed	yes
Adequately weighted flaps with chains	yes
'H' type vacuum cleaner, in inner stage	yes
Water, hand sprayer, bucket & PDE	yes
Transit overalls, etc, stored in outer stage	yes
Airlocks/Baglocks clear and free from debris	yes
Dwyer Gauge (wg) AM:	0.2
Dwyer Gauge (wg) PM:	0.2

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM 480 PM 490
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #1 Vacuum serial number: 175022208	Retest date: 2019-04-18
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #2 Vacuum serial number: 175023408	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes


VACUUM UNIT #3 Vacuum serial number: MVLP 092 SE	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 05/11/2018

Project number: SOU003492



Fixed scaffolds

FIXED SCAFFOLD #1	
	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	
yes	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 240	Gauge reading (PM): 240
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: Yes Directly connected comments:		
		
Comments: ALL UP AND RUNNING OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492



Daily entry

Recorded at 06/11/2018

Weather AM: PARTLY CLOUDY 13°

Weather PM: MOSTLY SUNNY 16°

Day photos





ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492






Days Events

Time	Description	Image
06/11/2018 08:02:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN	No image
06/11/2018 08:09:00 AM	GUYS ON SITE HAVE BEEN BRIEFED ON THE DAYS WORK AHEAD. WHICH WILL BE TO CONTINUE WITH THE HAND DIG UNTIL WE REACH OUR DEPTH.	No image
06/11/2018 08:20:00 AM	DCU HAS BEEN POWERED UP AND ALL CHECKS COMPLETE	
06/11/2018 08:28:00 AM	ENCLOSURE HAS ALSO BEEN UNSEALED AND ALL POWERED UP.. CHECKS COMPLETE AND RECORDED.	No image
06/11/2018 08:38:00 AM	PICTURE	
06/11/2018 08:38:00 AM	BAGLOCK AND DIRECT CONNECTION INTEGRITY LOOCKING GOOD AS IS THE FLAP MOVEMENT	No image
06/11/2018 08:40:00 AM	NPU SHOWING GOOD READING	
06/11/2018 08:44:00 AM	DYWER GAUGE READING SHOWING GOOD NEGATIVE PRESSURE THROUGHOUT THE ENCLOSURE	No image
06/11/2018 08:47:00 AM	3X OPERATIVES MAKE A START CHANGING UP IN THE DCU READY TO ENTER THE ENCLOSURE AND CONTINUE OUR WORKS.	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492




06/11/2018 10:17:00 AM	WE ARE GETTING NEAR OUR DEPTH NOW AND I BELIEVE BY THE END OF THE DAY WE WILL HAVE COMPLETED THE EARTH DIG.	No image
06/11/2018 11:01:00 AM	NEW FILTER PASSED IN FOR THE NPU.	No image
06/11/2018 11:23:00 AM	WASTE RUN WILL START THIS AFTERNOON AFTER LUNCH.	No image
06/11/2018 11:54:00 AM	OPERATIVES START TO LEAVE THE ENCLOSURE AND HEAD TO THE SHOWER READY FOR LUNCH	No image
06/11/2018 01:00:00 PM	RHODAR BACK ON SITE AND THE OPERATIVES ARE NOW CHANGING UP TO RE-ENTER THE ENCLOSURE AND CONTINUE WITH WORKS, ONE OPERATIVE WILL WORK O THE OUTSIDE STARTING THE WASTE RUN FOR THE DAY.	No image
06/11/2018 01:06:00 PM	ALL AFTERNOON CHECKS HAVE BEEN COMPLETE AND RECORDED AND ALL IS WELL	No image
06/11/2018 01:09:00 PM	NPU READING	
06/11/2018 01:10:00 PM	DWYER GAUGE READING SHOWING GOOD NEGATIVE PRESSURE STILL	
06/11/2018 01:11:00 PM	DCU CHECKS COMPLETE FOR THE AFTERNOON	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492



06/11/2018 01:12:00 PM	ENCLOSURE PICTURES, STRUCTURE STILL LOOKING GOOD AND WEATHERING WELL.	
06/11/2018 01:16:00 PM	ENCLOSURE PICTURES	
06/11/2018 01:21:00 PM	WASTE RUN STARTS.	No image
06/11/2018 02:36:00 PM	THE HAND DIG IS COMPLETE AND AT A DEPTH THAT IM HAPPY WITH. WE HAVE NOT COME ACROSS ANY THERMAL INSULATION DURING THE DIG SO AGAIN IM HAPPY THAT THE EARTH IS CLEAN UP TO OUR DEPTHS. I HAVE JUST CHANGED UP AND HAD A VISUAL OF THE WALL. I CAN NOT SEE ANY THERMAL INSULATION TO THE WALL WHICH IS GOOD NEW BUT WI INVITE THE ANALYST IN TO THE ENCLOSURE TOMORROW MORNING TO HAVE A LOOK BEFORE WE START THE CLEAN TO THE WALL.	No image
06/11/2018 02:37:00 PM	WASTE RUN IS NOW COMPLETE AND THE OPERATIVES ARE CLEANING THROUGH THE BAGLOCK AND DIRECT CONNECTION.	No image
06/11/2018 03:05:00 PM	OPERATIVES HEAD TO SHOWERS FOR END OF SHIFT	No image
06/11/2018 03:16:00 PM	NPU SWITCHED OFF AND ENCLOSURE SEALED	No image
06/11/2018 03:37:00 PM	OPERATIVES ARE THROUGH THE SHOWER AND THE DCU IS POWERED DOWN AND LOCKED	No image
06/11/2018 03:46:00 PM	RHODAR SIGN OUT AND LEAVE SITE	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492



Enclosure ENCLOSURE 1

List of operatives

ALEX UDALL

PETER KOSZTY

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	yes
Viewing panels / CCTV Image clear & distinct	yes
Warning signs displayed	yes
Adequately weighted flaps with chains	yes
'H' type vacuum cleaner, in inner stage	yes
Water, hand sprayer, bucket & PDE	yes
Transit overalls, etc, stored in outer stage	yes
Airlocks/Baglocks clear and free from debris	yes
Dwyer Gauge (wg) AM:	0.2
Dwyer Gauge (wg) PM:	0.2

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM 480 PM 490
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #2 Vacuum serial number: 175023408	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #1 Vacuum serial number: 175022208	Retest date: 2019-04-18
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes


VACUUM UNIT #3 Vacuum serial number: MVLP 092 SE	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 06/11/2018

Project number: SOU003492



Fixed scaffolds

FIXED SCAFFOLD #1	
	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 250	Gauge reading (PM): 240
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: Yes Directly connected comments:		
		
Comments: ALL UP AND RUNNING OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492




Daily entry

Recorded at 07/11/2018

Weather AM: MOSTLY CLOUDY 13°

Weather PM: RAIN 14°

Day photos






ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492




Days Events

Time	Description	Image
07/11/2018 08:06:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN	No image
07/11/2018 08:15:00 AM	DCU POWERED UP AND CHECKS COMPLETE	
07/11/2018 08:30:00 AM	ENCLOSURE UNSEALED AND POWERED UP VIA GENERATOR. ALL CHECKS COMPLETE	
07/11/2018 09:05:00 AM	WE HAVE NOTICED THAT THE HOLE WE HAVE DUG HAS TAKEN WATER OVER NIGHT AND HAS FILLED UP TO ABOUT 400MM DEEP. WE ARE GOING TO HAVE TO SPEND THE MORNING PUMPING IT OUT VIA THE WASTE FILTRATION SYSTEM ON THE DCU..	No image
07/11/2018 09:13:00 AM	OPERATIVES CHANGE UP AND HEAD INTO THE ENCLOSURE. ONCE THEY ARE ALL THROUGH THE DCU I WILL RUN A HOSE IN TO THE ENCLOSURE AND THROUGH THE WASTE FILTERS ON THE WASTE PUMP TO THE DCU.	No image
07/11/2018 09:29:00 AM	OPERATIVES HAVE NOW PLACED THE HOSE FROM THE DCU INTO THE PIT AND THE WATER IS PUMPING OUT. THIS IS WORKING WELL BUT IT WILL TAKE A WHILE	No image
07/11/2018 10:08:00 AM	WATER IS STILL BEING PUMPED OUT BUT WORKING OK.	No image
07/11/2018 10:16:00 AM	NPU READING	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492



07/11/2018 10:17:00 AM	DWYER GAUGE READING	
07/11/2018 10:51:00 AM	WORKS ARE BEING DELAYED AS WE ARE STILL PUMPING OUT THE WATER BUT ITS NOT TOO FAR OFF NOW.	No image
07/11/2018 11:05:00 AM	2 X OPERATIVES START THE WIRE BRUSH AND SCRAPE TO THE SMALL WALL AREA THAT WE HAVE UNCOVERED, I VISUALIZED THIS WAS YESTER AND THERE WAS ONLY THE ONE SMALL AREA AT THE TOP THAT HAD THERMAL INSULATION ON IT THE REST OF THE WALL LOOKED OK.	No image
07/11/2018 11:07:00 AM	THE THIRD OPERATIVE FINE CLEANS THE BAGLOCK AND THE DIRECT CONNECTION. THESE ARE REALLY THE ONLY AREAS THAT CAN BE CLEAN PROPERLY ALONG WITH A WIPE DOWN TO ALL THE POLY SHEETING, THIS IS DUE TO THE REST OF THE AREA BEING MUD.	No image
07/11/2018 12:08:00 PM	WORKS ARE COMPLETE AS FAR AS POSSIBLE WITH THIS TYPE OF AREA AND THE CONDITIONS WE ARE WORKING IN. THE 3 X OPERATIVES ALL HEAD OUT VIA THE DCU.	No image
07/11/2018 12:09:00 PM	I HAVE LEFT THE HOSE PUMPING OUT THE LAST REMAINING WATER IN THE HAND DIG WHILE THE GUYS HAVE LUNCH. ALL GOING WELL MYSELF AND THE ANALYST WILL ENTER THE ENCLOSURE AFTER LUNCH AND START HIS VISUAL.	No image
07/11/2018 02:08:00 PM	MYSELF AND THE ANALYST HAVE JUST BEEN IN THE ENCLOSURE FOR A PRE VISUAL AND HE IS SAYING HE WOULD LIKE THE WALL ENCAPSULATED AS ITS MUDDY AND AS A PRECAUTION. HE HAS NOT FOUND ANY INSULATION ON THE WALL.	No image
07/11/2018 02:24:00 PM	AFTER SPEAKING TO MVP HE HAS TOLD ME NOT TO ENCAPSULATE THE WALL AS THERE HAS BEEN NO INSULATION FOUND AND OBVIOUSLY THIS WOULD CREATE PROBLEMS FOR THE CLIENT.	No image
07/11/2018 02:25:00 PM	MVP WILL BE ON SITE TOMORROW MORNING AND HE WILL BE ABLE TO HAVE A LOOK HIMSELF AND SPEAK WITH THE CLIENT AND ANALYST THAT WILL ALSO BE ON SITE.	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492



07/11/2018 02:47:00 PM	FOR THE ABOVE REASONS THE ENCLOSURE AND DCU HAVE BEEN SHUT DOWN FOR THE DAY.	No image
		No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492



Enclosure ENCLOSURE 1

List of operatives

ALEX UDALL

PETER KOSZTY

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	yes
Viewing panels / CCTV Image clear & distinct	yes
Warning signs displayed	yes
Adequately weighted flaps with chains	yes
'H' type vacuum cleaner, in inner stage	yes
Water, hand sprayer, bucket & PDE	yes
Transit overalls, etc, stored in outer stage	yes
Airlocks/Baglocks clear and free from debris	yes
Dwyer Gauge (wg) AM:	0.2
Dwyer Gauge (wg) PM:	0.2

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM 480 PM 480
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #1 Vacuum serial number: 175022208	Retest date: 2019-04-18
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #2 Vacuum serial number: 175023408	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes


VACUUM UNIT #3 Vacuum serial number: MVLP 092 SE	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 07/11/2018

Project number: SOU003492



Fixed scaffolds

FIXED SCAFFOLD #1	
	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 240	Gauge reading (PM): 240
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: Yes Directly connected comments:		
		
Comments: ALL UP AND RUNNING OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492



Daily entry

Recorded at 08/11/2018

Weather AM: MOSTLY SUNNY 12°

Weather PM: MOSTLY SUNNY 14°

Day photos






ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492




Days Events

Time	Description	Image
08/11/2018 08:03:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN	No image
08/11/2018 08:14:00 AM	DCU CHECKS COMPLETE AND ALL RECORDED	
08/11/2018 08:25:00 AM	ENCLOSURE UNSEALED AND ALL POWERED UP, ALL CHECKS COMPLETE AND RECORDED.	
08/11/2018 08:28:00 AM	ENCLOSURE PICTURES SHOWING GOOD INTEGRITY	
08/11/2018 08:31:00 AM	WE HAVE A NEW ANALYST WITH US ON SITE TODAY WHO WILL BE COMPLETING OUR VISUAL IN A BIT AFTER SHE HAS BEEN INDUCTED.	No image
08/11/2018 08:44:00 AM	IIN THE MEAN TIME I HAVE THE OPERATIVES HAVE A GOOD TIDY THROUGH THE SITE INCLUDING THE DCU AND THE CLEAN END OF THE BAGLOCK.	No image
08/11/2018 09:30:00 AM	THE ANALYST HAS CHANGED UP ALONG WITH ONE OF MY OPERATIVES AN THEY HAVE BOTH ENTERED THE ENCLOSURE.	No image
08/11/2018 09:46:00 AM	THE VISUAL HAS NOW STARTED.	No image
08/11/2018 10:23:00 AM	VISAUL HAS NOW FINISHED AND ALL PASSED. THE PUMPS HAVE NOW BEEN PLACED ON	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492



08/11/2018 11:25:00 AM	PUMPS HAVE BEE REMOVED FROM THE ENCLOSURE AND HAVE BEEN TAKEN TO BE READ.	No image
08/11/2018 11:49:00 AM	AFTERNOON CHECKS HAVE ALL BEEN COMPLETE AND ALL IS WELL.	No image
08/11/2018 12:05:00 PM	PUMP RESULTS ARE BACK AND THE ENCLOSURE HAS PASSED.	No image
08/11/2018 12:07:00 PM	CONTRACTORS HANDOVER SHEET.	
08/11/2018 12:08:00 PM	THE OPERATIVES CHANGE UP IN TO WHITES AND HALF MASKS AND HEAD OUT TO SITE AND BEGIN HE DESHEET OF THE ENCLOSURE	No image
08/11/2018 12:25:00 PM	I BELIEVE WE WILL HAVE ELITE WITH US TOMORROW READY TO SYRIKE STRIKE THE SCAFFOLD	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492



Enclosure ENCLOSURE 1

List of operatives

ALEX UDALL

PETER KOSZTY

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	yes
Viewing panels / CCTV Image clear & distinct	yes
Warning signs displayed	yes
Adequately weighted flaps with chains	yes
'H' type vacuum cleaner, in inner stage	yes
Water, hand sprayer, bucket & PDE	yes
Transit overalls, etc, stored in outer stage	yes
Airlocks/Baglocks clear and free from debris	yes
Dwyer Gauge (wg) AM:	0.2
Dwyer Gauge (wg) PM:	NA NPU OFF

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM 480 PM NA NPU OFF
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #3 Vacuum serial number: MVLP 092 SE	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #1 Vacuum serial number: 175022208	Retest date: 2019-04-18
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #2 Vacuum serial number: 175023408	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 08/11/2018

Project number: SOU003492



Fixed scaffolds

FIXED SCAFFOLD #1	
No image	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 250	Gauge reading (PM): 250
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: Yes Directly connected comments:		
		
Comments: ALL UP AND RUNNING OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492




Daily entry

Recorded at 09/11/2018

Weather AM: PARTLY CLOUDY 13°

Weather PM: PARTLY CLOUDY 14°

Day photos




ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492




Days Events

Time	Description	Image
09/11/2018 08:00:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN.	No image
09/11/2018 08:08:00 AM	ELITE SCAFFOLDERS ARE DUE IN THIS MORNING TO STRIKE THE SCAFFOLD.	No image
09/11/2018 08:21:00 AM	DCU HAS BEEN SET UP AND READY TO BE TESTED BY THE ANALYST. CHECKS COMPLETE AND RECORDED	No image
09/11/2018 08:24:00 AM	DCU	
09/11/2018 08:29:00 AM	THE ENCLOSURE WAD DE-SHEETED YESTERDAY AND WILL NEED THE ANALYST TO COMPLETE THE 4 STAGE TODAY.	No image
09/11/2018 09:06:00 AM	ELITE HAVE TURNED UP AND ARE NOW BEING INDUCTED	No image
09/11/2018 09:18:00 AM	MYSELF AND TYLER HAVE CLEANED THE DCU THROUGH AND OVERED THE NPU. THE ANALYST IS NOW RUNNING HER PUMP IN THE UNIT.	No image
09/11/2018 11:19:00 AM	SCAFFOLD COMI G DOWN NICELY.	No image
09/11/2018 12:30:00 PM	SCAFFOLDERS HAVE NOW FINISHED AND LEFT SITE.	No image
09/11/2018 12:40:00 PM	DCU HAS BEEN COMPLETE AND CERTIFICATE IN PLACE	
09/11/2018 12:51:00 PM	MYSELF AND THE ANALYST GO OUT ON SITE AND START THE 4 STAGE.	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492



09/11/2018 01:06:00 PM	4 STAGE COMPLETE AND THIS CONCLUDES THE ENCLOSURES WORKS	
09/11/2018 01:15:00 PM	COMPLETED PICTURES OF THE WORKS	
09/11/2018 01:20:00 PM	TRANSIT/WASTE ROUTES REMOVED	
09/11/2018 01:45:00 PM	WORKS FOR THE DAY ARE FINISHED AND RHODAR SIGN OUT TO LEAVE, THE WATCH AND BRIEF WILL START MONDAY	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492



Enclosure ENCLOSURE 1

List of operatives

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	no
Viewing panels / CCTV Image clear & distinct	no
Warning signs displayed	no
Adequately weighted flaps with chains	no
'H' type vacuum cleaner, in inner stage	no
Water, hand sprayer, bucket & PDE	no
Transit overalls, etc, stored in outer stage	no
Airlocks/Baglocks clear and free from debris	no
Dwyer Gauge (wg) AM:	NA
Dwyer Gauge (wg) PM:	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492



Enclosure NPU's

NPU UNIT #1 NPU serial number: A5007-SE Retest date: 02/02/2019	Manometer reading: AM NA PM
Numbers correspond with numbers stated in Plan of Work	yes
Appropriate DOP Certs available	yes
Ducting & unit in good repair	yes
Pre-Filter changed daily	yes
Located farthest end from airlocks, venting to outside where possible	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #2 Vacuum serial number: 175023408	Retest date: 2019-02-02
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

VACUUM UNIT #1 Vacuum serial number: 175022208	Retest date: 2019-04-18
At least 2 units available on site (One at dirty end of airlock	no
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 09/11/2018

Project number: SOU003492



Fixed scaffolds

FIXED SCAFFOLD #1	
No image	Company hired from: ELITE Date of next inspection: 2018-10-31
Has the scaffold been inspected in the last 7 days?	no

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Hygiene unit

Unit number: 74SE	Gauge reading (AM): 240	Gauge reading (PM):
Gas cert: B5213299	Electric cert: IPN4/0634946	Air cert: JO17383
Directly connected: No Directly connected comments: IT WAS BUT THE ENCLOSURE HAS NOW BEEN TAKEN DOWN.		
		
Comments: ALL OK		

Air Test Certificate	yes
Cleanliness	yes
Internal Lights OK	yes
No external damage	yes
Key available	yes
Spirit level on A frame	yes
On level ground	yes
Steps	yes
LPG Cylinder OK	yes
Water heated OK	yes
Water filters in use	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION

Project number: SOU003492



Drain to foul	yes
240v Power Lead	yes
Earthing rod in use	yes
Charging Units OK	yes
Lockers OK	yes
Heating OK	yes
Shower Heads OK	yes
Shower Drains OK	yes
SC Doors Operate	yes
HEPA Filter on NPU	yes
Nail Brush	yes
Mirror	yes
Towels	yes
Mop / Bucket	yes
Waste Bags	yes
Transit Route Short	yes
Is there a Carbon Monoxide detector fitted to the unit?	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 12/11/2018

Project number: SOU003492




Daily entry

Recorded at 12/11/2018

Weather AM: PARTLY CLOUDY 13°

Weather PM: PARTLY CLOUDY 14°

Day photos




ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 12/11/2018

Project number: SOU003492




Days Events

Time	Description	Image
12/11/2018 08:01:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN	No image
12/11/2018 09:01:00 AM	OUR MACHINE DRIVER JOHN HAS ARRIVED. E WILL NEED TO BE INDUCTED, THE SITE MANAGER DANNY IS BUSY OUT ON SITE. HE WANTS TO GET SOME USE OF THE MACHINE BEFORE WE START AND HE CANT USE IT. HE WILL GIVE THE INDUCTION WHEN HES FINISHED	No image
12/11/2018 10:06:00 AM	INDUCTION HAS NOW STARTED	No image
12/11/2018 10:33:00 AM	INDUCTION COMPLETE AND MYSELF THE DRIVER AND THE SITE MANAGER HEAD OUT ON SITE TO DISCUSS THE MACHINE DIG.	No image
12/11/2018 10:39:00 AM	EXCLUSION ZONE HAS BEEN SET UP ALONG WITH THE HYGIENE STATION. WORKS NOW START DIGGING THE AREA DOWN FROM WHICH THE PREVIOUSLY CONTAMINATED EARTH WAS DRAGGED OVER. TJIS WILL GO STRAIGHT IN THE OPEN SKIP WE ALREADY HAVE ON SITE.	No image
12/11/2018 10:40:00 AM	EXCLUSION ZONE AND HYGIENE STATION	
12/11/2018 10:55:00 AM	WE HAVE STARTED TO PULL THE OLD EARTH BACK SPOR CHECK THE EARTH BEFORE ITS PLACE IN THE SKIP. THIS IS DONE ON A SMALL LAY DOWN AREA AS SEEN IN THE PICTURE	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 12/11/2018

Project number: SOU003492



12/11/2018 11:25:00 AM	EXCAVATION SO FAR.	
12/11/2018 11:34:00 AM	SKIP IS NOW FULL AND WE ARE WAITING FOR THE EXCHANGE TO BE DELIVERED	
12/11/2018 12:03:00 PM	SPOKE TO BOWMERS AND THENSKIS ARE 40 MINS AWAY.	No image
12/11/2018 01:09:00 PM	STILL NOT HAD THIS SKIP EXCHANGE, I HAVE CHASED AGAIN AND IM BEING TOLD THERE NEARBY	No image
		No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 12/11/2018

Project number: SOU003492



Non notifiable Job

List of operatives

JOHN CARPENTER

TYLER WILSON

Enclosures and airlocks

Structure sound – timbers / polythene, etc	
Viewing panels / CCTV Image clear & distinct	
Warning signs displayed	
Adequately weighted flaps with chains	
'H' type vacuum cleaner, in inner stage	
Water, hand sprayer, bucket & PDE	
Transit overalls, etc, stored in outer stage	
Airlocks/Baglocks clear and free from debris	
Dwyer Gauge (wg) AM:	
Dwyer Gauge (wg) PM:	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 12/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #1	Retest date: 2019-04-18
Vacuum serial number: 175022208	
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 13/11/2018

Project number: SOU003492




Daily entry

Recorded at 13/11/2018

Weather AM: PARTLY CLOUDY 12°

Weather PM: MOSTLY CLOUDY 14°

Day photos






ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 13/11/2018

Project number: SOU003492



Days Events

Time	Description	Image
13/11/2018 08:06:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN. ALSO HAVE JONH WITH ME TODAY WHOM WILL BE MY MACHINE DRIVER	No image
13/11/2018 09:08:00 AM	WE HAVE A SKIP EXCHANGE THIS MORNING, BOWMERS ARE ON SITE. THEY WILL BE TAKING ONE OF THE LOADED 20YARD OPEN SKIPS OFF TO LAND FILL AND DROPPING US AN EMPTY. BOWMERS WILL THEN BE BACK THIS AFTERNOON TO DO ANOTHER EXCHANGE	No image
13/11/2018 09:23:00 AM	MYSELF AND JOHN HEAD OUT ON SITE TO CARRY ON WITH THE MACHINE DIG. AND FILL. EXCLUSION ZONE SET UP AROUND OUR WORKS AND WE BOTH CHANGE INTO OUR COVERALS AND HALF MASKS.	
13/11/2018 09:32:00 AM	WORKS START WITH THE MACHINE DIG	No image
13/11/2018 12:13:00 PM	WE HAVE FILLED THE SKIP NOW AD ARE WAITING ON THE EXCHANGE TO ARRIVE BEFRE WE CONTINUE.	
13/11/2018 12:14:00 PM	EXCAVATION SO FAR...	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 13/11/2018

Project number: SOU003492



13/11/2018 12:15:00 PM	PICTURES OF EXCAVATION SO FAR.	
13/11/2018 01:52:00 PM	BOWMERS HAVE ARRIVE AND COMPLETED ANOTHER SKIP EXCHANGE.	No image
13/11/2018 02:08:00 PM	RHODAR HEAD BACK OUT N SITE ALONG WITH THE MACHINE DRIVER AND START THE DIG AGAIN, EXCLUSION ZONE BACK IN PLACE.	No image
13/11/2018 02:53:00 PM	WE HAVE FILLED THE NEW SKIP AND IT IS READY FOR THE MORNING EXCHANGE.	No image
13/11/2018 03:14:00 PM	SITE LEFT TIDY AND RHODAR CLEAN UP.	No image
13/11/2018 03:29:00 PM	RHODAR SIGN OUT AND LEAVE SITE	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 13/11/2018

Project number: SOU003492



Non notifiable Job

List of operatives

JOHN CARPENTER

Enclosures and airlocks

Structure sound – timbers / polythene, etc	
Viewing panels / CCTV Image clear & distinct	
Warning signs displayed	
Adequately weighted flaps with chains	
'H' type vacuum cleaner, in inner stage	
Water, hand sprayer, bucket & PDE	
Transit overalls, etc, stored in outer stage	
Airlocks/Baglocks clear and free from debris	
Dwyer Gauge (wg) AM:	
Dwyer Gauge (wg) PM:	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 13/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #1	Retest date: 2019-04-18
Vacuum serial number: 175022208	
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 14/11/2018

Project number: SOU003492




Daily entry

Recorded at 14/11/2018

Weather AM: MOSTLY SUNNY 12°

Weather PM: MOSTLY SUNNY 14°

Day photos



ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 14/11/2018

Project number: SOU003492




Days Events

Time	Description	Image
14/11/2018 08:03:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN I HAVE THE JOHN THE MACHINE DRIVER WITH ME AGAIN TODAY.	No image
14/11/2018 08:41:00 AM	BOWMERS HAVE JUST ARRIVED AND THE SKIP EXCHANGE HAS TAKEN PLACE.	No image
14/11/2018 08:42:00 AM	BOWMERS WILL GO AND TIP THE FULL SKIP AND DO ANOTHER EXCHANGE LATER TODAY.	No image
14/11/2018 09:06:00 AM	MYSELF AND JOHN HEAD OUT ON TO SITE AND RE START THE MACHINE DIG	No image
14/11/2018 09:07:00 AM	EXCLUSION ZONE IN PLACE	
14/11/2018 09:12:00 AM	BOTH OF US HAVE CHANGED IN TO COVERALS AND HALF MASKMAND WORK CONTINUE	No image
14/11/2018 10:54:00 AM	MACHINE DIG FINISHED FOR NOW AS THE SKIP IS NOW FULL.. PROGRESS SO FAR. MACHINE DRIVER IN HISFULL KIT	
14/11/2018 10:54:00 AM	MACHINE DRIVER DURING HIS WORKS	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 14/11/2018

Project number: SOU003492



14/11/2018 10:55:00 AM	PROGRESS	
14/11/2018 10:55:00 AM	PROGRESS OF THE DIG SO FAR.	
14/11/2018 11:05:00 AM	WE HAVE ANOTHER SKIP DUE FOR EXCHANGE AROUND 12.00 WHEN WORKS SHALL CONTINUE. RHODAR TAKE A LUNCH BREAK	No image
14/11/2018 01:57:00 PM	BOWMERS HAVE ARRIVED WITH THE EXCHANGE, THIS HAS NOW BEEN SWAPPED AND BOWMERS HEAD OFF	No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 14/11/2018

Project number: SOU003492



Non notifiable Job

List of operatives

JOHN CARPENTER

Enclosures and airlocks

Structure sound – timbers / polythene, etc	
Viewing panels / CCTV Image clear & distinct	
Warning signs displayed	
Adequately weighted flaps with chains	
'H' type vacuum cleaner, in inner stage	
Water, hand sprayer, bucket & PDE	
Transit overalls, etc, stored in outer stage	
Airlocks/Baglocks clear and free from debris	
Dwyer Gauge (wg) AM:	
Dwyer Gauge (wg) PM:	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 14/11/2018

Project number: SOU003492



Enclosure vacuum's

VACUUM UNIT #1	Retest date: 2019-04-18
Vacuum serial number: 175022208	
At least 2 units available on site (One at dirty end of airlock	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 15/11/2018

Project number: SOU003492




Daily entry

Recorded at 15/11/2018

Weather AM: PARTLY CLOUDY 14°

Weather PM:

Day photos



ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 15/11/2018

Project number: SOU003492



Days Events

Time	Description	Image
15/11/2018 08:04:00 AM	RHODAR ARRIVE ON SITE AND SIGN IN. DAVE COLE IS MY DRIVER TODAY.	No image
15/11/2018 08:34:00 AM	EXCLUSION ZONE SET UP AND MYSELF AND DAVE COLE HAVE CHANGED UP. THE MACHINE DIG CONTINUES.	
15/11/2018 09:23:00 AM	THE FIRST SKIP IS FULL NOW THAT WAS DROPPED OF YESTERDAY AFTERNOON. WE SHOULD HAVE AN EXCHANGE TAKING PLACE SOON.	No image
15/11/2018 09:50:00 AM	BOWMERS HAVE ARRIVED AND THE SKIP EXCHANGE HAS TAKEN PLACE	No image
15/11/2018 10:02:00 AM	RHODAR TAKE A QUICK BREAK.	No image
		No image

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 15/11/2018

Project number: SOU003492



Non notifiable Job

List of operatives

DAVE COLE

Enclosures and airlocks

Structure sound – timbers / polythene, etc	
Viewing panels / CCTV Image clear & distinct	
Warning signs displayed	
Adequately weighted flaps with chains	
'H' type vacuum cleaner, in inner stage	
Water, hand sprayer, bucket & PDE	
Transit overalls, etc, stored in outer stage	
Airlocks/Baglocks clear and free from debris	
Dwyer Gauge (wg) AM:	
Dwyer Gauge (wg) PM:	

ASDA FERRING -AIB/THERMAL DEBRIS SOIL REMEDICATION / Daily entry - 15/11/2018

Project number: SOU003492



Enclosure vacuum's


VACUUM UNIT #1	Retest date: 2019-04-18
Vacuum serial number: 175022208	
At least 2 units available on site (One at dirty end of airlock)	yes
Appropriate DOP certs available	yes
Hose & unit in good repair	yes

Project number: SOU003492

Post Remediation Checklist

Questionnaire

Question #1	Answer
Is there adequate lighting to carry out post remediation checks?	YES
images: No images	
Comments:	

Question #2	Answer
Have transit and waste routes been checked ensuring no tape marks are left to floors or if there is any evidence of enclosure, has this been notified to the client?	YES
images: 	
Comments:	