

SHEET 3 OF 3



REV 'B' - SEPTEMBER 2007 - Position of Foul Pumping Main surveyed (located by trial pits)
REV 'A' - July 2007 - Additional adjacent house roof level details surveyed

NOTES:

No assumptions should be made regarding the interconnection of manholes.
Drainage details have been obtained from surface inspection and should
be verified if of critical importance.

Coordinates based on Local OS grid determined from National GPS Network using OSTN02.
Add 490,000m to Easting, 100,000m to Northing for true OS co-ordinates.

Levels are based on OS datum determined from National GPS Network using OSGM02.
The level tie-in to traditional benchmarks is usually better than 0.05m, but please note
that it may differ by up to 0.20m and caution should be exercised when comparing to
other level data based on OSBM's such as Water Authority sewer records.

Land Surveyors & Engineers

siteline

No.1 Shelley Farm
Ower
Hampshire
SO51 6AS

Tel: 023 80 811081
Fax: 023 80 811012
E-mail: siteline.co.uk

KINGSOAK HOMES	Client
LAND AT FELPHAM WEST SUSSEX	Contract
SITE SURVEY	Title
136FE01B	Drawing No.
MAY 2007	Date
1:1250 (A0)	Scale
AB	Surveyor