

WSSC APC Littlehampton

Photo Schedule: Failed Floor Structure

West Sussex County Council
May 2020

Photos




Photo 1 – Boiler Room



Photo 2 – Cracking within ground floor WCs



Photo 3 – Corroded Steel Beam



Photo 4 – Corroded Steel Beam

Gareth Jones
Faithful+Gould Limited
First Floor
2 Charlotte Place
Southampton
Hampshire
SO14 0TB

