

Photo taken in the back garden of No 44 North St. looking towards No 42 showing relationship of MH to back of house and soil and waste pipes.

Note location of soil pipes of No 42 which discharge into a MH in a similar relationship to that shown below but with drain flowing towards Sussex St.

MH at the back of No 44, with the cover off, showing clearly the direction of flow down the back of the terrace to discharge into the sewer at the side of No.50

