

Actual Riser Install – 47 South Terrace, Littlehampton. BN17 5NU

View from side road at rear of property (St. Augustine Road);



View of actual riser install from garden at rear of 47;



Initial suggested pipe run changed resulting in less impact;



Riser pick up;



Up and over exisiting external black drain pipes;



Entry in keeping with black drain pipe;



Entry;



Majority of pipework fitted to wall that existing black drain pipes already fitted to;









Consideration given to painting pipe white but left black as inkeeping with existing pipework;



