



Geo-Environmental

General

- Specified Site
- Specified Buffer(s)
- X Bearing Reference Point

Risk of Flooding from Surface Water


- High - 30 Year Return
- Medium - 100 Year Return
- Low - 1000 Year Return

Suitability

See the suitability ratio below

- Nature to country
- Country to town
- Town to street
- Street to parcels of land
- Property

EANRW Suitability Map - Slice A



Order Details


Order Number: 145702729_1_1
Customer Ref: GE16903
National Grid Reference: 503370, 103260
Slice: A
Site Area (Ha): 2.71
Search Buffer (m): 1000

Site Details

Daisyfields Touring Park, Cornfield Close, Wick,
LITTLEHAMPTON, BN17 6LD

Landmark
A Landmark Information Group Service

Tel: 0844 844 8952
Fax: 0844 844 8951
Web: www.landmark.co.uk






Geo-Environmental

General


Geo-Environmental
Geo-Environmental
Geo-Environmental

Estimated Soil Chemistry Arsenic

Arsenic Concentrations mg/kg



Estimated Soil Chemistry Arsenic - Slice A



Order Details

Order Details: 145702729_1_1
Customer Ref: GE16903
National Grid Reference: 503370, 103260
Slice: A
Site Area (Ha): 2.71
Search Buffer (m): 1000

Site Details

Site Details: Daisyfields Touring Park, Cornfield Close, Wick, LITTLEHAMPTON, BN17 6LD

Landmark
A Landmark Information Group Service

Tel: 0844 844 8952
Fax: 0844 844 8951
Web: www.landmark.co.uk



Geo-Environmental


General

Geo-Environmental Ltd. (Incorporated in England)


X Existing Infrastructure Data

Estimated Soil Chemistry Cadmium

Cadmium Concentrations mg/kg



Estimated Soil Chemistry Cadmium - Slice A



Order Details

Order Details: 145702729_1_1
Customer Ref: GE16903
National Grid Reference: 503370, 103260
Slice: A
Site Area (Ha): 2.71
Search Buffer (m): 1000

Site Details

Daisyfields Touring Park, Cornfield Close, Wick,
LITTLEHAMPTON, BN17 6LD

Landmark
A Landmark Information Group Service

Tel: 0844 844 8952
Fax: 0844 844 8951
Web: www.landmark.co.uk