

OK

DOE REF: 9/187 Arundel Road

Crossbush

Early C19. Two storeys. Five windows. Stuccoed. Tiled roof. Glazing
bars intact. Cantled porch with twin pilasters to each front, doorway at
side and dome over. Good inn-sign showing two kinds of sail: a ship and a
windmill.