

117 & 117a ELMER ROAD MIDDLETON

MANHOLE FOUL WATER INVERT LEVELS

(SEE DRAINAGE DIAGRAM)

MH1: 1M DEPTH Below Ground level to invert level

MH2: 900mm DEPTH

MH5: 900mm DEPTH

MH3: 700mm DEPTH

MH4: 600mm DEPTH

GROUND WATER MONITORING (WINTER PERIOD)

TRIAL PIT DEPTH 1.2M below ground level

MONITORING PERIOD OCT 23 - Jan 24 2023

Mon 9 th Jan 23	NO WATER PRESENT	TIDAL DATA	HW 12.30	5.39M
Mon 23 Jan 23	NO WATER PRESENT	HW	12.03 @	6.06M
Mon 6 th Feb 23	NO WATER PRESENT	HW	12.00 @	5.4M "
Mon 20 th Feb 23	NO WATER PRESENT	HW	11.18	6.0M Spring
Tues 21 st Feb 23	NO WATER PRESENT	HW	12.00	6.15M "
Mon 16 th Oct 23	NO WATER PRESENT	HW	12.34	5.77M "
wed 15 th Nov 23	NO WATER PRESENT	HW Spring	12.00	5.79m "
Frid 27 th Nov 23	No water	HW	13.25	5.54 "
Thurs 14 th Dec 23	No water		11.45	5.80 spring
Thurs 28 Dec 23	No Water	HW Spring	11.58	5.60
Frid 12 th Jan 24	NO WATER	HW Spring	11.37	5.84m
Dug test pit a further 300mm to depth of 1.5m (the max. depth allowed before shuttering)				
Thur 18 th Jan 24	No Water present	HW	16.37	
Mon 29 th Feb 24	No Water present	HW	13.23	5.34m
Mon 12 th Feb 24	No water present.	HW spring	13.00	6.16m