

Photographs to Support Planning Application

Conservatory

18 Mill view Close
Pagham
Bognor Regis
West Sussex
PO21 3UF

For Mr S Farrant

August 2025

Project No: SFI

Document No: PSvI

Photo 1 to show: Existing front elevation (East) of park home 18 Millview Close.



Photo 2 to show: Existing side elevation (South).



Photo 3 to show: Existing rear elevation (West).



Photo 4 to show: The rear elevation and the southern end where the steps to the single external door to the kitchen are to be demolished and where the position of the new conservatory is proposed.



Photo 5 to show: Existing rear patio area and a white line to show approx floor location of the proposed conservatory, which is not to scale and for illusturtuve purposes.

