





APPENDIX C

PHOTOGRAPHIC LOG

05035 L01 (00) DRAFT

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 1		
Date: 25/01/2019		
Facing northwest, overview of BH206		
Photo No. 2		
Date: 25/01/2019		
BH206 hand pit arisings		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 3		
Date: 25/01/2019		
BH206 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		
Photo No. 4		
Date: 25/01/2019		
Facing northeast, overview of BH207		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 5		
Date: 25/01/2019		
BH207 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		
Photo No. 6		
Date: 25/01/2019		
Facing northwest, overview of BH208		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 7		
Date: 25/01/2019		
BH208 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		
Photo No. 8		
Date: 25/01/2019		
Facing northeast, overview of BH209		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 9		
Date: 25/01/2019		
BH209 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		
Photo No. 10		
Date: 24/02/2019		
BH210 handpit arisings		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 11		
Date: 24/02/2019		
BH210 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		
Photo No. 12		
Date: 25/01/2019		
Facing northwest, overview of BH211		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 13		
Date: 25/01/2019		
BH211 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		
Photo No. 14		
Date: 25/01/2019		
BH211 core soils recovery: 1. 2-3 m (L-R) 2. 1-2 m (L-R)		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 15		
Date: 21/01/2019		
Facing southeast, overview of TP201		
Photo No. 16		
Date: 21/01/2019		
Arisings from TP201		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 17		
Date: 21/01/2019		
View downhole of TP201, during soakaway test		
Photo No. 18		
Date: 23/01/2019		
Facing east, overview of TP202 and arisings		


PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 19		
Date: 2/01/2019		
Facing northeast, view of TP203 and arisings		
Photo No. 20		
Date: 23/01/2019		
Facing north, view of TP204 and arisings		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 21		
Date: 23/01/2019		
Downhole view of TP204		
Photo No. 22		
Date: 23/01/2019		
Facing northeast, view of TP205 and arisings		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 23		
Date: 23/01/2019		
Downhole view of TP205		
Photo No. 24		
Date: 21/01/2019		
Facing east, view of TP206 and arisings		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 25		
Date: 22/01/2019		
Facing east, view of TP207		
Photo No. 26		
Date: 22/01/2019		
Downhole view of TP207		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 27		
Date: 22/01/2019		
Facing northeast, view of TP208		
Photo No. 28		
Date: 22/01/2019		
Facing southwest, view of TP209		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 29		
Date: 21/01/2019		
Facing southeast, overview of TP210 and arisings		
Photo No. 30		
Date: 21/01/2019		
Downhole view of TP210		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 31		
Date: 21/01/2019		
Facing southwest, view of TP211		
Photo No. 32		
Date: 21/01/2019		
Downhole view of TP211		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 33		
Date: 23/01/2019		
Facing southwest, view of TP212 and arisings		
Photo No. 34		
Date: 24/01/2019		
View of TP2123		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 35		
Date: 22/01/2019		
Facing east, view of TP214		
Photo No. 36		
Date: 22/01/2019		
Downhole view of TP215		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 37		
Date: 22/01/2019		
Facing southwest, view of TP216		
Photo No. 38		
Date: 22/01/2019		
Facing southwest, view of TP218 and arisings		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 39		
Date: 22/01/2019		
Facing west, view of TP219 and arisings		
Photo No. 40		
Date: 22/01/2019		
Downhole view of TP219		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 41		View of TP220
Date: 22/01/2019		
Photo No. 42		Facing east, view of TP221 and arisings
Date: 23/01/2019		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 43		
Date: 23/01/2019		
Downhole view of TP221 during soakage test		
Photo No. 44		
Date: 23/01/2019		
Facing southeast, view of TP222		

PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 45		
Date: 23/01/2019		
Downhole view of TP222		
Photo No. 46		
Date: 23/01/2019		
Facing south, view of TP223		


PHOTOGRAPHIC LOG		305035 L01 (00)
Site Location: Land at Sefter Road, Bognor Regis, PO21 3EE		Appendix D
Photo No. 47		
Date: 23/01/2019		
Downhole view of TP223		

APPENDIX D

TRIAL PIT SOAKAWAY TEST DATA


05035 L01 (00) DRAFT

Location	TP201	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.20
Job number	305035	Width of trial pit (m)	0.45
Test date	21 January 2019	Water level at start (mbgl)	0.80
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	1.80
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.80

[illegible]

Results		Comments
Vp 75-25 (m3)	0.495	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	3.64	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ

Location	TP202	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.15
Job number	305035	Width of trial pit (m)	0.60
Test date	23 January 2019	Water level at start (mbgl)	0.60
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	1.48
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.48

[illegible]


Results		Comments
Vp 75-25 (m3)	0.57	1. Groundwater at 1.60 m prior to soakaway test.
ap 50 (m2)	3.71	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ



DRAFT

[illegible]

Trial Pit Soakaway Test Results



Results


Vp 75-25 (m3)	0.19
ap 50 (m2)	2.09
tp 75-25 (s)	44000
Infiltration Rate (m/s)	2.08E-06

Comments

1. Trial pit dry prior to soakaway test.


RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre,
Premier Way, Romsey, SO51 9AQ

Location	TP204	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.20
Job number	305035	Width of trial pit (m)	0.60
Test date	23 January 2019	Water level at start (mbgl)	0.50
Operator	Edward Hughes-Phillips 27-Feb-19	Depth to base of trial pit (mbgl)	1.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.35

[illegible]

Results		Comments
Vp 75-25 (m3)	0.66	1. Groundwater at 1.50 m prior to soakaway test.
ap 50 (m2)	4.12	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Way, Romsey, SO51 9AQ

Location	TP205	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.30
Job number	305035	Width of trial pit (m)	0.60
Test date	23 January 2019	Water level at start (mbgl)	0.50
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	1.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.46

[illegible]


Results		Comments
Vp 75-25 (m3)	0.69	1. Groundwater at 1.45 m prior to soakaway test.
ap 50 (m2)	4.29	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Way, Romsey, SO51 9AQ



DRAFT

[illegible]

Trial Pit Soakaway Test Results



Results

Comments

1. Trial pit dry prior to soakaway test.


RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre,
Premier Way, Romsey, SO51 9AQ



DRAFT

[illegible]

Trial Pit Soakaway Test Results




Results

Comments

1. Trial pit dry prior to soakaway test.


RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre,
Premier Way, Romsey, SO51 9AQ

Location	TP209	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.40
Job number	305035	Width of trial pit (m)	0.45
Test date	22 January 2019	Water level at start (mbgl)	0.50
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	1.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.45

[illegible]

Results		Comments
Vp 75-25 (m3)	0.54	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	3.93	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ

Location	TP210	Test number	1
Site	Sefton Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.80
Job number	305035	Width of trial pit (m)	0.60
Test date	22 January 2019	Water level at start (mbgl)	0.13
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	0.42
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	0.40

[illegible]


Results		Comments
Vp 75-25 (m3)	0.24	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	2.67	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Way, Romsey, SO51 9AQ



DRAFT

[illegible]

Trial Pit Soakaway Test Results




Results

Comments

1. Groundwater at 1.50 m prior to soakaway test.


RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre,
Premier Way, Romsey, SO51 9AQ

Location	TP216	Test number	1
Site	Sefton Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.90
Job number	305035	Width of trial pit (m)	0.60
Test date	22 January 2019	Water level at start (mbgl)	0.50
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	1.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.50

[illegible]

Results		Comments
Vp 75-25 (m3)	0.87	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	5.24	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Way, Romsey, SO51 9AQ

Location	TP217	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.40
Job number	305035	Width of trial pit (m)	0.60
Test date	22 January 2019	Water level at start (mbgl)	0.16
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	0.55
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	0.55


[illegible]

Results	
Vp 75-25 (m3)	0.28
ap 50 (m2)	2.61
tp 75-25 (s)	-
Infiltration Rate (m/s)	-

1. Trial pit dry prior to soakaway test.


RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre,
Premier Way, Romsey, SO51 9AQ

Location	TP219	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.40
Job number	305035	Width of trial pit (m)	0.60
Test date	22 January 2019	Water level at start (mbgl)	0.50
Operator	Edward Hughes-Phillips 27-Feb-19	Depth to base of trial pit (mbgl)	1.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	1.50

[illegible]

Results		Comments
Vp 75-25 (m3)	0.72	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	4.44	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ

Location	TP220	Test number	1
Site	Sefton Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.00
Job number	305035	Width of trial pit (m)	8.00
Test date	22 January 2019	Water level at start (mbgl)	0.13
Operator	Edward Hughes-Phillips 27-Feb-19	Depth to base of trial pit (mbgl)	0.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	0.50

[illegible]


Results		Comments
Vp 75-25 (m3)	2.96	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	19.70	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ



DRAFT

[illegible]

Trial Pit Soakaway Test Results



Results


Vp 75-25 (m3)	0.27
ap 50 (m2)	2.28
tp 75-25 (s)	-
Infiltration Rate (m/s)	-

Comments

1. Trial pit dry prior to soakaway test.


RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre,
Premier Way, Romsey, SO51 9AQ

Location	TP222	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	1.85
Job number	305035	Width of trial pit (m)	0.60
Test date	23 January 2019	Water level at start (mbgl)	0.20
Operator	Edward Hughes-Phillips 27-Feb-19	Depth to base of trial pit (mbgl)	0.90
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	0.90

[illegible]

Results		Comments
Vp 75-25 (m3)	0.39	1. Groundwater at 0.90 m prior to soakaway test.
ap 50 (m2)	2.83	
tp 75-25 (s)	-	
Infiltration Rate (m/s)	-	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ

Location	TP223	Test number	1
Site	Sefter Road, Bognor Regis, PO21 3EE	Length of trial pit (m)	2.10
Job number	305035	Width of trial pit (m)	0.60
Test date	23 January 2019	Water level at start (mbgl)	0.08
Operator	Edward Hughes-Phillips [REDACTED] 27-Feb-19	Depth to base of trial pit (mbgl)	0.50
Checked by	Kirsten Fairall 27-Feb-19	Depth of pit at end of test (mbgl)	0.50

[illegible]

Results		Comments
Vp 75-25 (m3)	0.26	1. Trial pit dry prior to soakaway test.
ap 50 (m2)	2.39	
tp 75-25 (s)	15500	
Infiltration Rate (m/s)	7.13E-06	
		RSK Environment Ltd, Unit 26 Basepoint Abbey Enterprise Centre, Premier Wav. Romsey. SO51 9AQ

